NS/INC21004253/Qtc ASS, REC. BY: Sun Pin Yr Regn: 10/10/2017 SHB 853A Veh No: Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover / Estimated Cost: Truck / Trailer or OD / TP / WS / TP RES / OD RES / EVA / INV / MV 795 loyota Prius Make: To Inspect Vehicle No: Insured / Std / NI / NA at Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Reading Eng/No: Insured: JTD1CB3 F4903572576 C/No: Policy No. Gen. Cond: Good Fair / Poor / Burnt Claims No. MT/1129808-001 Steering: [norder / Jammed / Leaked / Burnt or Excess: Sum Insured: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: Nil /S/Rim / STD A/Rim or Make of Veh: 195/65 R16 Tyre Size: 195/65 R16 (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / N/S OIS Remark: The veh had commenced its repair at the time of inspection. TOYO / YOKO or Rear Front Bal. or Market Value: R/Bal. Consistent?: Yes or No R/Bal. mm / IDAC Accident Rport: L/Bal. L/Bal. Consistent?: Yes or No mm GIA / PR Seen: D.O.I. 25/03/2021 D.O.A. 23/07/2021 Res.: Yes or No Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages (Frt)/ Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date / Time Action / Instruction Finalize amount \$3,100. Repair day 3 days. (L/S, before gst. (Red: 8169.28;72%) 11269.28 Days Of Repair: 3 Date/Time, File Pass to? : Preli. Report Resurvey No. of Trip: Survey Fee: : Final Report Transportation: Date/Time, File Return to? Add Fee: S + RS.\_\_SI : Site Insp (\$ Interview (\$ Photos Tech. Invs (\$ Others Reper Format : Weellend (\$ 11.81:17 3100 TOTAL