

Surveyor TGM

REF:

CS/ICS21004256/Bqf3

shian chan

ASSIGNMENT

From:

Date: 5/4/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL8 7175 B

at Workshop m/s Deam Autopro

of 160 Sin Ming Dr #01-14

Insured:

Policy No. MPC21A00018600

Claims No. DMPC21001124


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 59000/2

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SL8 7175 B

Yr Regn: 20/7/2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato K3

C.C. 1591

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 116785

T/Radio: Insured / Std / NI / NA

Eng/No: 64F6G1H634431

C/No: KNAFJ411MH5717988

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65/15

R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 30/3/2021

D.O.I. 5/4/2021

Survey held at Deam Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Range 6,000/2 - 7,000/2

20/4/21 @ 1.25pm Mr Lim finalised with John Ko US \$5550, 8 days. (Red \$13667.45, 71%)
Recommended LOR is L/S \$5,550/2 TGM 6/4/2021

MV 59,000/2 20/04/2021 - COR removed. Repair cost too high
PV 35,870/2
NV 23,130/2
TGM 5/4/2021

Date/Time, File Pass to?

☐ : Preli. Report

1) 20/4/2021

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

S + RS, SI

Photos

Others

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

5550)