

(08/11/13) wef

ASS. REG. BY: Paul

REF:

CS/u0121004257/Riv3

S
073F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFQ110Eat Workshop m/s. WEARNESof 249, ALEXANDRA RDInsured: UO1


Policy No. _____

Claims No. M12D15322104Sum Insured: _____ Excess: 750

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 156k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFQ110E Yr Regn: 2018 / D6LType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLVO XC60 TS momentum c.c 1969Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 24735 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: L4VU210ACKB284658Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/60R18R: 1 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/03/21 D.O.I. 08/04/21Survey held at WEARNESDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Int-97K

24/5/21 Final fig \$9680.62 confirmed by email (Red 5597.78,36%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 24/5/21-Typist

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: OD

Lump Sum / I.B.I. (\$ 9680.62)

SERVICE ESTIMATE

99157 - C00001 SL: SERVICE SALES - PC

Mr Gan Lian Aun Arthur
52 Sunset View

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 01/04/2021

WIP No. . : 18195

Veh.In/Out:

*Tel.No. . : Mobile: 96191212

Reg.No. . : SFQ110E

Reg.date . : 21/12/2018

Mileage . : 0

Chassis No: LYVUZ10ACKB284658

Singapore 597209

Closed by . . . : Michelle Ong Siew Be

Svc Consultant :

Remarks . . . : Mr Gan Lian Aun Arth

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802 TO REPLACE LHF DOOR, DOOR
MOULDING, DOOR HANDLE,
'B' PILLAR, ROCKER PANEL, ETC.

0 3400.00 0 3,400.00 S 2550

800 TO PUTTY AND SPRAY PAINT ON
LHF DOOR, DOOR MOULDING,
DOOR HANDLE, 'B' PILLAR, ROCKER
PANEL, ETC.

0 3750.00 0 3,750.00 S 2250

802 TO TRANSFER DOOR PARTS

0 250.00 0 250.00 S

280 TO CHECK WIRING INCLUDE

0 588.00 0 588.00 S

RESETTING OF ALL ELECTRICAL
MODULES

DOOR PANEL FRT LH XC 4/

1.0 EA 2695.90 2,695.90 S

XC60 18- DOOR PROTEC de-

1.0 EA 331.00 331.00 S

DOOR HANDLE BRACKET ?

1.0 EA 152.30 152.30 S

DOOR HANDLE OUTER LH su-

1.0 EA 388.40 388.40 S

ROCKER STRIP SEAL LH ?

1.0 EA 256.00 256.00 S

XC60 18- SEAL STRIP ?

1.0 EA 128.10 128.10 S

SERVICE ESTIMATE

99157 - C00001 SL: SERVICE SALES - PC
 Mr Gan Lian Aun Arthur
 52 Sunset View

Singapore 597209

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Gan Lian Aun Arth

GST Reg.No:M28920628X
 0 Page 2
 Inv.No. . : B&P
 Inv.date. : 01/04/2021
 WIP No. . : 18195
 Veh.In/Out:
 *Tel.No. . : Mobile: 96191212
 Reg.No. . : SFQ110E
 Reg.date. : 21/12/2018
 Mileage . : 0
 Chassis No: LYVUZ10ACKB284658

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	XC60 18- GUIDE MOULD ?	1.0 EA	256.00			256.00	S
	V032205553/XC60 18- X	1.0 EA	114.80			114.80	S
	BOTTOM RAIL ?	1.0 EA	1441.50			1,441.50	S
	SOUND DEADENING PAD ?	1.0 EA	578.00			578.00	S
	RUST INHIBITING FLUI <i>rec</i>	4.0 EA	37.70			150.80	S
	ADHESIVE TUBE CHEMIC <i>rec</i>	1.0 EA	797.60			797.60	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Labour Total 7,988.00
Parts Total 7,290.40
Package Total 0.00

Gross Total. 15,278.40
 Net..... 15,278.40
 GST @ 7.0% 1,069.49
 Total..... 16,347.90
 Paid..... 0.00
 Please Pay.. 16,347.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Rasul
Hp 90010068
6 days
08/04/21 @ 1400
Resury before paint

Revert 750
excess: 750

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/03/2021 16:01 (SGT)
Date of Accident	30/03/2021 16:35 (SGT)
Exact Location of Accident	106 Clementi Street 12, Block 106, Singapore
Additional Location Information	OPEN MSCP
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFQ110E
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	GAN LIAN AUN AUTHUR
NRIC No	SXXXX073F
Email Address	ganarthur@mac.com
Mobile Phone No	(Phone) +65-96191212
Alternative Phone No	+65-96191212

VEHICLE PARTICULARS

Manufacturer	Volvo
Model	Xc60
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1969

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DHOM120055732000
Cover Note Number	-

DRIVER

Name of Driver	GAN LIAN AUN AUTHUR
NRIC No	SXXXX073F

Date Of Birth	14/06/1963
Occupation	Indoor
Date Of Driving Pass	01/04/1981
Driving experience	39 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96191212
Alt. Phone Number	+65-96191212
Email Address	ganarthur@mac.com
Address	52 SUNSET VIEW
Address complement	-
Postcode	597209
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

HIT METAL DIVIDER AS I WAS LEAVING THE CARPARK LOT. NO VEHICLES IN THE PARKING LOT AT THAT TIME. DID NOT SEE THE DIVIDER.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


31/3/21 15:15
Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

31/03/2021
Witnessed by Reporting Centre Personnel

BK 106 CUMMINS S7 12 DPMI MSCP



A) SEQ 110E

Describe Circumstances of the Accident

Hit metal divider as I was leaving the car park lot. No vehicles in the parking lot at that time. Did not see the divider.

Declaration

I/We declare the foregoing particulars are true in every respect.

18/03/21 15:15
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

81/03/2021
Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	073F
Vehicle No.:	SFQ110E
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2021
Vehicle Make:	VOLVO
Vehicle Model:	XC60 T5 MOMENTUM
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	B4204T237312162
Chassis No.:	LYVUZ10ACKB284658
Maximum Power Output:	187.0 kW (250 bhp)
Open Market Value:	\$38,330.00
Original Registration Date:	21 Dec 2018
First Registration Date:	21 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$45,662.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2028
PARF Rebate Amount:	\$34,246.00
COE Expiry Date:	20 Dec 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,900.00
COE Rebate Amount:	\$24,090.00
Total Rebate Amount:	\$58,336.00

The information contained herein is correct as at 09 Apr 2021

OK



freedom M to go with

SEARCH

Volvo XC60

Price Range

Depreciation

2018

Vehicle Type



Search

View All

Advanced Search

Home » Used Cars » 1axis » Volvo XC60 T5 Momentum

Volvo XC60 T5 Momentum

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Price \$151,800

Depreciation ?

\$17,280 /yr

View models with similar depre

Reg Date

28-Sep-2018

(7yrs 5mths 18days COE left)

Mileage

34,800 km (13.7k /yr)

Manufactured ?

2018

Road Tax ?

\$1,176 /yr

Transmission

Auto

Dereg Value ?

\$58,116 as of today (change)

OMV ?

\$38,070

COE ?

\$32,311

ARF ?

\$45,298

Engine Cap

1,969 cc

Power

187.0 kW (250 bhp)

Curb Weight ?

1,841 kg

No. of Owners ?

1

Type of Vehicle

SUV

Features

4 Cylinder In Line Turbocharged, 8 Speed Auto Transmission, 250Bhp, Max Torque 350Nm, 0-100Km/H In 6.9s, Keyless, Cruise Control, IntelliSafe Assist. View specs of the Volvo XC60 (2017)

Accessories

12.3" Adaptive Digital Display, SmartPhone Integration, Electric Memory Seats, Sensus Navigation, Hands-Free Power Tailgate, LED Lights, Reverse Cam.

Description

1 Owner! Low Mileage! Condition Like New! Come And View Now Safety And Easy To Drive Car! 100% Loan Available Bank Loan Too! Come And View Now Via Appointment Only! Trade-In Welcome~!

Category

PARF Car, Premium Ad Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources




sgCarMart Used Car Warranty

Get \$0 future car repair bill. Ask your dealer for a warranty on this car. Learn more

Compare



Free



Location Map



Shortlist



Compare



Report Error



More

Seller Information

1axis

87 vehicles for sale. 108 sold in past 3 mths

5 Yishun Industrial Street 1 #01-18

North Spring Bizhub

Search cars nearby



Malcom Chia

96876257

Jack

84306433

Catherine Lee

90019707

Kervin Chia

88113768