(68/11/13) wef REF: CS3/ALG 210	004289/Ritf3 423d
ASS. REC. BI: PONCE	IGNMENT COSTPIRY: 2023/MAY
Date:	Veh No: XD 70 43 A Yr Regn: 2013 / May
From:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost: OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: XD 7043A	Make: UD TRUCKS GK BSE LOHNTC.C [08 37
at Workshop m/s LEE HENG	Colour Mult A/C: Insured / Std / NI / NA
of 7, Svon Lee ST of U1-39	Sp.Reading 506127 T/Radio: Insured / Std / NI / NA
	Eng/No:
Insured: AIG	C/No: GKBSE OUIIS
Policy No. 1700027433 Claims No. 1468293539SG	Gen. Cond: Good / Fair/ Poor / Burnt
	Steering: Iporder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	
(Client's Record)	
Make of Veh:	Modi: (I) / S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF KPATOS
Bal. or Market Value: 33 k	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. 8/2 mm
D/IO/IOIOINI/ IPS	L/Bal. 8 mm L/Bal. 8/8 mm
	1/1/2
Est. Repairs: days Res.: Yes or No	- <u>L/ 03 - (</u>
Lum Sum: % 3 Val.: Yes or No	Survey held at LEE HEVA
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	FRT N/S
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Repair Int-20K	
	· · · · · · · · · · · · · · · · · · ·
submit dar report	
	· · · · · · · · · · · · · · · · · · ·
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3
1) : Final Report	Resurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to?	
	Transportation:
2) Add Fe	
	: Interview (\$) Photos
Report Format: DAR	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$
,	
	TOTAL

XD7043A.pdf

PORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver

 3. Information provided must be as truthful and accurate as possible. Any witful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- policy liability.

 4. The result and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any fairse reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

27/03/2021 14:26 (SGT) 23/03/2021 08:50 (SGT) PIE, Singapore PIE TOWARDS TUAS Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

XD7043A

INSURED/POLICYHOLDER

is company?

Name Of Registered Owner

Company Reg No **Email Address**

Mobile Phone No

Alternative Phone No.

Yes

SG SAGAWA AMEROID PTE LTD

1XXXXXX423d

ziv.ong@sgh-global.com

(Phone) +65-66029932

(Office) +65-66029933

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

UDTrucks undefined

Employment

No - Claiming third party

Commercial vehicle

Manual

10837

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

MSIG Insurance (Singapore) Pte. Ltd.

Comprehensive

Yes

400000359MKR

DRIVER

Name of Driver NRIC No

MUHAMMAD SHAHRIL BIN SAMSUDIN SXXXX709A

or Birth	17/06/1990
upation Page	Outdoor
te Of Driving Pass	27/09/2011
riving experience	9 YEARS AND 6 MONTHS
condet	Male
Mobile Number	(Phone) +65-66029933
Alt. Phone Number	•
Email Address	ziv.ong@sgh-global.com
Address	BLK 217B SUMANG WALK #07-238
Address complement	•
Postcode	822217
is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	•
Insurance company of other vertice owned by onter	•
GENERAL INFORMATION OF THE ACCIDENT	Park Care Care Care Care Care Care Care Care
。 《《《《《《《》》 《《《《《《《》 》 《《《《》 》 》 《《《《》 》 《《《》 》 《《》 》 《《》 》 《《》 》 《《》 》 《《》 》 《《》 《《《》 》 《《》 《《》 《《》 《《》 《》	
Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry
	,
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	• ·
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	
7,00, 28,000	
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH	
11 3	
ATTACHMENT(S)	Carlotte Maria Commence
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No
and the same of th	
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number	SLQ9203R
Vehicle Manufacturer	•
Vehicle Model	•

Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver NRIC No Contact Number

Address

SXXXX802Z

SKETCH PLAN (A)XD 7043A DESCRIBE CIRCUMSTANCES OF THE ACCIDENT was travellis MU 70431 time Stonight of had lang (n/ vehicle XD 7043A Chim can policy Colm third garty Colm OD (TP drather works) C For record parpare DECLARATION J400000356 MFF foregoing particulars are true in every respect. 12.00 Policyholder's Signeture Driver's Agnature Reporting Contre Passonnel's Signature Usia & Three lif driver's not the policyholderi hitsima-

Back to One Motoring

quire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	423D
/ehicle Details	
rehicle No.:	XD7043A
ehicle to be Exported:	No
ntended Deregistration Date:	21 Apr 2021
ehicle Make:	UD TRUCKS
ehicle Model:	GKB5ELDHNT
rimary Colour:	White
Nanufacturing Year:	2013
ngine No.:	GH11711620
Chassis No.:	GKB5E00115
Maximum Power Output:	-
Dpen Market Value:	\$83,683.00
Original Registration Date:	13 May 2013
First Registration Date:	13 May 2013
Fransfer Count:	0
Actual ARF Paid:	\$4,185.00
mentere partere esta esta esta esta esta esta esta est	
PARF Eligibility:	No .
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended (OE Rebate Details	12 May 2023
COE Expiry Date: COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$58,502.00
COE Rebate Amount:	\$12,035.00
Total Rebate Amount:	\$12,035.00

The information contained herein is correct as at 21 Apr 2021

UD Trucks GKB5E

Overview **Financial** Accessories Similar Research **Photos** Map

Price \$48,800 **Fuel Type** Diesel **Depreciation** ② \$16,540 /yr Reg Date 03-Apr-2014 View models with similar depre (2yrs 11mths 12days COE left) Mileage N.A. Manufactured (?) 2014 Road Tax N.A. **Transmission** Manual Dereg Value (?) \$16,613 as of today (change) OMV (?) \$77,202 COE (?) \$56,302 ARF (7) \$3,861 **Engine Cap** 10,837 cc No. of Owners (?) Curb Weight (7) 6,800 kg



Type of Vehicle

1 Owner Only. 55 Ton Prime Mover. Manual Transmission. Clutch Just Replaced. Good Condition. New Paintwork Done. Bank/ In-house Loan Available.

Category

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



Car Valuation - Free

Truck


Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 19-Apr-2021 | Last Updated on: 20-Apr-2021



















Shortlist

(+) Compare

(!) Report Error

· More

Seller Information

Chuan Choon Motor Trading Co.

20 vehicles for sale, 20 sold in past 3 mths

♀ 5 Pioneer Road North #01-32 Tel: 62683105 Search cars nearby

Wee Meng

96619134 👁

Mr Ong

97328678 👁

VAN/LORRY (Frt) XD 7043A

(1)Replace (//) (2)Repairly (3)Check (1)Not Consistent (9C)

-	7410 (227)	3	
7	'ehic	le I	Vo:

(15)Not Working			10
at Portion	Con		<u> </u>
NC Item 991886 Frt Number Plate 991887 991	CON	AC	Qty
991887 Frt Number Plate Base	_		
991887 Fit Number I late Base 991300 Frt Bumper Lth 001477 Frt Bumper Upper	3+		
991477 Frt Bumper Upper 2001 - 991477 Frt Bumper Upper	- 37		
2001 991477 Frt Bumper Lower			
2002	-	-	\neg
2003 991449 Frt Bumper Side Cover 2004 991443 Frt Bumper Side	William St.		-
1006 991325 Frt Bumper Bracket			_
1008 991433 Frt Bumper Reinforcement		70mm	-
2005 991466 Frt Bumper Signal Lamp			
995100 Frt LH Bumper Fog Lamp Cover			-
993100 Frt E11 Bumper Fog Lamp Cover			
1012 995079 Frt LH Bumper Fog Lamp	-		
1020 995080 Fit RH Bumper Fog Lamp			
991793 Frt Grille		-	
991328 Frt Grille Emblem	_		
2006 990247 Frt Grille Sticker		-	30
991799 Frt Grille Chrome Moulding	_	-	
2007 991891 Frt Panel		-	
2008 991874 Frt Lower Panel		-	77 10000
2009 991328 Frt Panel Emblem		-	
2010 990247 Frt Panel Sticker	•	-	
2011 991893 Frt Panel Garnish			
1024 991222 Frt Apron Panel		300	
2012 991527 Frt Corner Panel	1.0	-	
2013 991532 Frt Corner Panel Signal Lamp	4	1	
2014 995245 Frt Signal Lamp LH	CA	/	
2015 995246 Frt Signal Lamp RH	100	18	
995153 Frt LH Headlamp Assy	CA	1	
991821 Frt RH Headlamp Assy		-	
995088 Frt LH Side Lamp	CA	- /	-
1032 995089 Frt RH Side Lamp			
2016 992149 Frt Wiper Panel		_	+
2017 995043 Frt Wiper Nozzle		-	-
992140 Frt Wiper Arm		_	-
992142 Frt Wiper Blade	-	-	+
2018 992145 Frt Wiper Link		1000	
2019 992148 Frt Wiper Motor		+	+
995045 Wiper Panel Garnish 992093 Frt Windscreen			-
		+	
992097 Frt Windscreen Rubber	-	-	
992098 Frt Windscreen Sealant 2020 992114 Frt Windscreen Outer Pillar		\neg	
2021 992113 Frt Windscreen Inner Pillar	-	365	_
2021 992115 Fit windscreen miles I man		7	-
1339 991020 ERP Unit			
2022 991958 Frt Side Mirror (Big)			
2022 991959 Frt Side Mirror (Small)			
2024 991962 Frt Side Mirror (Round)			9.8
2024 991902 Fit Side Willion (Rodald) 2025 995015 Frt Wing Mirror Stay		+	
992013 Frt Support Panel			
1033 990248 Bonnet			
990287 Bonnet Lock		+	
990273 Bonnet Hinge		\top	
990305 Bonnet Rubber		\top	1
990119 Air Con Condenser		\dashv	
1023 990122 Air Con Fan Assy		+	
990122 Ali Coli Fali Assy 990149 Air Con Liquid Pipe		\dashv	
990149 An Con Edula Fipe		+	+
995006 Air Coll Receiver Differ		+	
	1	+	-
1053 992738 Radiator Cowling		-	-
992742 Radiator Fan Assy		\dashv	_
1056 992758 Radiator Hose Top			
1038 992741 Radiator Expansion Tank			
2026 992596 Oil Cooler			
1079 994431 Power Steering Cooler Pipe			
1059 990151 Air Duct		\dashv	
1060 990070 Air Cleaner Assy	-	+	-
990219 Battery		+	-
LODA MARIE J J J V L I J I D d LLC I V			
1069 990223 Battery Bracket			

		l'ehicle No:					
VAC	INC	Item	CO	NA	C	Otv	1
1002	991011	Engine Under Cover				201	1
2027	990940	Engine Mounting Frt Cabin Assy]
2028	991501	Frt Cabin Mounting			1		1
2029	991502	Frt Cabin Rear Panel		+	-		4
1092	991520	Frt LH Chassis Member		+	- 2		4
1093	991520	Frt RH Chassis Member	+	+		_	4
1094	990728	Frt Vertical Cross Member	-	+			4
		Frt Lower Cross-Member		\dashv	-	-	\dashv
2030	990143	Air Con Evaporator Assy	+	-			\dashv
2031	990106	Air Con Blower		_		<u> </u>	\dashv
		Brake Master Pump Assy	+		_		\dashv
		Brake Booster Pump Assy	+			1	
2032	990431	Brake Pedal	\top		_	T	
		Accelerator Pedal	\top				
		Clutch Pedal					
		Steering Wheel Airbag		•			
1128	994485	Steering Wheel Airbag Sensor					
1131	990029	Airbag Control Unit					
		Frt RH Seat Belt Assy					
		Frt LH Seat Belt Assy					
1124	990753	Dashboard Assy					
1125	992282	Glove Box Cover					
1126	992281	Glove Box Compartment					
1096	995070	Frt LH Fender					
1097	995072	Frt LH Fender Inner Panel			1		
1100	991740	Frt LH Fender Inner Shield					
1/1/0/1	995179	Frt LH Mudflap		•			
2035	994966	Frt LH Wheel Guard					
1102	995170	Frt LH Wheel Rim			L		
1104	995065	Frt LH Tyre					
11105	995071	Frt RH Fender					
10(06	991739	Frt RH Fender Inner Panel					
151(0.9)	991740	Frt RH Fender Inner Shield			L	_	
11110	991884	Frt RH Mudflap	_		\perp	+	
2036	994966	Frt RH Wheel Guard	_		_	_	
		Frt RH Wheel Rim			\vdash	+-	
10113	995065	Frt RH Tyre	_		\vdash	+	
1255	995326	Frt LH Door	+		-	+	_
		Frt LH Door Protector	+	_	┝	+	
		Frt LH Door Hinge	+	-	┝	+	_
1200	99314	Frt LH Door Wing Mirror Frt LH Door Glass	+		H	+	
1202	99310	Frt LH Door Glass Regulator	+		+	+	
1205	00150	6 Frt LH Door Glass Regulator Moto	r		-		_
1205	99156	2 Frt LH Door Rubber	+		\vdash	+	_
1066	99163	6 Frt LH Door Outer Handle	\neg	•		+	_
		7 Frt LH Door Inner Trim Board	\top		1		
15 2 T	99532	7 Frt RH Door			1		
	99165	4 Frt RH Door Protector	\top		T		-
1318	99160	1 Frt RH Door Hinge			1		
1910	99168	5 Frt RH Door Wing Mirror					
130	99158	4 Frt RH Door Glass			T		
120	99150	5 Frt RH Door Glass Regulator			T	1	
100	99150	6 Frt RH Door Glass Regulator Mot	or		1		-
		52 Frt RH Door Rubber			1		
		66 Frt RH Door Outer Handle			20		
		7 Frt RH Door Inner Trim Board	1		+		_
203	7 0016	14 Frt Door Frt Pillar	Ball	A Fis		1	-
			1361	11 11	-	1	_
		57 Frt Door Rear Pillar			+	-	
		72 Frt Wheel Arch Panel	100	F-6 . BC	+	-	_
		59 Frt Wheel Arch Panel Garnish		_	-	-	_
204	1 9919	96 Frt Step Panel					_
204	2 9944	98 Frt Step Panel Top Garnish					
		95 Frt Step Panel Inner Garnish	25		123	See and	
		53 Wiper Washer Tank			- 0	2	
		47 Sticker			79		
開発を	が近 フラロン	FRONT bury'th cover	7	CI	2	/	1
		1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			-	-	
	0.000 1.1404	agen 13 H	1	0			T

No of Items:

Type: M.Call M.Cycle / Bus / Van / Lorry / Tavi In-

Assessor:

3 days