



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004271/Kvf3n2	
			Date: 14/06/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLG 4158Z	Veh. Inspected	GBD 2630Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101025/MYE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	05/04/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VSKYBAM20Z0087854	Colour	METALLIC GREY	
Odometer	137994 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R14	YOKOHAMA	9 mm	
L/H Front Tyre	185/65 R14	YOKOHAMA	9 mm	
R/H Rear Tyre	185/65 R14	YOKOHAMA	9 mm	
L/H Rear Tyre	185/65 R14	YOKOHAMA	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/04/2021	Inspection Date	05/04/2021	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	