

ASS. REC. BY:

Steve

REF:


CS/AIG 21004277/ETF3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 1900103121
 Claims No. 1302300409SG
 Sum Insured: _____ Excess: 300
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SML 8504T Yr Regn: 7/6/19
 Type (M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: KIA Cerato c.c. 1597
 Colour: Blue A/C: Insured / Std / NI / N
 Sp. Reading: 25125 T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: KNAF 3416 MK 5944995
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45 R17
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or B Kumho

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 2/4/21 D.O.I. 5/4/21
 Survey held at Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt LH R: Frt RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-74K

Finalise at \$11,099.20 before GST and excess

RED: 6910;38%

Date/Time, File, Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: 11

Resurvey No. of Trip: _____

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Inve

(\$



: Weekend

(\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Special Form 1:

Form 2: Form 3: Form 4:



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10071/MR Lee Si Yang, Samuel Reg No/Reg Date SML8504T*KC17/ 07/06/201 Date In/Mileage 03/04/2021/ 0 Chassis No KNAF3416MK5044995 Engine No G4FGKH737946 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	05/04/2021/ 14:21	QUK	282 / Kevin Leong	31467		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, BOTH FRT FENDER, SUPPORT & AFFECTED AREA REPAIR ON FRT RH DOOR				2 1/2	X 400		1000 3600.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER & FRT RH DOOR				5	X 350		1750.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR							120.00
M SUNDRY TO TOP UP AIRCON GAS							80.00
M SUNDRY PERFORM RUST PREVENTION							120.00
A 33900099 REPLACE FRT UNDERCARRIAGE							400.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY TO TRANSFER FRT RH RIM INCLUDING BALANCING							30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY TO APPLY ZERTONA COATING (provide Sales Agreed)							400.00
M SUNDRY SUNDRIES							99 50.00
M LAMP ASSY-HEAD, LH				1.00	2210.00	20.00	1768.00
M HORN ASSY-LOW PITCH				1.00	74.00	20.00	59.20
M PANEL ASSY-HOOD				1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, RH				1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, LH				1.00	43.00	20.00	34.40
M PANEL-FENDER, LH				1.00	430.00	20.00	344.00
M INSULATOR-FENDER LH				1.00	27.00	20.00	21.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
ATG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10071/MR Lee Si Yang, Samuel Reg No/Reg Date SML8504T*KC17/ 07/06/201 Date In/Mileage 03/04/2021/ 0 Chassis No KNAF3416MK5044995 Engine No G4FGKH737946 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/04/2021/ 14:21	QUK	282 / Kevin Leong	31467

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M CARRIER ASSY-FRONT END MODULE ?	1.00	675.00	20.00	540.00
M ARM COMPLETE-FR LWR,LH ?	1.00	286.00	20.00	228.80
M KNUCKLE-FRONT AXLE,LH ?	1.00	350.00	20.00	280.00
M HUB ASSY-FR WHEEL ?	1.00	436.00	20.00	348.80
M GEAR ASSY-STEERING ?	1.00	770.00	20.00	616.00
M STRUT ASSY-FR,LH ?	1.00	280.00	20.00	224.00
M PAD-FRONT SPRING,UPR ?	1.00	11.00	20.00	8.80
M PAD-FRONT SPRING,LWR ?	1.00	23.00	20.00	18.40
M INSULATOR ASSY-STRUT ?	1.00	85.00	20.00	68.00
M BRACKET-FR BUMPER UPR SIDE MTG ?	1.00	22.00	20.00	17.60
M AIR DUCT-FR BUMPER,LH ?	1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY ?	1.00	84.00	20.00	67.20
M LAMP ASSY-SIDE REPEATER,LH ?	1.00	143.00	20.00	114.40
M COVER-FR BUMPER ?	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER ?	1.00	485.00	20.00	388.00
M MOULDING-FRONT BUMPER,LH ?	1.00	216.00	20.00	172.80
M GUARD ASSY-FRONT WHEEL,LH ?	1.00	95.00	20.00	76.00
M ORNAMENT-KIA NO.115 ?	1.00	32.00	20.00	25.60
M WHEEL ASSY-ALUMINIUM ?	1.00	926.00	20.00	740.80
M PANEL-FENDER,RH ?	1.00	430.00	20.00	344.00

Estimate

Steve CLKK) 00-ALM AL
5/4/21, 3.30pm EXPR - ?
P/P
My Bel Spy
8 dgs

LKK Auto Consultants hence notify

the presence of the following:

Confirm & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Nett 15,080.00
7% GST on 15080.00 1055.60
Total Payable 16,135.60

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information
Country/State of Loss

03/04/2021 10:13 (SGT)
02/04/2021 10:30 (SGT)
E Coast Rd, Singapore
EAST COAST CARPARK B3 - EAST COAST PARK SERVICE RD
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SML8504T

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
NRIC No
Email Address
Mobile Phone No
Alternative Phone No

No
LEE SI YANG, SAMUEL
SXXXX949B
SAMNONSENSELEE@GMAIL.COM
(Phone) +65-93804257
+65-93804257

VEHICLE PARTICULARS

Manufacturer
Model
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category
Transmission
CC

Kia
Cerato
-
-
Yes
Private car
Auto
1591

INSURANCE COMPANY

Name of Insurance Company
Type of Coverage
Fleet Policy
Policy Number
Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd.
Comprehensive
No
1900103121
-

DRIVER

Name of Driver
NRIC No

LEE SI YANG, SAMUEL
SXXXX949B

Date of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

20/11/1989
Outdoor
18/03/2009
12 YEARS AND 1 MONTH
Male
(Phone) +65-93804257
+65-93804257
SAMNONSENSELEE@GMAIL.COM
BLK 139 BEDOK NORTH AVE 3 #09-184

-
-
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
3
No
-
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT COLLISION-HEAD TO SIDE

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
Yes
No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address

SLG7577C
Suzuki
-
-
Brown
Private car
TAY SEOW HWEI
(Phone) +65-96832793
-

Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
FWD Singapore Pte. Ltd.
-
CAR A
-

DETAILS OF OTHER VEHICLE PROPERTY 2:

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SMY6572R
-
-
-
-
Private car
SEAH JENG TAH
(Phone) +65-96855139
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 02 Apr 2021, at around 1030H, I was driving SMV 85047 out from the East Coast Park (ECP) Road Safety Park carpark R3.

As I was exiting, LEXUS, SMV 6572R, driven by Mr Seah Jeng Teik, stopped for me. I proceeded to exit the car park as both directions were clear.


As I was entering the further lane with traffic moving from left to right, I was hit by Suzuki, SLG 75779, driven by Mr Tay Siew Hwee.


Because of the impact with the left front of the car, ~~it~~ I hit the front right my front right bumper hit the right bumper of SMV 6572R.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lee Si Yang, Samuel
Period of Insurance : 07 Jun 2019 To 06 Jun 2021
Engine No. : G4FGKH737946
Chassis No. : KNAF3416MK5044995

Vehicle No. : SML8504T
Policy No. : 1900103121
Endorsement No. : 000000000365826
Issued Date : 09 Nov 2020

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Mileage Condition : Unlimited Mileage

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lee Si Yang, Samuel - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

AIG Asia Pacific Insurance Pte. Ltd.
This computer generated document does not require a signature.

0504624050
FULCOKICP2 - CORPORATE

22 UBI ROAD 4 FULCO BUILDING
SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

SSPWTC