

ASS. REC. BY:

Steve

REF:


CS/AIG 21004277/ETF3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SML 8504T Yr Regn: 7/6/19  
 Type ☒ M.Ca / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /  
 Truck / Trailer or  
 Make: KIA Cerato c.c. 1597  
 Colour: Blue A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ N  
 Sp. Reading: 25125 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ N  
 Eng/No: \_\_\_\_\_  
 C/No: KNAF 3416 MK 5944995  
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt  
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
 Modl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or  
 Tyre Size: F: 225/45 R17  
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kumho

Front Rear  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 2/4/21 D.O.I. 5/4/21  
 Survey held at Cycle & Carriage

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop orFrt LH R. Frt RH

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-74K

Date/Time, File, Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Inve

(\$



: Weekend

(\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL


Special Form 1:

Form 2000 / 1.1.1.1



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10071/MR Lee Si Yang, Samuel Reg No/Reg Date SML8504T*KC17/ 07/06/201 Date In/Mileage 03/04/2021/ 0 Chassis No KNAF3416MK5044995 Engine No G4FGKH737946 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	05/04/2021/ 14:21	QUK	282 / Kevin Leong	31467		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, BOTH FRT FENDER, SUPPORT & AFFECTED AREA REPAIR ON FRT RH DOOR				2 1/2	X 400		1000 3600.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER & FRT RH DOOR				5	X 350		1750.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR							120.00
M SUNDRY TO TOP UP AIRCON GAS							80.00
M SUNDRY PERFORM RUST PREVENTION							120.00
A 33900099 REPLACE FRT UNDERCARRIAGE							400.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY TO TRANSFER FRT RH RIM INCLUDING BALANCING							30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY TO APPLY ZERTONA COATING (provide Sales Agreed)							400.00
M SUNDRY SUNDRIES							90 50.00
M LAMP ASSY-HEAD, LH				1.00	2210.00	20.00	1768.00
M HORN ASSY-LOW PITCH				1.00	74.00	20.00	59.20
M PANEL ASSY-HOOD				1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, RH				1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, LH				1.00	43.00	20.00	34.40
M PANEL-FENDER, LH				1.00	430.00	20.00	344.00
M INSULATOR-FENDER LH				1.00	27.00	20.00	21.60

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
ATG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10071/MR Lee Si Yang, Samuel Reg No/Reg Date SML8504T*KC17/ 07/06/201 Date In/Mileage 03/04/2021/ 0 Chassis No KNAF3416MK5044995 Engine No G4FGKH737946 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/04/2021/ 14:21	QUK	282 / Kevin Leong	31467

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00
M ARM COMPLETE-FR LWR,LH	1.00	286.00	20.00	228.80
M KNUCKLE-FRONT AXLE,LH	1.00	350.00	20.00	280.00
M HUB ASSY-FR WHEEL	1.00	436.00	20.00	348.80
M GEAR ASSY-STEERING	1.00	770.00	20.00	616.00
M STRUT ASSY-FR,LH	1.00	280.00	20.00	224.00
M PAD-FRONT SPRING,UPR	1.00	11.00	20.00	8.80
M PAD-FRONT SPRING,LWR	1.00	23.00	20.00	18.40
M INSULATOR ASSY-STRUT	1.00	85.00	20.00	68.00
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M AIR DUCT-FR BUMPER,LH	1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20
M LAMP ASSY-SIDE REPEATER,LH	1.00	143.00	20.00	114.40
M COVER-FR BUMPER	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER	1.00	485.00	20.00	388.00
M MOULDING-FRONT BUMPER,LH	1.00	216.00	20.00	172.80
M GUARD ASSY-FRONT WHEEL,LH	1.00	95.00	20.00	76.00
M ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60
M WHEEL ASSY-ALUMINIUM	1.00	926.00	20.00	740.80
M PANEL-FENDER,RH	1.00	430.00	20.00	344.00

Steve CLKK) 00-ALM AL  
5/4/21, 3.30pm EXPR - ?  
P/P  
My Bel Spy  
8 dgs

LKK Auto Consultants hence notify

the presence of the following:

Confirm &amp; accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Nett 15,080.00  
7% GST on 15080.00 1055.60  
Total Payable 16,135.60

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission .....  
Date of Accident .....  
Exact Location of Accident .....  
Additional Location Information .....  
Country/State of Loss .....

03/04/2021 10:13 (SGT)  
02/04/2021 10:30 (SGT)  
E Coast Rd, Singapore  
EAST COAST CARPARK B3 - EAST COAST PARK SERVICE RD  
Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number .....

SML8504T

### INSURED/POLICYHOLDER

Is company? .....  
Name Of Registered Owner .....  
NRIC No .....  
Email Address .....  
Mobile Phone No .....  
Alternative Phone No .....

No  
LEE SI YANG, SAMUEL  
SXXXX949B  
SAMNONSENSELEE@GMAIL.COM  
(Phone) +65-93804257  
+65-93804257

### VEHICLE PARTICULARS

Manufacturer .....  
Model .....  
Variant .....  
Exact purpose for which vehicle was being used at time of accident .....  
Are you claiming under your own insurance policy for repair to your vehicle? .....  
Vehicle Category .....  
Transmission .....  
CC .....

Kia  
Cerato  
-  
-  
Yes  
Private car  
Auto  
1591

### INSURANCE COMPANY

Name of Insurance Company .....  
Type of Coverage .....  
Fleet Policy .....  
Policy Number .....  
Cover Note Number .....

AIG Asia Pacific Insurance Pte. Ltd.  
Comprehensive  
No  
1900103121  
-

### DRIVER

Name of Driver .....  
NRIC No .....

LEE SI YANG, SAMUEL  
SXXXX949B

Date Of Birth .....  
 Occupation .....  
 Date Of Driving Pass .....  
 Driving experience .....  
 Gender .....  
 Mobile Number .....  
 Alt. Phone Number .....  
 Email Address .....  
 Address .....  
 Address complement .....  
 Postcode .....  
 Is the driver the policyholder? .....  
 If No, Relationship of the Driver with the Insured .....  
 Does Driver Own Other Vehicles? .....  
 Vehicle Registration Number of Other Vehicle Owned by Driver .....  
 Insurance Company of Other Vehicle Owned by Driver .....

20/11/1989  
 Outdoor  
 18/03/2009  
 12 YEARS AND 1 MONTH  
 Male  
 (Phone) +65-93804257  
 +65-93804257  
 SAMNONSENSELEE@GMAIL.COM  
 BLK 139 BEDOK NORTH AVE 3 #09-184

-  
 -  
 Yes  
 -  
 No  
 -  
 -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
 Weather Conditions .....  
 Road Surface .....

Collision - Head to Rear  
 Clear  
 Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....  
 Number of vehicles involved in the accident .....  
 Was anybody injured in the Accident? .....  
 Was any injured conveyed to hospital by ambulance? .....  
 Was any other material or property damaged? .....  
 Number of Passengers (Including Driver) .....  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....

No  
 3  
 No  
 -  
 Yes  
 1  
 No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....  
 Was notice of intended Prosecution given? .....  
 If yes, against whom? .....

No  
 No  
 -

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT  
 COLLISION-HEAD TO SIDE

#### ATTACHMENT(S)

Are accident photos available for attachment? .....  
 Was there any video captured by Car Camera? .....  
 Was there any audio recorded? .....

Yes  
 Yes  
 No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number .....  
 Vehicle Manufacturer .....  
 Vehicle Model .....  
 Vehicle Variant .....  
 Vehicle Colour .....  
 Vehicle Category .....  
 Name of Driver .....  
 Contact Number .....  
 Address .....

SLG7577C  
 Suzuki  
 -  
 -  
 Brown  
 Private car  
 TAY SEOW HWEE  
 (Phone) +65-96832793  
 -

Address complement  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 Details of property damaged in accident  
 No. Of Passenger (Including Driver)

-  
 -  
 FWD Singapore Pte. Ltd.  
 -  
 CAR A  
 -

**DETAILS OF OTHER VEHICLE PROPERTY 2:**

Vehicle Registration Number  
 Vehicle Manufacturer  
 Vehicle Model  
 Vehicle Variant  
 Vehicle Colour  
 Vehicle Category  
 Name of Driver  
 Contact Number  
 Address  
 Address complement  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 Details of property damaged in accident  
 No. Of Passenger (Including Driver)

SMY6572R  
 -  
 -  
 -  
 -  
 Private car  
 SEAH JENG TAH  
 (Phone) +65-96855139  
 -  
 -  
 -  
 -  
 -  
 -  
 -





## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



**Describe Circumstances of the Accident**

On 02 Apr 2021, at around 1030H, I was driving SMV 85047 out from the East Coast Park (ECP) Road Safety Park carpark B3.


As I was exiting, LEXUS, SMV 6572R, driven by Mr Seah Jeng Teoh, stopped for me. I proceeded to exit the car park as both directions were clear.


As I was entering the further lane with traffic moving from left to right, I was hit by Suzuki, SLG 75779, driven by Mr Tay Siew Hwee.


Because of the impact with the left front of the car, ~~it~~ I hit the front right my front right bumper hit the right bumper of SMV 6572R.

**Declaration**

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



# CERTIFICATE OF INSURANCE

## KIA AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : Lee Si Yang, Samuel  
**Period of Insurance** : 07 Jun 2019 To 06 Jun 2021  
**Engine No.** : G4FGKH737946  
**Chassis No.** : KNAF3416MK5044995

**Vehicle No.** : SML8504T  
**Policy No.** : 1900103121  
**Endorsement No.** : 000000000365826  
**Issued Date** : 09 Nov 2020

### ABOUT THE COVER

**Make/Model** : KIA Cerato  
**Engine Capacity/Tonnage** : 1,591.00 CC  
**Driver Restriction** : NA  
**Person or Classes of Persons Entitled to Drive\*** :

**Sum Insured** : Market Value  
**Off Peak Car** : No

**First Year of Registration** : 2019  
**Insuring with COE/PARF** : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Mileage Condition** : Unlimited Mileage

**Age Condition** : All Age Condition

**Limitation as to use\*** :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

**Loss of Use 1500cc - 1600cc**

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

**Section 1**  
**Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0**

**Section 2**  
**Property Damage - \$0**

**Windscreen : \$100**

**Named Driver and Excess (where applicable)**

Lee Si Yang, Samuel - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

**Hire Purchase Company/Employer's Loan: MayBank**

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

**AIG Asia Pacific Insurance Pte. Ltd.**  
This computer generated document does not require a signature.

0504624050  
FULCOKICP2 - CORPORATE

22 UBI ROAD 4 FULCO BUILDING  
SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

SSPWTG