



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Motorcycle (FBD802H)
Date of Loss	30 March 2021
Time of Loss	16:45
Loss Description	SHD6662J (INSD) HIT REAR OF FBD802H (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate
Amount

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work
completion *



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# FBD802H

Purchase Date

DD/MM/YYYY



Registration State

SINGAPORE

Registration Date *

17/10/2008



Mileage

Age of Vehicle

12

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2008

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

CHIN AH PENG

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD	<input type="text" value="HONDA"/>
Model	Motorcycle	<input type="text" value="ANF 125MSS A"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="NF125MM5000922"/>
Engine No		<input type="text" value="NF125MME5000922"/>
Engine Capacity		<input type="text" value="125"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text"/> ▼
Gender	Unknown	<input type="text"/> ▼
Marital status	Unknown	<input type="text"/> ▼
Identification #		<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

06/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

70/90-17

Front left side

THUNDER5mm

Front right side

Spare wheel

Rear Tyre Size

80/90-17

Rear left side

THUNDER5mm

Rear right side

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<input type="text" value="Yes"/>	<input checked="" type="text" value="No"/>	Part supplied by
Paint Material Ratio	<input type="text" value="80"/>				

A
X
A











Save





Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts														
Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PA
	0	2		FORK INNER TUBES	Serviceable	0	0	No	0	0	0	0	0	De
	0	2		FORK OUTER TUBES	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		FORK UNDER BRACKET	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		FRONT SPORT RIM	Repair	0	0	No	0	0	0	0	0	De
	0	1		FRONT RIM SHAFT	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		FRONT RIM BEARING	Serviceable	0	0	No	0	0	0	0	0	De

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PA
	0	1		SIDE MIRROR N/S	Damaged	0	65	No	0	10	0	0	58.5	Re
	0	1		HANDLE-BAR	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		HANDLE BAR ENDS	Cut	0	30	No	0	10	0	0	27	Re
	0	1		SET HAND GRIP	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		FRONT FOOTREST BRACKET	Bent	0	55	No	0	10	0	0	49.5	Re
	0	1		FRONT FOOTREST RUBBERS	Damaged	0	56	No	0	10	0	0	50.4	Re
	0	1		GEAR PEDAL	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		REAR FOOTREST N/S	Cut	0	38	No	0	10	0	0	34.2	Re
	0	1		REAR FOOTREST O/S	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		REAR FOOTREST BRACKET	Serviceable	0	0	No	0	0	0	0	0	De

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PA
	0	1		REAR TAILLAMP	Cracked	0	88	No	0	10	0	0	79.2	Re
	0	1		REAR FENDER	Damaged	0	68	No	0	10	0	0	61.2	Re
	0	1		REAR SPORT RIM	Repair	0	0	No	0	0	0	0	0	De
	0	1		REAR RIM SHAFT	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		REAR SWING ARM	Bent	0	350	No	0	10	0	0	315	Re
	0	1		REAR ABSORBER	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		MAIN STAND	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		SIDE STAND	Repair	0	0	No	0	0	0	0	0	De
	0	1		FAIRING ASSY	Repair	0	0	No	0	0	0	0	0	De

Labour









Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------	--------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO PROVIDE TOWING	0	30	0	0	Reviewing		
	0		TO CHECK WIRING AND RESET HEADLAMP FOCUSING	0	0	0	0	Deny		
	0		TO RESPRAY	0	250	0	0	Reviewing		
	0		TO PROVIDE LABOUR	0	280	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS OF
REPAIR : 4
DAYS

Reviewing

0

0



0

1 SET
NUMBER
PLATE

Reviewing

0

10

REAR BENT



0













FORK
OILS
(2PCS)

Deny

0

0

NOT
NECESSARY

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FORK OIL SEALS (2PCS)	Deny	0	0	NOT NECESSARY	
	0	1 SET STEERING CONE BEARING	Deny	0	0	NOT NECESSARY	
	0	REAR BOX	Reviewing	0	180	CUT	
	0	REAR BOX BRACKET	Deny	0	0	REPAIR	
	0	1 SET STICKER	Reviewing	0	90	NECESSARY	
	0	E.R.P IU	Reviewing	0	165	CUT	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$1,680.00

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

Labour

Spare Parts

Miscellaneous

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

1300



Home Service Requests Messages Claims

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$1,300.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
----------	----------	----------

Miscellaneous

Submit for Review