SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

05/04/2021 19:31 (SGT) 04/04/2021 11:45 (SGT)

Singapore

Slip Road of Ubi Ave 2 towards Paya Lebar Road

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBJ6296Y

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

MERIDIAN CURTAINS & FURNISHINGS

5XXXX467M

smartoneauto@gmail.com (Phone) +65-94518821 (Office) +65-67447656

VEHICLE PARTICULARS

Manufacturer Mcdel

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

Toyota Dyna

Employment

No - Claiming third party Commercial vehicle

Manual 2982

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number NTUC Income Insurance Co-operative Ltd

Comprehensive

No

5117962469

DRIVER

Name of Driver Passport No/FIN XIE QING GXXXX302X



Date Of Birth Occupation

Date Of Driving Pass

Driving experience

Gender

Mobile Number Alt. Phone Number

Email Address

Address complement

Postcode

Address

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Employee No

02/09/1980

19/10/2018

2 YEARS AND 6 MONTHS

smartoneauto@gmail.com 349 Changi Road

(Phone) +65-85230280

Outdoor

Male

419817

No

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

Collision - Head to Rear

Clear Dry

OTHER INFORMATION

Was any fcreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

Yes No

Yes 1

No

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

No

CIRCUMSTANCES OF ACCIDENT

Refer to Sketch Plan

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes No No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category

Name of Driver Contact Number

Address Address complement **SLK3651B**

Private car

Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

Yes

No

INJURED 1

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

isi

Name of injured person XIE QING Address Address Complement Post Code Approximate Age Years Old Injuries Sustained **BODY PAIN** Injured person in which vehicle? GBJ6296Y

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Inscrers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims
- (collectively the "Purposes") (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Parsonal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VICOM LTD)

23 KAKI BUKIT AVENUE 4S(415933)

Witnessed by Reporting Centre Personnel

Sketch Plan

A= 6BJ62967 B= SLK 3651B Slip Road of Ub. Ave 2 towards Paya Leber Road

scribe Circumstance	s of the Accident
	/
	/
h	
	/
	Refer to attached
	Refer to attached
f-	
	1
/	
/	
/	
6-/	

Declaration

IWe declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VICOM LTD)

23 KAKI BUKIT AVENUE 4S(415933)

Witnessed by Reporting Centre Personnel

On 04.04.21 at about 11:45 hours at slip road of Ubi Ave 2 towards Paya Lebar Road. While I was stopping at the above slip road waiting for oncoming traffic to clear, suddenly I heard a loud bang from behind. I alighted and realized it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my vehicle.

Vehicle (A): GBJ6296Y

Vehicle (B): SLK3651B



