

ASS. REC. BY:

REF:

AIG/210043001K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

SRG 8101D

Yr Regn:

01, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

c.c

1598

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

78760

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH 104354597

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order /

Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

NII / S/Rim / STD / R/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/4/21

D.O.I.

6/4/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - R.S. SI

Furnish

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Thirumaran S/O M Manickam
BLK 880 #07-265 Yishun Street 81
S760880

Not Worth
1-B.1, 6/1 Sep 8
Penny After Point
7 days

File No: SH/2021/028/04/001/TP
Date: 06-April-2021

Estimated cost of repair for vehicle no: SFQ8101D Toyota Corolla Altis
Accident involving vehicle no: SFQ8101D & SKR7929A on 03.04.2021

Description	Quantity	Cost Price
Bonnet <i>Bi ✓</i>	1	
Bonnet lock <i>Di ✓</i>	1	
RH Bonnet hinge <i>Bi ✓</i>	1	
LH Bonnet hinge <i>Di ✓</i>	1	
RH head lamp <i>mg ✓</i>	1	
LH head lamp <i>✓</i>	1	
Front grille <i>cm ✓</i>	1	
Front grille clips (1 set) <i>nc ✓</i>	1	
Front grille chrome moulding set <i>cm ✓</i>	1	
Front grille emblem <i>nc ✓</i>	1	
RH front fender <i>Bi ✓</i>	1	
RH front fender badge "Dual Vvti" <i>nc ✓</i>	1	
Front bumper <i>Bi ✓</i>	1	
Front bumper centre grille <i>cm ✓</i>	1	
Front bumper sponge <i>cm ✓</i>	1	
Front bumper reinforcement <i>Bi ✓</i>	1	
RH Front bumper retainer <i>Di ✓</i>	1	
LH Front bumper retainer <i>Di ✓</i>	1	
RH Front bumper bracket <i>?</i>	1	
LH Front bumper bracket <i>?</i>	1	
Front bumper lower dust cover <i>?</i>	1	
Front bumper lower dust cover clips (1 set) <i>?</i>	1	
Front support panel <i>Bi ✓</i>	1	
Front support panel top garnish <i>mg Di ✓</i>	1	
Front support panel top garnish clips (1 set) <i>nc ✓</i>	1	
Bonnet lock centre bracket <i>Bi ✓</i>	1	
RH head lamp inner panel <i>?</i>	1	
LH head lamp inner panel <i>?</i>	1	
Air con condensor <i>Bi ✓</i>	1	
RH Air con condensor air guide <i>?</i>	1	
LH Air con condensor air guide <i>?</i>	1	
Air con condensor pipe inlet <i>?</i>	1	
Air con condensor pipe outlet <i>?</i>	1	
Radiator <i>?</i>	1	
Radiator auto fan cowling <i>cm ✓</i>	1	
Radiator auto fan motor <i>?</i>	1	



Radiator auto fan blade	7	1
Air con condensor auto fan cowling	7	1
Air con condensor auto fan motor	7	1
Air con condensor auto fan blade	7	1

Less 20%

Front number plate	1	S. Nett	\$	mit 45.00 ✓
Engine coolant	1	S. Nett	\$	14 30.00 ✓
To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality			\$	100/ 120.00
To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment			\$	700/ 750.00
To spray paint affected front and inner damaged portion inclusive of preparatory works and material			\$	800/ 900.00
To apply anti-corrosion Tuff-Kote			\$	100.00 90/
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp			\$	20/ 25.00
To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes			\$	120.00 ?
Towing charges			\$	60.00 50/

T/Party: AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 of 2

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

514I

Vehicle Details

Vehicle No.:

SFQ8101D

Vehicle to be Exported:

Yes

Intended Deregistration Date:

05 Apr 2021

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA ALTIS 1.6 CVT

Primary Colour:

Grey

Manufacturing Year:

2016

Engine No.:

1ZRX585917

Chassis No.:

MR053REH104554597

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$19,990.00

Original Registration Date:

20 Jan 2017

First Registration Date:

20 Jan 2017

Transfer Count:

1

Actual ARF Paid:

\$19,990.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

19 Jan 2027

PARF Rebate Amount:

\$14,992.00

Intended COE Rebate Details

COE Expiry Date:

19 Jan 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,101.00

COE Rebate Amount:

\$28,996.00

Total Rebate Amount:

\$43,988.00

The information contained herein is correct as at 05 Apr 2021

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 514I

Vehicle Details

Vehicle No.: SFQ8101D
Vehicle to be Exported: Yes
Intended Deregistration Date: 05 Apr 2021
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 CVT
Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: 1ZRX585917
Chassis No.: MR053REH104554597
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,990.00
Original Registration Date: 20 Jan 2017
First Registration Date: 20 Jan 2017
Transfer Count: 1
Actual ARF Paid: \$19,990.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Jan 2027
PARF Rebate Amount: \$14,992.00

Intended COE Rebate Details

COE Expiry Date: 19 Jan 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,101.00
COE Rebate Amount: \$28,996.00
Total Rebate Amount: \$43,988.00

The information contained herein is correct as at 05 Apr 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/04/2021 09:51 (SGT)
Date of Accident	03/04/2021 10:44 (SGT)
Exact Location of Accident	Mandai Rd, Singapore
Additional Location Information	Mandai Road/Mandai Lake Road junction
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFQ8101D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Thirumaran S/O M Manickam
NRIC No	SXXXX514I
Email Address	1202mthira@gmail.com
Mobile Phone No	(Phone) +65-96381657
Alternative Phone No	(Home) +65-96381657

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla Altis 1.6 CVT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1599

INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MP316212
Cover Note Number	-

DRIVER

Name of Driver	Thirumaran S/O M Manickam
NRIC No	SXXXX514I

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

