A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113(change)

HP: 8386 8989

Co. Reg. No.: 53368526E

Date of Estimate: 05.04.2021 Vehicle No: CB8803B

Owner: Goh Transport Services Co Pte Ltd

Date of Accident: 29.03.2021
Make & Model: YUTONG ZK6107H

Chassis No : LZYTBTD6XE1024349

ESTIMATE FOR ACCIDENT VEHICLE NO PC3399A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<u>PARTS</u>

SUB TOTAL LESS 5 %

DISCOUNTED SUB TOTAL

\$0.00 \$0.00

S. NETT ITEM

1 1 Front auto side mirror with warmer L/H

/ CRy.

S/N \$1,860.00 1,660

\$1,860.00

\$300.00 250

\$300.00250

\$100.00 ?

\$100.0050

\$100.00 30

\$900.00

SUB TOTAL LESS 0 %

DISCOUNTED SUB TOTAL

\$1,860.00 \$0.00

LABOUR

- 1 Panel beating for replace and repair affected parts
- 2 Spray painting on affected area
- 3 Wiring charges & testing commissioning
- 4 Apply putty and anti-corrosion to affected parts
- 5 Transfer side mirror mechanism L/H

SUB TOTAL (LABOUR)

1,660 610 2,270

Repur day 2 days 1919 netone puin photo.

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

\$2,270 2days.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1