

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD	R	Ref:	CC4/ASM21004305/Ags3q2	
	8 SHENTON WAY AXA TOWERSING		С	Date:	20/09/2021	
	ATTN:CYNTHIA		C	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMR 3780M	Veh. Inspected		SLE 3414B	
	Policy No.	GA531118	Coverage (\$)		0.00	
	Claim No.	S1M03759	Excess (\$)		0.00	
	Assign From		Assign Date		05/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	RU11116901	Colour		WHITE	
	Odometer	417814 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	HABILEAD		6 mm	
	L/H Front Tyre	215/60 R16	HABILEAD		6 mm	
	R/H Rear Tyre	215/60 R16	HABILEAD		6 mm	
	L/H Rear Tyre	215/60 R16	HABILEAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/04/2021	Inspection Date		06/04/2021	
	Survey held at	MG SOLUTION PTE LTD				
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					