

(02/11/13)

Wef

ASS. REC. BY:

REF:

CS/CTI 21004307/RIV f3

B
044A

ASSIGNMENT

COG XPRY: 2022/JAN

From:

Date:

Estimated Cost:

Veh No:

SGQ 33504

Yr Regn: 2007/JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SGQ 33504

Make:

SUZUKI SWIFT SP 1.6M

c.c 1586

at Workshop m/s: RICO 60

Colour:

RED

A/C: Insured / Std / NI / NA

of 8, KKKI BUKIT ME 4 #02-24

Sp. Reading

273187

T/Radio: Insured / Std / NI / NA

Insured:

CTI SMW 3078X

Eng/No:

Policy No.

DMPCSN W00183672000

C/No:

ZC 318108618

Claims No.

SNM 21D 201608 / CO2 / TOHHS

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

6K

Tyre Size:

F:

215/45R16

R:

44

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HABILON

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

19/03/21

D.O.I.

06/04/21

Survey held at

RICO 60

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 1.5K

22/4/21 LS \$1500 confirmed by email (Ref 16, 501.38, 929)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

6

1)

☐

Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2) 23/4 - typist

Add Fee:

☐

Site Insp (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I: (\$ 1500/2)

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	044M
Vehicle Details	
Vehicle No.:	SGQ3350Y
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Mar 2021
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT SPORT 1.6 M
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	M16A1175619
Chassis No.:	ZC31S108618
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$17,394.00
Original Registration Date:	11 Jan 2007
First Registration Date:	11 Jan 2007
Transfer Count:	3
Actual ARF Paid:	\$11,739.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,323.00
COE Rebate Amount:	\$4,207.00
Total Rebate Amount:	\$4,207.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Mar 2021

OK



ENJOY FREE 2 MONTHS OF STANDARD VIP

[SEARCH](#)

[Advanced Search](#)

Home » Used Cars » Car Buddy Pte Ltd » Suzuki Swift Sport 1.6M (COE till 09/2022)

Suzuki Swift Sport 1.6M (COE till 09/2022)

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$11,888		
Depreciation ⓘ	\$8,310 /yr	Reg Date	12-Sep-2007 (1yr 5mths 4days COE left)
Mileage	N.A.	Manufactured ⓘ	2007
Road Tax ⓘ	\$1,030 /yr	Transmission	Manual
Dereg Value ⓘ	\$6,304 as of today (change)	OMV ⓘ	\$12,173
COE ⓘ	\$22,041	ARF ⓘ	\$13,391
Engine Cap	1,586 cc	Power	92.0 kW (123 bhp)
Curb Weight ⓘ	1,090 kg	No. of Owners ⓘ	4
Type of Vehicle	Hatchback		

Features

Powerful And Fuel Efficient 1.6L DOHC VVT Engine, 5 Speed Manual Transmission, Knockdown Rear Seats. View specs of the Suzuki Swift

Accessories

Semi Bucket Sports Seats, SARD Radiator, Samco Hoses, Upgraded Sound System, D2Coilovers, Window Shade.

Description

They Say Only Real Man Drive 3 Pedals. One Of The Popular Pocket Hatch. Higher Loan Could Be Achieved. Call Our Experience Sales Executives To Avoid Disappointment. Viewing Strictly Via Appointment Only.

Category

COE Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

[Shortlist](#)
[Compare](#)
[Report Error](#)
[More](#)

Seller Information

Car Buddy Pte Ltd

31 vehicles for sale, 25 sold in past 3 mths

3 Ang Mo Kio Avenue 9 #01-02C/D

Far Horizon Garden

Search cars nearby

 Aizat	92319670 
Jayven	93269409 
Kelvin	84488668 

Posted on: 20-Feb-2021 | Last Updated on: 14-Mar-2021

[Upfront](#)
[SHORTLISTED](#)
[HISTORY](#)
[Compare](#)
[\\$25](#)
[more Financial info](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/03/2021 16:43 (SGT)
Date of Accident	19/03/2021 22:05 (SGT)
Exact Location of Accident	Geylang Road, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ3350Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	LQW Leasing
Company Reg No	5XXXX044M
Email Address	derrick21tan@hotmail.com
Mobile Phone No	(Phone) +65-81293444
Alternative Phone No	(Home) +65-81293444

VEHICLE PARTICULARS

Manufacturer	Suzuki
Model	Swift
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	VFX/P2322293
Cover Note Number	-

DRIVER

Name of Driver	Kew Yao Cheng
NRIC No	SXXXX966C

Date Of Birth	04/04/1994
Occupation	Outdoor
Date Of Driving Pass	08/04/2015
Driving experience	5 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81293444
Alt. Phone Number	-
Email Address	yaocheng6944@gmail.com
Address	1 Tampines North Drive #01-28
Address complement	-
Postcode	528559
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Jolyn Lee Wan Peng
Gender	Female

PASSENGER 2

Name	Elieen Lee Pei Shan
Gender	Female

PASSENGER 3

Name	Cheng Yew Lun
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached police report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMW3278X
Vehicle Manufacturer	Mini
Vehicle Model	Cooper
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Jolyn Lee Wan Peng
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SGQ3350Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	Elieen Lee Pei Shan
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SGQ3350Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

INJURED 3

Name of injured person	Cheng Yew Lun
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SGQ3350Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

INJURED 4

Name of injured person	Kew Yao Cheng
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-

Injured person in which vehicle?	SGQ3350Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstances of the Accident

Refer to attached police Report

Refer to attached police Report

Declaration

We declare the foregoing particulars are true in every respect.

LOH LEASING
122-83245844W

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

We declare the foregoing particulars are true in every respect.

LOW LEASING
822-822858644

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

LOW LEASING
832-522458644

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Policyholder's Signature / Date & Time	Driver's Signature (If driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
--	--	---

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel



**SINGAPORE
POLICE FORCE**



T/20210320/7003

3 of 3

Report No. T/20210320/7003

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPB /
TAY CHUN KEEN
Contact No.: 65476229

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
20/03/2021 02:32

Classification Of Case:



**SINGAPORE
POLICE FORCE**



T/20210320/7003

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20210320/7003

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	JOLYN LEE WAN PENG	ID No.	S9420507G
Related Vehicle	SGQ3350Y (Car)	Contact No.	93236588
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	03	Degree of	Serious
Driver			
Name	KEW YAO CHENG	ID No.	S9410966C
Related Vehicle	SGQ3350Y (Car)	Contact No.	81293444
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	03	Degree of	Serious

Brief Details.

On 19/03/2021, at about 1005HR, I was driving my vehicle (SGQ3350Y) with Jolyn Lee Wan Peng(S9420507G) and 2 others travelling along Geylang Rd before a shell station where suddenly I felt a impact on the right of my vehicle. I came down to check and realised I'm involved in an accident with a car(SMW3278X) filtering out.



**SINGAPORE
POLICE FORCE**



T/20210320/7003

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20210320/7003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/03/2021 02:32		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: KEW YAO CHENG			Address: 120 MARSILING RISE #12-56 SINGAPORE 730120		
ID Type / ID No.: NRIC NO / S9410966C			Contact No.: Home/Office: Mobile: 81293444		
Nationality: SINGAPORE CITIZEN			Email: YAOCHENG6944@GMAIL.COM		
Sex: Male	Age: 26	Date of Birth: 04/04/1994	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Grab driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/03/2021 22:05	Type of Location: Straight Road
Location: GEYLANG ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of
SGQ3350Y	Car				Seriously Damaged	3
SMW3278X	Car				Seriously Damaged	0

Customer:

Company:

License No: SGQ3350Y

Odometer:

Date:

6/4/2021 10:04 AM


VIN

Technician:

Order No.:

Graphic Alignment Report

SUZUKI, 2005, SWIFT(Custom)



RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -15%	
SN	
Labour	
Total	
Lump Sum	
ERV	

TO: CT

Vehicle No : SGQ 3350 Y

Make & Model : SUZUKI SWIFT

DATE: 5/4/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	HEAD LAMP RH <i>cm</i>	1	\$ 537.10	\$ 396 537.10
2	HEAD LAMP LOWER BRACKET RH ? <i>X su</i>	1	\$ 157.60	\$ - 157.60
3	FRONT BUMPER <i>de</i>	1	\$ 720.90	\$ 555 720.90
4	FRONT BUMPER SIDE RETAINER <i>ne</i> <i>1pc</i>	2	\$ 98.50	\$ 28 197.00
5	FRONT BUMPER FOG LAMP RH <i>X su</i>	1	\$ 311.00	\$ 311.00
6	FRONT BUMPER FOG COVER RH <i>X su</i>	1	\$ 155.90	\$ 155.90
7	FRONT BUMPER DIFFUSER <i>cm</i>	1	\$ 355.80	\$ 170 355.80
8	FRONT BUMPER UNDER COVER <i>X su</i>	1	\$ 317.40	\$ 317.40
9	FRONT FENDER RH <i>bt</i>	1	\$ 390.60	\$ 275 390.60
10	FRONT FENDER QUARTER COVER RH <i>X su</i>	1	\$ 89.00	\$ 89.00
11	FRONT FENDER INNER SHIELD RH <i>X su</i>	1	\$ 198.00	\$ 198.00
12	FRONT LOWER ARM RH ? <i>bt</i>	1	\$ 260.00	\$ 189 260.00
13	FRONT KNUCKLE ARM RH ? <i>bt</i>	1	\$ 385.30	\$ 223 385.30
14	FRONT WHEEL BEARING RH ? <i>bt</i>	1	\$ 184.60	\$ 121 184.60
15	FRONT LINKAGE RH <i>X su</i>	1	\$ 237.10	\$ 237.10
16	FRONT DRIVE SHAFT RH <i>X su</i>	1	\$ 985.00	\$ 985.00
17	STEERING RACK AND PINION <i>X su</i>	1	\$ 1,350.00	\$ 1,350.00
18	SIDE SKIRT RH <i>cm</i>	1	\$ 745.00	\$ 267 745.00
19	FRONT DOOR RH <i>repair</i>	1	\$ 795.30	\$ 795.30
20	FRONT DOOR FRAME SIDE BLACK STICKER RH <i>X su</i>	2	\$ 95.00	\$ 190.00
21	FRONT DOOR SIDE MIRROR RH <i>repair</i>	1	\$ 455.00	\$ 455.00
22	FRONT DOOR OUTER MOULDING RH <i>X su</i>	1	\$ 188.90	\$ 188.90
23	FRONT DOOR HINGE RH <i>X su</i>	2	\$ 144.90	\$ 289.80
24	FRONT DOOR CHECKER RH <i>X su</i>	1	\$ 137.50	\$ 137.50
25	FRONT DOOR INNER LOCK RH <i>X su</i>	1	\$ 311.00	\$ 311.00
26	FRONT DOOR WEATHERSTRIP RH <i>X su</i>	1	\$ 198.00	\$ 198.00

	2224		
	152	Subtotal :	\$ 10,142.80
	1890.40	Less 15% :	\$ 1,521.42
		Parts Total :	\$ 8,621.38

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER CLIPS SET <i>na</i>	1	\$ 50.00	\$ 30 50.00
2	FRONT BUMPER UNDER COVER CLIP SET <i>X na</i>	1	\$ 40.00	\$ 40.00
3	FRONT GRILLE <i>con</i> <i>pru 550</i>	1	\$ 1,200.00	\$ 1,200.00
4	FRONT FENDER INNER SHIELD CLIP <i>na</i>	1	\$ 40.00	\$ 40.00
5	FROTN ADJUSTABLE ABSORBER SET <i>X su</i>	1	\$ 1,600.00	\$ 1,600.00
6	SPORT RIM <i>su</i> <i>920</i>	1	\$ 1,200.00	\$ 300 1,200.00
7	TYRE <i>X su</i>	1	\$ 400.00	\$ 400.00
				\$ 4,530.00

	LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	<i>600</i>	\$ 1,600 0.00
TO SPRAY PAINT AFFECTED AREA	<i>700</i>	\$ 1,600.00
TO PERFORM LIGHTING & WIRING CHECK	<i>30</i>	\$ 150 0.00
TO APPLY ANTI-RUST & TUFF KOTE	<i>1530</i> <i>40</i>	\$ 250 0.00
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	<i>na X</i>	\$ 450.00
REMOVE AND INSTALL FRONT UNDER CARRIAGE <i>phat?</i>	<i>100</i>	\$ 500 0.00
TO CHECK FOUR WHEEL ALIGMENT - alignment copy	<i>60</i>	\$ 100 0.00
REMOVE AND INSTALL FRONT DOOR PARTS	<i>X na</i>	\$ 200.00
	<i>1890.40</i>	
	<i>920.00</i>	
	<i>1530.00</i>	
	LABOUR TOTAL	\$ 4,850.00

<i>4340.40</i>	Total Parts Cost	\$ 13,151.38
<i>209</i>	Total Labour Cost	\$ 4,850.00
<i>6</i>	Total Repair Cost	\$ 18,001.38
<i>3472.32</i>		

APPROVED DETAILS

NO. OF WORKING DAYS *6 days*

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY - *06/04/21 @ 1050* *\$1,500*

SURVEYED BY *RASUL CLKK*

CONTACT NUMBER *90010068*

FAX NUMBER

Resny after repair

L/S-3,450

Repair limit

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: