

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Ray Lye
Date: 05.04.2021
Time: 16:08:14
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305462181
REGN NO : SHA4271H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I40
DATE OF REGN : 12.05.2016
DATE/TIME IN : 05.04.2021 15:00
ACCIDENT DATE : 03.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER W LIP & FOG LAMP C	1	1,025.20	20.00	820.16	820.16
0002 04-01-0103-0574-A PANEL-FENDER LH+	1	663.00	20.00	530.40	530.40
SUB-TOTAL :					1,350.56

JOB NATURE

0000 PB	PANEL BEATING	600.00	280
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 20-05	RENEW ADVERTISMENT STICKER-fender	100.00	880
SUB-TOTAL :		1,300.00	

TOTAL : 2,650.56 1410.40

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

1/4/21 15:00
2 days #

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanphie 92495749
WP 6/4/21 3pm
1/5 Resurvey after repair
2 days
Tanphie 1/4/21