

ASS. REC. BY: GQ

REF: CS3/Asm 1901611 / ~~Fals~~

Special Instruction:

Surveyor: ~~Rain~~

ASSIGNMENT (Office)

5/4/2021 5:18 PM

From (Person):

~~Daniel~~ ~~Pau~~

of

Asm (AXA)

Date/Time:

~~10.9.19 10.47am~~

Estimated Cost:

HENG XIN YI

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 3841P

Insured:

YP 6494M

at Workshop m/s

Paul Hoe Batteries & Motor Services

Tel:

96235068

of

1 Kaki Bukit Ave 6 #01-109

Policy No:

Claim No:

59 M02011

Sum Insured:

Excess:

Make of Veh:

D.O.A.

7.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

imp?

H.O.D. Endorsement:

Date/Time:

11.9.19

9.56am

Person Contacted:

Paul

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLL 3841P - X
	YP 6494 M - CC4/Asm 19008585/K129352
	Dismantle: 11/9/2019
	After repair: 16/9/2019

D.O.A - 09/05/2018

PRV 1104
Bureau

REF:

ASM (AXA)

PRS

ASSIGNMENT

From:

Date:

11.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 3841P

at Workshop n/s Paul Hoe Batteries

of 1 Kaki Bukit Ave 6 #01-109

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLL 3841P

Yr Regn:

FEB / 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA HRV

C.C 1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

58303

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRV1830GX2016S3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60 R16

R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

4

mm

L/Bal.

5

mm

L/Bal.

4

mm

D.O.A.

07/09/2019

D.O.I.

11/09/19

1226pm

Survey held at

Paul Hoe Batteries

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$3000-\$4000

Repair days: 5 days

MV: \$12000

PV: \$51162

NV: \$20000

12/9/2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

5

1)

☐

Final Report

Resurvey No. of Trip:

2

Survey Fee:

100

Transportation:

) S + RS: \$

) Photos

) Others

)

TOTAL

100

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

PRS

Lump Sum / I.B.I. (\$

Nivitha (LKK Auto)

From: santosh.nikam@axa.com.sg
Sent: Tuesday, 10 September 2019 5:00 PM
To: admin-d@lkkauto.com
Subject: Service appointment in Vendor Portal: claim S9M02011 for vehicle SLL3841P

AXA confirms your appointment as Surveyor / Assessor (Company), to carry out Pre-Repair Survey service for claim number S9M02011.

Please log in to <https://vp.smartclaims.axa.com.sg/claim-portal/>

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Service Request Details

Claim

S9M02011

Reference

None 

Loss Date

September 7, 2019

Report Date

Sep 10, 2019 11:58:12 AM

Request Date

September 10, 2019

Due Date

September 17, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

P. Paul

T: 9.56 a.m

V: In

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLL3841P

Model
UNKNOWN

Service Address

...

Primary Contact/Insured

SRM SERVICES
29 TAI SENG AVENUE, #03-07, NATURAL COOL LIFESTYLE HUB, 534119, Singapore
63380083
JEUNESSE@VIRTUALINVEST.BIZ

Claim Handler

PAY Daniel

zhihao.pay@axa.com.sg

Additional Instructions

2

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From: Rachel Ling <jin@tcmg.com.sg>
Sent: Tuesday, 10 September, 2019 10:47 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: 'Ling Leong Hui'; 'Jenny'; 'Mdm Ling'
Subject: [EXTERNAL] PRE REPAIR INSPECTION NOTICE FOR SLL 3841 P | YOUR REF: YP 6494 M

Categories: Santosh

Our Ref :TCMG/SLL 3841 P/0919/PHB
Your Ref: YP 6494 M

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Wu Jingxun Eric**, the owner and/or driver of motor vehicle no. **SLL 3841 P**, which was involved in an accident along Bedok North Road beside Block 109 on 7th September 2019 at 16:10 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **YP 6494 M** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Paul Hoe Batteries & Motor Services, (1 Kaki Bukit Avenue 6 #01-109 - Paul Hoe @ 9623 5068).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Regards,
Rachel Ling

TOMMY CHOO, MARK GO LLC
151 Chin Swee Road
#14-15/16 Manhattan House
Singapore 169876

Tel: 6532 2455
Fax: 6538 9850



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 6256350

To : AXA Insurance Pte Ltd

Survey details

Date of loss	7-Sep-19
Date of appointment	10-Sep-19
Date of survey	11-Sep-19
Location of survey	PAUL HOE BATTERIES & MOTOR SERVICES

Vehicle Details:

Claim Type:	Third Party
Vehicle number	SLL 3841P
Make and Model	HONDA HRV 1.5 LX CVT
Date of registration	23-Feb-17
Excess	
Market Value	\$72,000
Parf Rebate	\$51,162
Nett Loss	\$20,838

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	

Number of days of repair	5
--------------------------	---

Remarks:

The estimated repair cost of the
damaged vehicle is in the region of
\$3,000.00 - \$4,000.00

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:		Singapore NRIC
Owner ID:		795Z
Vehicle Details		
Vehicle No.:		SLL3841P
Vehicle to be Exported:		No
Intended Deregistration Date:		12 Sep 2019
Vehicle Make:		HONDA
Vehicle Model:		HRV 1.5 LX CVT
Primary Colour:		Silver
Manufacturing Year:		2016
Engine No.:		L15B4531653
Chassis No.:		JHMRU1830GX201653
Maximum Power Output:		96.0 kW (128 bhp)
Open Market Value:		\$23,687.00
Original Registration Date:		23 Feb 2017
First Registration Date:		23 Feb 2017
Transfer Count:		0
Actual ARF Paid:		\$20,162.00 $\times 50\% = \underline{\underline{\$10,081}}$
Intended PARF Rebate Details		
PARF Eligibility:		Yes
PARF Eligibility Expiry Date:		22 Feb 2027
PARF Rebate Amount:		\$15,121.00
Intended COE Rebate Details		
COE Expiry Date:		22 Feb 2027
COE Category:		A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):		10
QP Paid:		\$48,401.00
COE Rebate Amount:		\$36,041.00
Total Rebate Amount:		\$51,162.00

The information contained herein is correct as at 12 Sep 2019

Remaining: 7 years 5 months 15 days (89.5) OK

Depri: \$8400/yearly \$700/monthly

$89.5 \times \$700 = \$62,650$

$\$62,650 + \$10,081 = \$72,731$

CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Sleek Black Avantgarde E250, New Road Tax, C&C Unit



Full C&C Serviced, New Road Tax, High OMV, Low Mileage Used Direct Owner [StarAd](#)



Lake View Credit Pte Ltd

[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

13 vehicles

honda hrv

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda hrv	Any	Any	2017	Any	Any	Any	Available

Honda HR-V 1.5A LX

\$75,800

\$8,610 /yr

13-Jun-2017

1,496 cc

22,000 km

SUV

Available

Full Agent Unit 5 Yrs Unlimited Mileage Warranty! Very Low Mileage Of 22K Km. Car Is In Immaculate Condition. Seldom Used And 100% Accident Free. Always Parked Under Shelter. Full Service Record In Kah Motors. Owner Buy As A 2nd Car But Hardly Use. Never Used As...

DIRECT OWNER

Posted: 11-Sep-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda

Honda HR-V 1.5A DX

\$79,000

\$8,870 /yr

16-Oct-2017

1,496 cc

25,138 km

SUV

Available

Kah Motor Unit. Full Agent Maintained. 5 Years Unlimited Mileage Warranty Till Oct 2022. Premium Crystal Red Metallic Exterior With Black Interior. Non-PHV Unit. Popular SUV In The Market. Spacious Leg Room With Large Boot Space. Attractive Interest Rate From 1.99%. Pl...

PREMIUM AD

Inchcape Pre-Owned

Posted: 11-Sep-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda

Honda HR-V 1.5A DX

\$75,800

\$8,460 /yr

19-Oct-2017

1,496 cc

34,000 km

SUV

Available

Enjoy Lowest Interest Rates At 1.98%! Loan Of Up To 90% Is Available Here! A Very Reliable Family Oriented SUV That Will Never Fail You. The Most Popular Fuel Efficient And Spacious SUV In The Market. Still Under Agent Warranty. One Owner Only. 100% Accident Fre...

PREMIUM AD

Euro Performance Asia Pte Ltd

Posted: 09-Sep-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda

Honda HR-V 1.5A DX

\$75,888

\$8,460 /yr

27-Oct-2017

1,496 cc

25,976 km

SUV

Available

Sporty Black Color, 1 Careful Owner, Fully Serviced And Maintained By Kah Motor With 5 Years Warranty. Low Mileage Done At 25976km Only. Extremely Well Maintained By Meticulous Owner. Bank/In House Loan Available. Buy With A Peace Of Mind. Trade In Welcome, Co...

PREMIUM AD

Posted: 06-Sep-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda

Skoda Karoq takes on Honda and Subaru

The Skoda Karoq is the latest entry into our crossover segment but how well does it fare against more established rivals like the Honda HR-V and the Subaru XV?

[Read this article](#)

Honda HR-V 1.5A LX

\$77,800

\$8,760 /yr

17-Jul-2017

1,496 cc

34,370 km

SUV

Available

1 Owner! Low Mileage Of Only 34000km Travelled! Full Agent Service Records With Agent Warranty Till July 2022! High Trade In And In House Financing Available! View Today.

Posted: 06-Sep-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda

Honda HR-V 1.5A LX

\$77,800

\$8,430 /yr

06-Dec-2017

1,496 cc

18,000 km

SUV

Available

High Specs LX Model With Lowest Mileage Done Per Year And Lowest Depreciation, Even Lower Than DX Models! Director's 2nd Car. Immaculate Condition. Fully Agent Serviced. Warranty Still With Kah Motor. As Good As One Owner As Director Transfer The Ownership...

PREMIUM AD

Posted: 05-Sep-2019 Tags: 2017 Honda HR-V, 2017 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda

Honda HR-V 1.5A DX

\$72,800

\$8,720 /yr

28-Feb-2017

1,496 cc

36,000 km

SUV

Available

1 Owner, Full Agent Unit 5Yrs Unlimited Mileage Warranty! Low Mileage Of 36k Km. Car Is As Good As New. Accident Free. Always Parked Under Shelter. Buy With Peace Of Mind. Owner Sold Due To Family Expanding, Changing To 7 Seaters. 100% Loan Available. We Do Hig...

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 13:58
Date Of Accident	07/09/2019 16:10
Exact Location Of Accident	ALONG BEDOK NORTH ROAD BESIDE BLK 109
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3841P
Insured/Policyholder	
Name Of Registered Owner	WU JINGXUN ERIC
NRIC No	S8510795Z
Email Address	COSLAYER@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91996619
Alternative Phone No	OFFICE-91996619

Vehicle Particulars

Manufacturer	HONDA
Model	HRV 1.5 LX CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01002439
Cover Note Number	

Driver

Name of Driver	WU JINGXUN ERIC
NRIC No	S8510795Z
Date Of Birth	09/04/1985
Occupation	INDOOR
Date Of Driving Pass	22/09/2006
Driving Experience	12 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91996619
Fax Number	
Contact Number	OFFICE-91996619
EMail Address	COSLAYER@HOTMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KOH BEE LIAN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

My vehicle was stationary in the middle lane of BEDOK NORTH ROAD waiting for traffic to clear ahead of me suddenly third party vehicle collided onto my vehicle rear. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6494M
Vehicle Make/Model/Colour	ISUZU / FRR90SUQA-C
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	K GORDON
NRIC/Passport Number	S9128488Z
Contact Number	87693034
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER

MOHAMED SAIFULLAH S/O SYED MASOOD

Policyholder's Signature

Date & Time:

8 Sep 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name:

ARC/IN No.

SKETCH PLAN



Vehicle A: SLU3841P
Vehicle B: YP6494M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT

DECLARATION

I/we declare the foregoing particulars are true in every respect

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

ACCIDENT STATEMENT (2000 characters)

My vehicle was stationary in the middle lane of BEDOK NORTH ROAD waiting for traffic to clear ahead of me suddenly third party vehicle collided onto my vehicle rear. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

8 September 2019 at 3:56 PM

Date/Time:

8 September 2019 at 3:56 PM



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS3/ASM19016111/Fcf3e2		
8 SHENTON WAY #24-01		Date: 23-09-2019		
AXA TOWERSINGAPORE 068811				
ATTN : DANIEL PAY		Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YP 6494M	Veh. Inspected	SLL 3841P	
Policy No.		Coverage (\$)	0.00	
Claim No.	S9M02011	Excess (\$)	0.00	
Assign From	DANIEL PAY	Assign Date	10/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRU1830GX201653	Colour	SILVER	
Odometer	58303 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	5 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	4 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	07/09/2019	Inspect Date / Time	11/09/2019 (12:25 PM)	
Survey held at	PAUL HOE BATTERIES & MOTOR SERVICES BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/ASM19016111/Fcf3e2

Inspected By

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.