

(08/51/13) wef
ASS. REC. BY: Paul

REF:

CC3/A1421004320/RITC

390J

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT9574R

at Workshop m/s. PREMIUM

of PREMIUM SECURE

Insured: AKH

Policy No. 3764746846SG

Claims No. 3764746846SG

Sum Insured: _____ Excess: TMA

(Client's Record) 800

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 5AK 62K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKT9574R Yr Regn: 2015 JMW

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ANDI A41-8 TFS / MU c.c 1798

Colour: BLACK A/C: Insured / Std / NI / NA

Sp.Reading: 112119 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ2BK6FA115080

Gen. Cond: Good / ☒ Fair / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/03/21 D.O.I. 05/04/21 @ 1630

Survey held at PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit 12k

Confirm All in \$17,000/- 17days.

red: 30515.50; 74%

red:

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 17

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0277/2021/HR
DATE : 1-Apr-21
WIP : 21811

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LEE SWEE LING CHERYL
ADDRESS : 46 ALMOND CRESCENT
SINGAPORE 677800
TELEPHONE : HP +65 81101773
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100473850-04
VEHICLE NO : **SKT 9574 R**
MODEL CODE : A4 1.8 FSI MU
MODEL YEAR : 26/6/2015
ENGINE NO : CJE 100458
CHASSIS NO : WAUZZZ8K6FA115080
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Mar-21
PLACE OF ACCIDENT : PIE TOWARDS CHANGI, NEAR LAMPOST NO 1794

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 9574 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE & REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	/
2	TO REMOVE & TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM & WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	/
3	TO RENEW REAR WINDSCREEN & LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$	600.00	/
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN & LHS 1/4 GLASS.	S/N \$	400.00	X
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN & 1/4 GLASS.	S/N \$	200.00	/
6	TO DISLODGE & REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE & RELAY TRAYS, ELECTRICAL & AUDIO EQUIPMENT. INSPECT FOR DAMAGE & RENEW WHERE NECESSARY.	S/N \$	1,400.00	/
SUB TOTAL LABOUR CHARGES		:	\$ 3,160.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKT 9574 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE & REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER & DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 X	
9	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00 ?	
10	TO PUT THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$ 1,800.00 ?	
11	TO DISMANTLE & RENEW REAR BUMPER & REAR LID. TO CUT OUT & WELD LHS REAR FENDER, LHS CONNECTING PLATE, LHS BOTTOM PLATE & LHS INNER SIDE PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 9,100.00 ✓ <i>3500</i> <i>(7) @ 500</i>	
12	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS, LHS SILL PANEL, LHS CONNECTING PLATE, LHS BOTTOM PLATE, LHS INNER SIDE PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES & END PANELLING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION & JOINT SEALER WORKS.	S/N \$ 7,700.00 ✓ <i>3575</i> <i>@ 550</i> <i>(6-5)</i>	
13	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 24,432.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>de /</i>	1	\$	2,451.00	
2	REAR BUMPER FIXING APRTS <i>?</i>	1	\$	228.00	
3	REAR BUMPER SPOILER <i>scr /</i>	1	\$	267.00	
4	REAR BUMPER CARRIER <i>?</i>	1	\$	681.00	
5	REAR BUMPER HOLDER BRACKET <i>7: x 9</i> <i>LH / RH</i>	2	\$	446.00	223
6	REAR BUMPER GUIDE SECTION <i>7</i> <i>LH / RH</i>	2	\$	89.00	44.50
7	REAR BUMPER UPPER GUIDE SECTION <i>7</i> <i>LH / RJ</i>	2	\$	47.00	23.5
8	REAR BUMPER PIN <i>?</i>	<i>1 pc /</i>	\$	12.00	6
9	REAR BUMPER SECURING STRIP <i>?</i>	1	\$	14.00	
10	REAR BUMPER PARKING AID SENSOR <i>dis -</i>	<i>1 pc /</i>	\$	732.00	244
11	REAR BUMPER PARKING AID SENSOR SEAL <i>re /</i>	4	\$	6.00	
12	REAR BUMPER WIRING SET <i>?</i>	1	\$	515.00	
13	REAR BOOT LID <i>st /</i>	1	\$	3,361.00	
14	REAR BOOT LID ATTACHMENT PARTS <i>?</i>	1	\$	75.00	
15	REAR BOOT LID HINGE - LH / RJ <i>?</i>	1	\$	512.00	
16	REAR BOOT LID GASKET <i>re /</i>	1	\$	205.00	
17	REAR BOOT LID ADHESIVE <i>re /</i>	1	\$	19.00	
18	"A4" EMBLEM <i>re /</i>	1	\$	99.00	
19	"AUDI" EMBLEM <i>re /</i>	1	\$	138.00	
20	"TFSI" EMBLEM <i>re /</i>	1	\$	99.00	
SUB TOTAL SPARE PARTS		:	\$	9,996.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR SIDE PANEL - LH <i>buc /</i>	1	\$ 4,003.00	
22	REAR WINDOW <i>q X</i>	1	\$ 1,128.00	
23	REAR SIDE WINDOW - LH <i>nee /</i>	1	\$ 305.00	
24	PRIMER <i>ne /</i>	1	\$ 20.00	
25	BOTTOM OUTER FLOOR PLATE - LH <i>?</i>	1	\$ 403.00	
26	REAR SIDE PANEL CONNECTING PLATE - LH <i>?</i>	1	\$ 340.00	
27	REAR OUTER WHEEL HOUSING - LH <i>?</i>	1	\$ 647.00	
28	REAR SIDE PANEL - LH <i>?</i>	1	\$ 206.00	
29	REAR WHEEL HOUSING LINER - LH <i>at /</i>	1	\$ 222.00	
30	REAR WHEEL HOUSING LINER ATTACHMENT PARTS - LH <i>ne /</i>	1	\$ 45.00	
31	REAR SIDE PANEL VENT TRIM <i>de /</i>	1	\$ 72.00	
32	OUTER TAIL LIGHT - LH <i>bo /</i>	1	\$ 1,075.00	
33	INNER TAIL LIGHT - LH <i>sc /</i>	1	\$ 901.00	
34	REAR CROSS PANEL TRIM <i>?</i>	1	\$ 189.00	
35	REAR BOOT COMPARTMENT TRIM - LH <i>de /</i>	1	\$ 413.00	
36	REAR BOOT COMPARTMENT FLOOR COVERING <i>X</i>	1	\$ 708.00	
37	REAR BOOT LID TRIM <i>X</i>	1	\$ 278.00	
38	REAR BOOT WARNING TRIANGLE RETAINER <i>X</i>	1	\$ 58.00	
39	REAR BOOT WARNING TRIANGLE <i>X</i>	1	\$ 193.00	
40	REAR DOOR SILL TRIM STRIP - LH <i>?</i>	1	\$ 89.00	
SUB TOTAL SPARE PARTS		:	\$ 11,295.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKT 9574 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	1/ GLASS SEALANT <i>new</i>	S/N	\$	100.00	
42	ACRYLIC SEALANT <i>new</i>	S/N	\$	180.00	
43	CAVITY WAX <i>new</i>	S/N	\$	140.00	
44	STONE CHIP <i>new</i>	S/N	\$	180.00	
45	METAL FILLER POWDER <i>new</i>	S/N	\$	280.00	
46	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$	200.00	
47	SUNDRIES <i>?</i>		\$	400.00	
TOTAL SPARE PARTS		:	\$	22,771.00	
TOTAL LABOUR CHARGES		:	\$	24,432.00	
GRAND TOTAL		:	\$	47,203.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Resur - 4p 90010068

: 05/04/21 @ 1630

: 14 days

: EXCESS: TBA

: Resur before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/04/2021 15:13 (SGT)
Date of Accident	31/03/2021 17:50 (SGT)
Exact Location of Accident	Near PIE, Singapore
Additional Location Information	PIE TOWARDS CHANGHI, NEAR LAMPOST NO. 1794
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT9574R
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LEE SWEE LING CHERYL
NRIC No	SXXXX340J
Email Address	ACTAY.55@GMAIL.COM
Mobile Phone No	(Phone) +65-81101773
Alternative Phone No	+65-67608240

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A4
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1795

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100473850-04
Cover Note Number	-

DRIVER

Name of Driver	CLARISSE TAY SIEW CHENG
NRIC No	SXXXX344I

Date of Birth	18/11/1994
Location of Driving Pass	Indoor
Driving experience	10/09/2013
Gender	7 YEARS AND 6 MONTHS
Mobile Number	Female
Alt. Phone Number	(Phone) +65-92769052
Email Address	-
Address	CLARISSETAY@GMAIL.COM
Address complement	46 ALMOND CRESENT
Postcode	-
Is the driver the policyholder?	S677800
If No, Relationship of the Driver with the Insured	No
Does Driver Own Other Vehicles?	Child
Vehicle Registration Number of Other Vehicle Owned by Driver	No
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	CHLOE TAY
Gender	Female

PASSENGER 2

Name	BLAKE TAY
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ON PIE TOWARDS CHANGI AND JUST PASSED THE JLN BAHAR EXIT. I WAS ON THE 3RD LANE HEADING TOWARDS THE KJE (BKE) EXIT WHEN THE CARS INFRONT OF ME SLOWED DOWN AND CAME TO A STOP SO I ALSO SLOWED DOWN AND STOPPED BEHIND THE CAR INFRONT OF ME. I SAW FROM MY REAR VIEW MIRROR THAT A WHITE VAN WAS COMING TOWARDS ME VERY FAST, AND IN ORDER FOR IT TO TRY TO AVOID HITTING DIRECTLY INTO MY REAR, IT SWERVED TO THE LEFT. UNFORTUNATELY IT STILL HIT THE REAR LEFT SIDE OF MY CAR. THE VAN THEN CAME TO A STOP ON THE LANE NEXT TO ME ON MY LEFT. SOON AFTER THAT, ANOTHER CAR BEHIND THE WHITE VAN - A TOYOTA CAR - ALSO HIT INTO MY REAR ON THE LEFT SIDE

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC8072J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJE132H
Vehicle Manufacturer	Toyota
Vehicle Model	Alphard
Vehicle Variant	-
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time



charisse

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan




PIE TOWARDS

Describe Circumstances of the Accident

I was driving on the PIE towards Changi and just passed the Jln Bahar exit. I was on the 3rd lane heading towards the KJE (BKE) exit when the cars in front of me slowed down and came to a stop so I also slowed down and stopped behind the car in front of me. I saw from my rear view mirror that a white van was coming towards me very fast, and in order for it to try to avoid hitting directly into my rear, it swerved to the left. Unfortunately, it still hit the rear left side of my car. The van then came to a stop on the lane next to me on my left. Soon after that, another car behind the white van - a Toyota car - also hit into my rear on the left side.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

★ Clarisse
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Audi A4 1.8A TFSI MU

Overview Financial Accessories Similar Research Photos Map

Price \$59,000

Depreciation ? \$11,230 /yr
View models with similar depre
Reg Date 25-Jun-2015
(4yrs 2mths 17days COE left)

Mileage 88,700 km (15.3k /yr)
Manufactured ? 2015

Road Tax ? \$976 /yr
Transmission Auto

Dereg Value ? \$46,438 as of today (change)
OMV ? \$29,476

COE ? \$71,509
ARF ? \$23,267

Engine Cap 1,798 cc
Power 125.0 kW (167 bhp)

Curb Weight ? 1,545 kg
No. of Owners ? 1

Type of Vehicle Luxury Sedan

Features

1.8L Turbocharged Engine, 8 Speed Multi Tronic Auto Transmission, Cruise Control, Sport Mode, ABS, ESP, 8 x Airbags, Electronic Parking Brake. View specs of the Audi A4 (2005-2007)

Accessories

Factory Audi Audio System With MMI Screen, Electric Driver Seat, Retractable Side Mirrors, Reverse Sensors, Recorders.

Description

Monthly Installment From \$900/Month! Car's In Fantastic Condition! One Of The Cheapest In The Market And Lowest Depreciation Guaranteed! Smooth Engine And Transmission. Original Paintwork! Clean Interior And Exterior! Powerful And Fuel Efficient Drive! Well Taken Care By Previous Owner! Please Contact Us For A Viewing Appointment! Trade In Welcome! Full Loan Available! Don't Miss It.

Category

PARF Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



sgCarMart Used Car Warranty

Get \$0 future car repair bill. Ask your dealer for a warranty on this car. Learn more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

SHORTLISTED HISTORY

Compare




tion

https://www.sgcarmart.com/used_cars/info.php?ID=956214&DL=3100



Location Map

Price Chart



Click on the point to view the vehicle

Shortlist

Compare

More

Seller Information

Sphere Auto Pte Ltd

17 vehicles for sale. 16 sold in past 3 m

19 Jurong Port Road
Search cars nearby

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	340J
Vehicle No.:	SKT9574R
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Apr 2021
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU (EU6)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CJE100458
Chassis No.:	WAUZZZ8K6FA115080
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$29,476.00
Original Registration Date:	26 Jun 2015
First Registration Date:	26 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$23,267.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2025
PARF Rebate Amount:	\$16,286.00
COE Expiry Date:	25 Jun 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,501.00
COE Rebate Amount:	\$30,152.00
Total Rebate Amount:	\$46,438.00

The information contained herein is correct as at 07 Apr 2021

OK