



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /EUNICE BOH CHEK CHING (EUNICE M Reg No/Reg Date SML718X / 03/05/201 Date In/Mileage / 23845 Chassis No KNAF3416MK5031212 Engine No G4FGJH722098 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX00000	Credit	05/04/2021/ 16:29	QUD	247 / DonBong	31553				2400.00
Description of Goods / Services									
E PNT88000									1800
RENEW ACCIDENT DAMAGED PARTS ON LH FRONT DOOR, LH REAR DOOR, CUT/WELD PANEL-SIDE SILL, OUTRER, LH, REPAIR LH REAR FENDER <i>4 1/2 X 40</i>									
E PNT88000									120.00
TO TRANSFER LH FRONT DOOR GLASS, DOOR TRIM, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL									
E PNT88000									120.00
TO TRANSFER LH REAR DOOR GLASS, DOOR TRIM, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL									
E PNT88000									1750.00
TO REMOVE AND INSTALL FLOOR CABIN TRIM CABIN TO FACILITATE REPAIR WORK									
E PNT98000									1480
PAINT WORK SPRAY LH FRONT DOOR, LH FRONT DOOR HANDLE, LH REAR DOOR, PANEL-SIDE, SILL OUTRER, LH, LH REAR FENDER AND AFFECTED PORTION <i>4 PM + 80</i>									
M SUNDRY									80
SUPPLY BODY SEALANT									
A 54900099									40
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									
M SUNDRY									120.00
PERFORM RUST PREVENTION									
A 10028901									20
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST									
M SUNDRY									1021.60
SUNDRIES									
M	PANEL ASSY-FRONT DOOR, LH					1.00	1277.00	20.00	1021.60
M	HINGE ASSY-FRONT DOOR, LH					1.00	30.00	20.00	24.00
M	HINGE ASSY-DOOR LOWER, LH					1.00	27.00	20.00	21.60
M	HANDLE ASSY-DOOR OUTSIDE, LH					1.00	164.00	20.00	131.20
M	COVER-FR DR O/S HDL LH					1.00	14.00	20.00	11.20
M	PAD-FR DR O/S HDL COVER, RH					1.00	5.00	20.00	4.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address (AIG Asia Pacific Insurance Pte. Ltd.) and Owner Name & Vehicle Info (EUNICE BOH CHEK CHING).

Table with 4 columns: Account No (LAX00000), Terms (Credit), Date/Time Printed (05/04/2021/ 16:29), CSE (QUD), Operator (247 / DonBong), WIP No (31553).

Main table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like PAD-FR DR O/S HDL HINGE, BASE ASSY-FR DR O/S HANDLE, etc.

SURVEYOR NAME: Steve (LKK) 5/4/21, 4.39pm
SURVEYOR SIGNATURE: [Signature]
DATE: [Blank]
REMARKS: P/P, 13 # days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
Windscreen damaged part(s) during resurvey
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Summary table with columns: Net (9,649.20), 7% GST on (675.44), Total Payable (10,324.64).

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.