

ASS. REC. BY:

Steve

REF:

AIG

CS/AIG21004324/Etc

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 2070136022

Claims No. 5473660109SG

Sum Insured:


Excess:

0

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMV 16220

Yr Regn:

18/9/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Stonic

c.c. 998

Colour:

Blue

A/C: Insured / Std / NI / N

Sp. Reading

11308

T/Radio: Insured / Std / NI / N

Eng/No:

KNA 068HVL6382829

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R17

R:

 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Continental*

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

5/4/21

D.O.I.

5/4/21

Survey held at

Cycle & Carriage

Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-85K

Confirm part by part \$7885.60, 9days

red:5009.4;38%

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: 9

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

8 + RS, SI

Phone

Others

TOTAL

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Insp

(\$



: Weekend

(\$

3rd Party:

od

ump Sum / UIC: 7885.60