SS. REC. BY: Taufuh REF: 1N	16
AS	SSIGNMENT
Date:	Veh No: SHD 4660C. Yr Regn: 20191 Dec
10111.	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
stimated Cost: DD / IFP I WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: Hunder long c.c /580
To Inspect Vehicle No:	Colour Blue AC: Insured / Std / NI / NA
at Workshop m/s	Sp.Reading T/Radio: Insured / Std / NI / NA
of	Eng/No: 11/9:67
Insured:	C/NO: KM M C851CV-291 10008.
Policy No.	Gen. Cond: Good Fair / Poor / Burnt
Claims No. Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
Sum moded.	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record) Make of Veh:	Modi: NII / SIRim / STD A/Rim or
mano si toni	Tyre Size: F:
(Policy Condition)	R:
Remark: The veh had commenced its	O/S BSIDUNIEXNOVAIGYIFSILIZAIMICIOHTSUIPIRISUMII
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal mm , NSSS
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A.
Lum Sum: % 3 Val.: Yes or No	Des. of Damages: Frt / Rear / Ots / N/S / U/C / Roomop or
CA REV REP. 24 HRS	. // // 00
Venicle:	The U/C / Chassis frame / Body Structure affected due to collision.
Date:Person contacted.	nich.
Date / Time Action / Instruction Action / Instruction	
	Days Of Repair:
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: Survey Fee:
1) : Final Report	. Transportation:
Date/Time, File Return to?	Add Fee: : Site Insp (\$)_s+RSSI
2) .	: Interview (\$) Photos
Rep rof ormal :	. Tech. Invs (\$) Others
Lump Sum (LBA: C)	:Weelfend (\$
Felitaly Assess Lespana .	TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE VTUC-CP

Date: 05.04.2021

Time: 08:49:52

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO

: 305461748 : SHD4660C

MILEAGE

: 0000000000

MAKE

: HYUNDAI

MODEL DATE OF REGN : IONIQ(G3) : 19.12.2019

DATE/TIME IN

: 03.04.2021 08:50

ACCIDENT DATE

: 01.04.2021

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0104-2137-G REAR WHEEL CAP LH 1 346.40 20.00 277.12

0002 28-01-0302-2017-A Rear Fender (PETROL ONLY) 1 30.00 10.00 27.00 AM

0003 28-01-9999-2023-A Rear Door APPS LH 1 80.00 10.00 72.00

0004 04-01-0104-2282-G REAR BUMPER

1 459.40 20.00 367.52 RY

0005 04-01-0101-0111-G REAR BUMPER CLIPS 10 L 22.00 20.00 17.60 ⋉

0006 04-01-0104-0596-G REAR DOOR LH

1 1,789.90 20.00 1,431.92

SUB-TOTAL : 2,193.16

JOB NATURE

0000 PB PANEL BEATING-Rear Fender LH etc

0001 SP

SPRAYPAINT CHARGE

900.00

0002 20-00

TUFF COAT ON AFFECTED PARTS.

0003 L

TRANSFER OF DOOR

120.00

SUB-TOTAL : 1,900.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE NTUC-CPP

Date: 05.04.2021 Time: 08:49:52

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

DATE:

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO **REGN NO** : 305461748 SHD4660C

MILEAGE

: 0000000000

MAKE

: HYUNDAI : IONIQ(G3)

MODEL DATE OF REGN

: 19.12.2019

DATE/TIME IN

: 03.04.2021 08:5

ACCIDENT DATE

: 01.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL

: 4,093.16

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

Tanphi 97495749 WP 5/4/218430

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 5280 Facsimile + 65 5280 975:

Date/Time: 03.04.2021 12:11

Page: 1

eam:

ARC Repair TP(CLSO)1

JOB CARD Sales Order:

KMHC851CVLU190626

JC NO.: 305461748

OMER

(R)

COMFORT TRANSPORTATION PTE LTD

7010045

OMERNO 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

MODEL IONIQ(G3)

HYUNDAI

REGN NO.: SHD4660C

03.04.2021 08:50

MILEAGE

YR OF MANU. 19.12.2019

CHASSIS

MAKE

TARGET DATE

COMPLETION DATE/TIME:

JUNT CARD NO.


JOB DESCRIPTION

ccident Date: 01.04.2021

ATURE: 3P 01.04.2021

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:		
SERVICE ADVISOR		CUSTOMER'S SIGNATURE
edgement Slip	Exit Pass	

SHD4660C

LIMTS

Signature/Date

Vehicle No.:

SHD4660C

f Service Advisor

Name of Service Advisor

To be kept by Security Guard

turned to Service Reception upon collection

\$J0421430002 / JP Knights Pte Ltd ENTRY DATE & TIME: 03/04/2021 10:03 (SGT) SUBMITTED BY: Ashikin VERSION: 1 (03/04/2021 10:03 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- . Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information
Country/State of Loss

03/04/2021 10:03 (SGT) 01/04/2021 20:15 (SGT) Ang Mo Kio Ave 3, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD4660C

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
Company Reg No
Email Address
Mobile Phone No
Alternative Phone No

Yes
COMFORT TRANSPORTATION PTE LTD
1XXXXX821R
fleetsafety@cdgtaxi.com.sg
(Phone) +65-97499612
(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer
Model
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category
Transmission
CC

-

Hyundai

Ioniq

Private hire

No - Claiming third party Taxi Auto

1580

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

AXA Insurance Pte Ltd ThirdPartyFireTheft Yes VFX/P2419138

DRIVER

Name of Driver NRIC No

POON KHYE CHEONG SXXXX991I Date Of Birth Occupation

Date Of Driving Pass Driving experience

Gender

Mobile Number Alt. Phone Number **Email Address**

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

22/12/1952 Outdoor

31/03/1983

38 YEARS AND 1 MONTH

(Phone) +65-97499612

fleetsafety@cdgtaxi.com.sg

BLK 51 STRATHMORE AVENUE #26-187

140051

No

Hirer

No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Major/Minor Rd

Clear Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No

No

No

Yes

2

2

PASSENGER 1

Name Gender

UNKNOWN Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT

ON 010421 AT AROUND 2015HRS, I WAS DRIVING MY VEHICLE A SHD4660C ALONG ANG MO KIO AVE 3. I HAD JUST MADE A U TURN ON THE SAME ROAD TOWARDS HOUGANG. VEHICLE B SLM678J HAD JUST MADE A WIDE LEFT TURN OUT FROM THE FILTER LANE OF SERANGOON NORTH AVE 3 AND HIT MY VEHICLE AFTER I HAVE COMPLETED MY U-TURN. I WAS DRIVING ON THE 3RD LANE WHEN SHE HIT MY REAR LEFT WHEEL ARCH AREA. THERE WAS DAMAGES AT THE AREA. THERE WAS NO INJURY.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident Was there any audio recorded?

Yes Yes

FILE IS NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer

SLM678J Honda

Vehicle Model Vezel Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number (Phone) +65-91726882 Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be ferwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of thereport being made available
 aforesaid:
- 8. Consent under the Personal Data Protection Act (PDPA) Lunderstand, acknowledge, agree and consent that
- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose anti/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured whicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved (all insurer(s) who have insured vehicle(s) involved (all insurer(s) who
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
- (IV) administering my claims (including the mailing of correspondence, statements, involves, reports or notices to me, which could involvedisclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or.
- (V) complying with applicable law in administering processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the issurers' lawyers/law firms, may/are permitted to collect,use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or ISIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & time

Sketch Plan

Driver's Signature (If driver is not the policyholder)/ Date & Time

Witnessed by Reporting Personnel

K411

A - SHD 4660C

B - SLM 6783

SERANGOON NORTH

AUENIUE 3

Doceri	ha	Circumstance	ne of	eha	Bookdows

On 010421 at around 2015hrs, i was driving my vehicle A
SHD4660C along Ang Mo Kio Ave 3. I had just made a U turn on the
same road towards hougang. Vehicle B SLM678J had just made a
wide left turn out from the filter lane of serangoon north ave 3 and
hit my vehicle after i have completed my u-turn. I was driving on the
3rd lane when she hit my rear left wheel arch area. There was
damages at the area. There was no injury.
The state of the s

Declaration

I/We declare the foregoing particulars are true in every respect.

透透剂

Driver's Signature (If driver is not the policyholder)/ Date & Time 2/4/2/ 0945

MAI