COMFORTDELGRO
ENGINEERING

305461732		
08184121		
: 	: 305461732 : 08/0/-/21	

Date	Э	08'04121	59 Loya	DelGro Engineering Pte Ltd ng Drive Singapore 508969			
FIN	ALIZA1	TON FORM	Fax: 65	46 8156			
То	: _	LKK	Fax :				
Attn	ž.	TAUFIKH	_				
Veh	icle Re	g No. : SHD3310U	_	01/04/21			
The	survey	and estimates of the repairs of the above-mention	ned vehicle are as follows:-				
Z	The	repair job shall bill to:	NTUC	GBB615S			
2.	The	finalized amount shall be:					
	(a)	Spare Parts after List discount		<u> </u>			
	(b)	Labour Charges					
		Total for Part-By-Part Repair Cost					
	(c.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost		\$2,300.00			
3.	Estin	nated normal period for repairs:3_	working days.				
 We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 							
5.	Than	k you for your assistance.	We confirm the esti finalized amount				
	Signa	ature:	Signature:	rufikh			
	Name	: CHIANG	Name : Ta	aufikh			
	Tel	: 62148314	Date 2	8/4/21			
	Fax	65468156					
For (Official	Use Only					

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day		YES			
2. Loss of Income Paid	H	N			
3. Survey Fees	H	100			
4. LTA Search Fee	\$7.49/\$2.00				
Medical Fees (on behalf of driver, if applicable)				_	
6 Overrun					

kemarks:				