

ASS. REC. BY:

REF: CS3/III20008937/Gtf3-1

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Gabriel Wee of III Date/Time: 25/8/2020 9:21 AM

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 7983E Insured: SH 9102M

at Workshop m/s Teamwork Garage Pte Ltd Tel: 68442475

of 53 UBI AVENUE 1, #01-16 PAYA UBI IND. PARK

Policy No: MCOM0015 Claim No: MCT20080305

Sum Insured: Excess:

Make of Veh: D.O.A. 20-8-20
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 25-8-20 11.00A.M Person Contacted: SHU SHAN Vehicle ☒ IN OUT

Date/Time	Action/Instruction (X) Estimate
	SMK 7983E- X
	SH 9102M- CC4/III20008151/Ups3 DOA :03/08/2020
	lump sum \$1150,3days (red: 3200; 73%)