

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21004342/Eqce2	
	8 SHENTON WAY TOWERSINGAPOR		Date:	30/04/2021		
	ATTN: YU DOMINI	C YISHAN		Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 4349T	Veh. Inspected		FBH 4725A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M034XS	Excess (\$)		0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date		06/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA YZF R15	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2013	
	Chassis No.	ME11CK055D2005930	Colour		WHITE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/70Z R17	BRIDGESTONE		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	150/60Z R17	BRIDGESTONE		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.					
5.	5. General Information					
	Accident Date	30/01/2021	Inspect Date /	Time	07/04/2021 (11:30 AM)	
	Survey held at	FRIENDSHIP MOTOR CO	•			
		BLK 1005 BUKIT MERAH LANE 2 #01-18 SINGAPORE 159761				
5a.		Remarks				
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLE	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,000				
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/ASM21004342/Eqce2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser