

(08/11/13) wef
ASS. REC. BY: Farah

REF:

CS3/11121004349/R1qf3

B38B


ASSIGNMENT

COTG XPRY: 2026/Jan

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKA 507U
at Workshop m/s: MAX MOTOR
of 1/KALI MUKIT RUK 6 Arutany 101-98
Insured: 111
Policy No. D21MFL0000447
Claims No. MFL2021D0001414
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 37K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 507U Yr Regn: 2011 JAN
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 A c.c 1598
Colour: GRAY A/C: Insured / Std / NI / NA
Sp. Reading: 82032 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MROS3ZEG 106173231

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15
R: u.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or ROKIT 6

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 3/04/21 01/04/2021 D.O.I. 06/04/21

Survey held at MAX MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 18k

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 4 days

07/04/21 Submit PRS.

Date/Time, File Pass to?

☐

: Preli. Report

1) 07/04 Typist

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : PRS

Lump Sum / I.B.I: (\$ _____)

G SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/04/2021 14:48 (SGT)
 Date of Accident 01/04/2021 22:55 (SGT)
 Exact Location of Accident Singapore
 Additional Location Information TANGLIN ROAD
 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKA507U

INSURED/POLICYHOLDER

Is company? No
 Name Of Registered Owner SHAWA HONG YEOW (CAI HONGYAO)
 NRIC No SXXXX838B
 Email Address shawa87@hotmail.com
 Mobile Phone No (Phone) +65-96343461
 Alternative Phone No +65-96343461

VEHICLE PARTICULARS

Manufacturer Toyota
 Model TOYOTA / COROLLA ALTIS 1.6 AUTO
 Variant -
 Exact purpose for which vehicle was being used at time of accident Private use
 Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
 Vehicle Category Private car
 Transmission Auto
 CC 1598

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
 Type of Coverage Comprehensive
 Fleet Policy No
 Policy Number 5121104340
 Cover Note Number -

DRIVER

Name of Driver SHAWA HONG YEOW (CAI HONGYAO)
 NRIC No SXXXX838B

Date Of Birth 12/09/1987
 Occupation Indoor
 Date Of Driving Pass 20/01/2021
 Driving experience 3 MONTHS
 Gender Male
 Mobile Number (Phone) +65-96343461
 Alt. Phone Number +65-96343461
 Email Address shawa87@hotmail.com
 Address BLK 276 YISHUN STREET 22 #11-260
 Address complement -
 Postcode 760276
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? No
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name ALVIN QUAH CHENG JUN
 Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Traffic Police
 Police Station Phone No (Phone) +65-65470000
 Alt. Police Station Phone No (Fax) +65-65474900
 Police Station Address 10 Ubi Avenue 3 Singapore 408865
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

AS PER POLICE REPORT No.T/20210402/7011;

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP4338Z
 Vehicle Manufacturer Mazda

Vehicle Model	MAZDA / MAZDA3 SEDAN 1.5 AT EU6
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	SHAWA HONG YEOW (CAI HONGYAO)
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKA507U
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	ALVIN QUAH CHENG JUN
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKA507U
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

100 KAKI BUKIT (VAC)


23 Kaki Bukit Ave 4 #02-02

Singapore 415933

Tel: 67416697 Fax: 67492305


Email: vackb@vicom.com.sg


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Owner ID Type:	Singapore NRIC
Owner ID:	838B
Vehicle No.:	SKA507U
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Apr 2021
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	3ZZ4993090
Chassis No.:	MR053ZEE106173231
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	18 Jan 2011
First Registration Date:	18 Jan 2011
Transfer Count:	2
Actual ARF Paid:	\$16,716.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	17 Jan 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$19,069.00
COE Rebate Amount:	\$18,218.00
Total Rebate Amount:	\$18,218.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Apr 2021

OK

Toyota Corolla Altis 1.6A (COE till 12/2025)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)



Price \$36,998

Depreciation ? \$7,810 /yr

Reg Date 26-Jan-2011
(4yrs 8mths 24days COE left)

Mileage 149,856 km (14.7k /yr)

Manufactured ? 2010

Road Tax ? \$816 /yr

Transmission Auto

Dereg Value ? \$17,671 as of today (change)

OMV ? \$16,286

COE ? \$18,652

ARF ? \$16,286

Engine Cap 1,598 cc

Power 90.0 kW (120 bhp)

Curb Weight ? 1,195 kg

No. of Owners ? 2

Type of Vehicle Mid-Sized Sedan

Features

Original Owner Condition. Well Maintained By Matured Owner. Owned By Car Knowledgeable Owner. Impressive Condition And Hard To Say No To. View specs of the Toyota Corolla Altis (2008-2013)

Accessories

Clean Original Leather Seat, Factory Head Unit With Reverse Cam. 17" Sport Rim. In Car Camera.

Description

Come For No Obligation Viewing And Test Drive, Feel It Yourself! Very Good Condition. Rare To Find Such Well Kept Car At Its Age! Don't Missed It! View To Believe. No Repairs Needed. Engine And Gearbox In Superb Condition. Straight Chassis With No Funny Noise. Very Clean Interior Non-Smoker Unit. Zero Electronics Failure. Flexible Loan Offered. Administrations And Highest Trade-In.

Category

COE Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.


Resources



Get market value of your existing car for free. Get started



Price Chart



Click on the point to view

Shortlist (+) More

Seller Information

CarQuotations

9 vehicles for sale. 16 sold

421 Tagore Industrial Area
Tagore 8