



AIG-TP CLAIM
SURVEY: 06/04/21
UKL-STEVE

VEHICLE NO : SMQ 3525 P

MODEL : MIT/OUTLANDER 2.0 STYLE

WIP : 64115

Material	:	\$	<u>2,724.40</u>
Labour	:	\$	<u>1,110.00</u>
Sub-Total	:	\$	<u>3,834.40</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>3,834.40</u>
GST 7%	:	\$	<u>268.41</u>
Grand Total	:	\$	<u>4,102.81</u>
Finalise By/Date : <u>Larry ON 19/04/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS

* TP VEHICLE NO: SLV1391G

* GIA Search fee \$ 2.00

* claim loss of RENTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 06/04/2021	<table> <tr> <td>Cust No/Name</td><td>/Mr Ragupathy S/O Narayanamoorth</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMQ3525P / 12/11/2019</td></tr> <tr> <td>Date In/Mileage</td><td>09/04/2021/ 14885</td></tr> <tr> <td>Chassis/Package</td><td>GF7W0601993 /#</td></tr> <tr> <td>Engine No</td><td>4J11BH5944</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 STYLE(994)</td></tr> <tr> <td>Colour/Trim</td><td>P02 RED METALLIC / BK BLACK</td></tr> </table>	Cust No/Name	/Mr Ragupathy S/O Narayanamoorth	Reg No/Reg Date	SMQ3525P / 12/11/2019	Date In/Mileage	09/04/2021/ 14885	Chassis/Package	GF7W0601993 /#	Engine No	4J11BH5944	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)	Colour/Trim	P02 RED METALLIC / BK BLACK
Cust No/Name	/Mr Ragupathy S/O Narayanamoorth														
Reg No/Reg Date	SMQ3525P / 12/11/2019														
Date In/Mileage	09/04/2021/ 14885														
Chassis/Package	GF7W0601993 /#														
Engine No	4J11BH5944														
Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)														
Colour/Trim	P02 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/04/2021/ 10:04	TLE	884 / Lauro Songcuan	64115

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER & BODY KITS				530.00✓
E PNT98000 SPRAY PAINT REAR BUMPER				350.00✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00✓
E PNT88000 REMOVE & REFIT REVERSE SENSOR				60.00✓
A SUNDRIES SUNDRIES				20.00✓
X BODY KIT, OUTLANDER ✓	1.00	1554.00	00.00	1554.00✓
X FACE,RR BUMPER ✓	1.00	811.00	23.00	624.47✓
X LAMP ASSY,COMB,RR LH ✓	1.00	603.00	23.00	464.31✓
X MOULDING,RR BUMPER,LH ✓	1.00	106.00	23.00	81.62✓
Z TEXT TP CLAIM AIG - SLV1391G SURVEY: STEVE (LKK) 06.04.2021 DOA: 13.03.2021 03 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	2,724.40	Nett	3,834.40
Labour	1,090.00	7% GST on	268.41
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	4,102.81
Sundry/Others	20.00		
Total(w/o GST)	3,834.40		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

All DTCs

For 110.3525P
Before we start we want to check all the good

2021.04.09

Item	Setting	Information
M.U.T.-3 Version		SEW20121-00
V.C.I. Version		B179
Vehicle Information		DBA-GF7W 2019MY

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active
KOS/IMMO/Keyless	KOS_8A880020	U0184	AUDIO CAN timeout	Active
OSS	OSS_9588000B	U0184	AUDIO CAN timeout	Active
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000	C2253	EPB SW malfunction	Stored
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	

All DTCs

For no 21962525P

After to check

use master unit to erase all

2021.04.09

Setting	
Item	Information
M.U.T.-3 Version	SEW20121-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2019MY

to use bond

25.06.2021

to Q.C

Test drive check after

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCS	
OSS	OSS_9588000B		No DTCS	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error	