

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD BIKE UNKNOWN (FBC281R)

Date of Loss

12 March 2021

Time of Loss

Loss Description

YK9401M (INSD) C/W FBC281R (TP)

Comment

Workshop Details

Total Rebate
Amount

0

Nett Loss Amount

-\$3,706.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work
completion *

20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	FBC281R	Purchase Date	<div>DD/MM/YYYY</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>11/10/2007</div> <div></div>
Mileage	<div>44178</div>	Age of Vehicle	13

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2006</div>


Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	GARY ENG TENG MUN	<div></div>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD BIKE	<input type="text" value="TRIUMPH"/>
Model	UNKNOWN	<input type="text" value="SCRAMBLER MANUAL"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="SMTTJ9171G6277930"/>
Engine No		<input type="text" value="1279067"/>
Engine Capacity		<input type="text" value="865"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

06/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

110-80-19

Front left side

SHINKO7mm

Front right side

Spare wheel

Rear Tyre Size

150-70-17

Rear left side

SHINKO7mm

Rear right side



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PAI
	0	2		FORK GAITOR	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		FRONT RIM SHAFT	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		CLUTCH LEVER	Cut	0	205	No	0	10	0	0	184.5	Re
	0	1		BRAKE LEVER	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		HANDLE BAR	Bent	0	480	No	0	10	0	0	432	Re
	0	1		KEY SWITCH HOLDER	Damaged	0	280	No	0	10	0	0	252	Re
	0	1		GEAR PEDAL	Cracked	0	290	No	0	10	0	0	261	Re

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PAI
	0	1		GEAR PEDAL RUBBER	Missing	0	60	No	0	10	0	0	54	Re¹
	0	1		FRONT FOOTREST - L/H	Broken	0	150	No	0	10	0	0	135	Re¹
	0	1		FRONT FOOTREST - R/H	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		EXHAUST ASSY	Dented	0	1750	No	0	10	0	0	1575	Re¹
	0	1		REAR FOOTREST - L/H	Broken	0	150	No	0	10	0	0	135	Re¹
	0	1		REAR FOOTREST - R/H	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		TAIL LAMP ASSY	Broken	0	305	No	0	10	0	0	274.5	Re¹
	0	1		ENGINE COVER	Repair	0	0	No	0	0	0	0	0	De

Labour









Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------	--------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO PROVIDE TOWING (LOD)	0	60	0	0	Reviewing		
	0		TO CHECK WIRING AND RESET HEADLAMP FOCUSING	0	0	0	0	Deny		
	0		TO REPAIR BODY FRAME	0	0	0	0	Deny		
	0		TO PROVIDE LABOUR	0	280	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 4 DAYS	Reviewing	0	0		
	0	1 SET NUMBER PLATE	Deny	0	0	NOT NECESSARY	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$3,643.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$3,303.00
Labour	\$0.00	\$340.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	2900		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$2,900.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$2,900.00

Submit for Review