

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | | |
|------------------------------------|--|--|-------------------|-------|-------------------------|--|
| | NTUC INCOME INSURANCE CO-OPERATIVE LTD | | | Ref: | CS/INC21004363/Aqf3n2 | |
| | 73 BRAS BASAH F #05-01 NTUC TRA 189556 | ROAD DE UNION HOUSESINGAPORE | D | ate: | 15/07/2021 | |
| | ATTN: SERENE LI | M | C | ode: | INC | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | FBM 6298B | Veh. Inspected | | FBR 8907M | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | MT/1126351-002 | Excess (\$) | | 0.00 | |
| | Assign From | ANNIE KOH | Assign Date | | 05/04/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | YAMAHA SNIPER | c.c | | 150 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2018 | |
| | Chassis No. | MH3UG0740J0133040 | Colour | | BLACK | |
| | Odometer | 7894 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 70/90 R17 | DUNLOP | | 6 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 120/70 R17 | DUNLOP | | 6 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 26/03/2021 | Inspect Date / Ti | me | 06/04/2021 (10:40 AM) | |
| | Survey held at | PRO-JEX V2D | | | | |
| | | 25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB SINGAPORE 417800 | | | | |
| 5a. | Remarks | | | | | |
| | | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | 4 | Worki | ng Days | |