

ASS. REC. BY:

Steve T

CS/SMO21004365/EKqf3

ASSIGNMENT

From:

PRS

Date:

Veh No:

SV45E

Yr Regn:

20/19/11

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

Make:

Mercedes-Benz

C180

c.c. 1597

at Workshop m/s

Colour:

Black

A/C: Insured / Std / NI / M

of

Sp. Reading

277081

T/Radio: Insured / Std / NI / M

Insured:

Eng/No:

Policy No.

C/No:

W00294045 21 628172

Claims No.

CMTD2101038/SYH

Gen. Cond: Good / (Fair) / Poor / Burnt

Sum Insured:

Excess:

(Client's Record)

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:


F:

225/45 R17

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

29K(est)

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

3/4/21

O.O.I.

6/4/21

Survey held at

V-Tech

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time

Action / Instruction

M/V - 29K

Estimation range of COR: \$2000-\$3000; 4 repair days.

21/07/21 Submit PRS.

Date/Time, File, Pass to?



Prell. Report

Days Of Repair:

4

21/07 Typist



Final Report

Resurvey No. of Trips:

1

Survey Fee:

Date/Time, File, Return to?

Transportation:

Add Fee:



Site Insp (\$

\$ - RS - SI



Interview (\$

Photos



Tech. Invs (\$

Others



Wash and (\$

TOTAL

Approved/signed:

PRS

Date/Time, File, Return to?