

20

Date: 05.04.2021  
Time: 10:11:02  
Page: 1

|               |   |                  |
|---------------|---|------------------|
| JOB NO        | : | 305461949        |
| REGN NO       | : | SH 8509E         |
| MILEAGE       | : | 0000000000       |
| MAKE          | : | HYUNDAI          |
| MODEL         | : | IONIQ(G3)        |
| DATE OF REGN  | : | 14.11.2019       |
| DATE/TIME IN  | : | 03.04.2021 08:55 |
| ACCIDENT DATE | : | 02.04.2021       |

| QTY | IND | UNIT-PRICE | DISC% | AMOUNT |
|-----|-----|------------|-------|--------|
|-----|-----|------------|-------|--------|

|      |                   |                           |      |        |       |        |    |
|------|-------------------|---------------------------|------|--------|-------|--------|----|
| 0001 | 04-01-0104-2544-G | CAP-RR HOOK               | 1    | 98.80  | 20.00 | 79.04  | de |
| 0002 | 04-01-0104-2282-G | COVER-RR BUMPER#          | 1    | 459.40 | 20.00 | 367.52 | de |
| 0003 | 04-01-0104-2533-G | MOULDING ASSY-RR BUMPER C | 1    | 451.25 | 20.00 | 361.00 | de |
| 0004 | 04-01-0101-0111-G | BUMPER COVER CLIP REAR    | 10 L | 22.00  | 20.00 | 17.60  | ue |
| 0005 | 04-01-0104-1150-A | PROTECTOR MAT             | 1    | 50.00  | 2.00  | 50.00  | ue |
| 0006 | 04-01-0104-2531-G | BRACKET ASSY-RR BUMPER SI | 1    | 55.80  | 20.00 | 44.64  | nn |
| 0007 | 04-01-0104-2545-G | MOULDING-REAR BUMPER LWR  | 1    | 47.50  | 20.00 | 38.00  | nn |
| 0008 | 04-01-0104-2577-G | GUARD ASSY-REAR WHEEL REA | 1    | 173.60 | 20.00 | 138.88 | nn |
| 0009 | 04-01-0104-0851-G | REFLECTOR/REFLEX ASSY-RR  | 1    | 41.45  | 20.00 | 33.16  | nn |

|         |                   |
|---------|-------------------|
| 0000 PB | PANEL BEATING     |
| 0001 SP | SPRAYPAINT CHARGE |

47.50 20.00 33.88  
173.60 20.00 33.88  
41.45 20.00 33.16  
SUB-TOTAL 1,129.84  
400.00 350

1072.90  
858.32  
SN 50

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 05.04.2021

Time: 10:11:02

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305461949  
REGN NO : SH 8509E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 14.11.2019  
DATE/TIME IN : 03.04.2021 08:5  
ACCIDENT DATE : 02.04.2021

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

|            |                             |       |    |      |
|------------|-----------------------------|-------|----|------|
| 0002 17-01 | CHECK ALL LIGHTING          | 50.00 | 30 | 660. |
| 0003 L     | REMOVE/REFIX REVERSE SENSOR | 80.00 | 30 |      |

SUB-TOTAL : 830.00

TOTAL : 1,959.84

660  
50  
858.32

MVA NAME & SIGNATURE  
DATE :

DATE :  
SURVEYOR NAME & SIGNATURE

AUTHORISED : YES / NO

\$1568.32 #  
2 days.

Tanphin 97495749  
WP 5/4/21 @ 4pm  
P/P Resurvey before paint  
02 days  
Tanphin e/Inhouse

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: