

(08/11/13) wef

ASS-REC. BY: PAME

REF:

CS/CT121004373/R10f3

124C

COB X P RY: 2024/APR

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJQ 1734Bat Workshop m/s: RICO 60of 8, KARL BUKIT ME 4 # 02-24Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 20K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJQ 1734B Yr Regn: 2009 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA UOS 3 AUTO c.c. 1497Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 304550 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0534Y9305110345Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModj: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 21/03/21D.O.I. 06/04/21Survey held at RICO 60Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 12K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	12K

TO: CHAINA TAIPING
Vehicle No : SJQ 1734 B
Make & Model : TOYOTA VIOS
DATE: 31/3/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BOOTLID <i>bt</i> ✓	1	\$ 754.60	\$ 754.60
2	BOOTLID LOGO <i>re</i> ✓	1	\$ 89.00	\$ 89.00
3	BOOTLID EMBLEM(VIOS) <i>re</i> ✓	1	\$ 92.40	\$ 92.40
4	BOOTLID OUTER GARNISH <i>x</i>	1	\$ 225.80	\$ 225.80
5	BOOTLID CAR PLATE LAMP <i>x</i>	2	\$ 89.50	\$ 179.00
6	BOOTLID STOPPER <i>re</i> ✓	2	\$ 30.00	\$ 60.00
7	BOOTLID INNER LOCK <i>bt</i> ✓	1	\$ 319.50	\$ 319.50
8	BOOTLID LOCK CATCH <i>x</i>	1	\$ 36.00	\$ 36.00
9	BOOTLID WEATHERSTRIP <i>re</i> ✓	1	\$ 198.60	\$ 198.60
10	BOOTLID STOPPER <i>re</i> ✓	4	\$ 30.00	\$ 120.00
11	BOOT LID HINGE <i>x</i>	2	\$ 217.50	\$ 435.00
12	REAR BUMPER <i>de</i> ✓	1	\$ 489.00	\$ 489.00
13	REAR BUMPER SIDE RETAINER <i>re</i> ✓	2	\$ 89.50	\$ 179.00
14	REAR BUMPER ATTACHMENT RETAINER <i>x</i>	2	\$ 78.90	\$ 157.80
15	REAR BUMPER REFLECTOR <i>cm</i> ✓	2	\$ 76.40	\$ 152.80
16	REAR BUMPER BRACKET <i>bt</i> ✓	2	\$ 135.00	\$ 270.00
17	TAILLAMP <i>cm</i> ✓	2	\$ 485.00	\$ 970.00
18	TAILLAMP INNER SPONGE SEAL <i>re</i> ✓	2	\$ 25.00	\$ 50.00
19	TAILLAMP LOWER BARCKET <i>x</i>	2	\$ 67.20	\$ 134.40
20	TAILLAMP PANEL <i>x</i>	2	\$ 133.50	\$ 267.00
21	REAR FENDER <i>x</i>	2	\$ 965.00	\$ 1,930.00
22	REAR FENDER INNER COWLING <i>cut x</i> <i>tpc</i>	2	\$ 194.60	\$ 389.20
23	REAR FENDER INNER TRIM <i>cut</i> <i>1pc</i> <i>1</i>	2	\$ 268.00	\$ 536.00
24	REAR FENDER AIR VENT <i>x</i>	2	\$ 56.00	\$ 112.00
25	REAR WINDSCREEN MOULDING <i>x</i>	1	\$ 125.00	\$ 125.00
26	REAR END PANEL <i>bt</i> ✓	1	\$ 548.00	\$ 548.00

	REAR END PANEL TOP GARNISH <i>cm/</i>	1	\$	178.50	\$	178.50
28	REAR FLOOR PANEL <i>1/2 X</i>	1	\$	845.00	\$	845.00
29	REAR FLOOR PANEL TOP BOARD <i>cut/</i>	1	\$	499.00	\$	499.00
30	REAR CENTER TOOL SPONGE <i>7 de/</i>	1	\$	374.50	\$	374.50
31	REAR SIDE TOOL SPONGE <i>8 cm/</i>	2	\$	237.90	\$	475.80
32	REAR SPRE TYRE BOLT <i>X</i>	1	\$	59.00	\$	59.00
33	REAR CHASSIS MEMBER <i>repair</i>	1	\$	742.60	\$	742.60
34	REAR EXHAUST PIPE <i>6t/ photo?</i>	1	\$	595.40	\$	595.40
35	REAR EXHAUST INSULATOR <i>X</i>	1	\$	99.60	\$	99.60
36	REAR EXHAUST MOUNTING <i>X</i>	1	\$	58.20	\$	58.20
37	REAR EXHAUST GASKET <i>X</i>	1	\$	45.00	\$	45.00
38	EXHASUT CHROME HEAD <i>X</i>	1	\$	150.00	\$	150.00

Subtotal : \$ 12,942.70

Less 25% \$ 3,235.68

Parts Total : \$ 9,707.03

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR NUMBER PLATE <i>SEA/</i>	1	\$ 50.00	\$ 35 50.00
2	REAR BUMPER CLIPS <i>re/</i>	1	\$ 50.00	\$ 30 50.00
3	TAILLAMP CLIPS <i>re/</i>	1	\$ 30.00	\$ 20 30.00
4	TAILLAMP PANEL SEALANT <i>X</i>	1	\$ 80.00	\$ X 80.00
5	REAR FENDER COWLING CLIPS <i>X</i>	1	\$ 30.00	\$ X 30.00
6	REAR FENDER INNER TRIMD CLIPS <i>re/</i>	1	\$ 40.00	\$ 20 40.00
7	REAR END PANEL TOP GARNISH CLIPS <i>re/</i>	1	\$ 30.00	\$ 20 30.00
8	REAR END PANEL INSULATION SEAL <i>re/</i>	1	\$ 150.00	\$ 60 150.00
9	REAR FLOOR PANEL INSULATION SEAL <i>X</i>	1	\$ 150.00	\$ 150.00
10	REAR WINDSCREEN SEALANT <i>X</i>	1	\$ 60.00	\$ 60.00
11	REAR WINDSCREEN INNER SEAL <i>X</i>	1	\$ 60.00	\$ 60.00
12	REVERSE SENSOR <i>re/</i>	1	\$ 350.00	\$ 200 350.00

SPECIAL NETT \$ 1,080.00

LABOUR FRONT REAR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	<i>600</i>	\$ 1,800.00
TO SPRAY PAINT AFFECTED AREA	<i>600</i>	\$ 1,800.00
TUFF COAT	<i>80</i>	\$ 250.00
WIRING CHECK	<i>30</i>	\$ 100.00
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	<i>60</i>	\$ 300.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$ 60 120.00

FRONT CHASSIS ALIGNMENT	X	\$	300.00
TRANSFER BOOTLID MECHANISM	60	\$	120.00
TRANSFER REAR WINDSCREEN	X	\$	150.00
CONDUCT WATER LEAKAGE TEST	30	\$	100.00
REMOVE AND REFIX REAR EXHAUST PIPE	80	\$	150.00
LABOUR TOTAL		\$	5,190.00
		Total Parts Cost	\$ 10,787.03
		Total Labour Cost	\$ 5,190.00
		Total Repair Cost	\$ 15,977.03

APPROVED DETAILS

NO. OF WORKING DAYS

6 days

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY 06/04/21 @ 1120

SURVEYED BY PASUL CLKK

CONTACT NUMBER 900100568

FAX NUMBER

Pay after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/04/2021 11:24 (SGT)
Date of Accident	31/03/2021 13:59 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE/ Tuas Before KPE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ1734B
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Justin Yeo Jun Meng
NRIC No	SXXXX124C
Email Address	yeo_justin@icloud.com
Mobile Phone No	(Phone) +65-96447427
Alternative Phone No	(Home) +65-96447427

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1400

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	MT 00876354
Cover Note Number	nil

DRIVER

Name of Driver	Justin Yeo Jun Meng
NRIC No	SXXXX124C

Date Of Birth	10/01/1998
Occupation	Indoor
Date Of Driving Pass	19/11/2020
Driving experience	4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96447427
Alt. Phone Number	(Home) +65-96447427
Email Address	yeo_justin@icloud.com
Address	767 Bedok Reservoir View #06-219
Address complement	-
Postcode	470767
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Report Please refer to Police Report

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS994Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGW994C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	Justin Yeo Jun Meng
Address	767 Bedok Reservoir View #06-219
Address Complement	-
Post Code	470767
Approximate Age Years Old	-
Injuries Sustained	unknown
Injured person in which vehicle?	SJQ1734B
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

Describe Circumstances of the Accident

Handwritten notes on lined paper:

- TO POWER
- Point
- Retel

Declaration

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel



SINGAPORE POLICE FORCE



T/20210331/7023

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20210331/7023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/03/2021 15:54	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: JUSTIN YEO JUN NENG			Address: 767 BEDOK RESERVOIR VIEW #06-219 SINGAPORE 470767		
ID Type / ID No.: NRIC NO / S9803124C			Contact No.: Home/Office: Mobile: 96447427		
Nationality: SINGAPORE CITIZEN			Email: yeo_justin@icloud.com		
Sex: Male	Age: 23	Date of Birth: 10/01/1998	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/03/2021 13:55	Type of Location: Straight Road
Location: PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
SGS994Z	Car					0
SGW994C	Car					0
SJQ1734B	Car	TOYOTA	VIOS J AUTO	Blue		0



SINGAPORE POLICE FORCE



T/20210331/7023

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

2 of 3

Report No. T/20210331/7023

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJQ1734B	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00876354	19/12/2020	26/04/2022

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	JUSTIN YEO JUN NENG		ID No. S9803124C
Related Vehicle	SJQ1734B (Car)		Contact No. 96447427
Hospital/Clinic	OUR FAMILY PHYSICIAN CLINIC & SURGERY		Class of Driving Licence & Expiry Class: 3A Date of Expiry: NIL
Date	31/03/2021		Date 31/03/2021
No. of Days granted Medical Leave	05	Degree of	Serious

Brief Details.

ON THE STATED DATE AND TIME. I, VEHICLE A (SJQ1734B) WAS TRAVELLING STRAIGHT ON THE STATED VENUE. WHEN THE FRONT VEHICLE SLOWED DOWN AND STOP, I FOLLOWED SUIT WITHOUT HAVING ANY COLLISION WITH THE FRONT VEHICLE. SUDDENLY I FELT A HUGE IMPACT FROM THE REAR PORTION OF MY STATIONARY VEHICLE. AFTER I ALIGHTED I THEN REALISE THAT IS VEHICLE B (SGS994Z) THAT HAD COLLIDED ONTO MY VEHICLE. I WISH TO STATE THAT THIS IS A 3CARS CHAIN COLLISION.

DUE TO THE IMPACT I WAS INJURED WITH NECK, SHOULDER AND BACK PAIN I WENT TO SEE THE DOCTOR AND WAS GIVEN 5DAYS MC.

VEHICLE A : SJQ1734B

VEHICLE B : SGS994Z

VEHICLE C : SGW994C



**SINGAPORE
POLICE FORCE**



T/20210331/7023

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20210331/7023

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
TAY CHUN KEEN
Contact No.: 65476179

Authentication Stamp
NP168

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
31/03/2021 15:54

Classification Of Case:

Toyota Vios 1.5A J (COE till 03/2024)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price **\$20,500**

Depreciation ⑦ **\$6,860 /yr**

Reg Date 08-Apr-2009
(2yrs 11mths 26days COE left)

Mileage 153,000 km (12.8k /yr)

Manufactured ⑦ 2009

Road Tax ⑦ **\$821 /yr**

Transmission Auto

Dereg Value ⑦ **\$7,630 as of today (change)**

OMV ⑦ **\$11,696**

COE ⑦ **\$12,763**

ARF ⑦ **\$11,696**

Engine Cap 1,497 cc

Power 80.0 kW (107 bhp)

Curb Weight ⑦ 1,095 kg

No. of Owners ⑦ 2

Type of Vehicle Mid-Sized Sedan

Features

Airbags, ABS, Side Mirror Indicator. View specs of the Toyota Vios (2007-2013)

Accessories

Sports Rims, Leather Seats, CD/MP3/WMA Player, Reverse Sensors.

Category

COE Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources




Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist

Compare

More

Seller Information

Lim Khim Motor Trading

4 vehicles for sale. 8 sold in past

⑦ 160 Sin Ming Drive #03-18
Sin Ming AutoCity
Search cars nearby

⑦ Eric Lim

Posted on: 03-Apr-2021 | Last Updated on: 04-Apr-2021

Upfront Payment

> more Financial info

Transfer Fee ⑦ **\$25**

Down Payment ⑦ **\$6,150 (change) Maximum 70% Loan**

1st Instalment ⑦ **\$449** Based on 2.48% interest rate
Get your loan approved now in 60 seconds. T&Cs apply.
Learn More



Total Upfront Payment ⑦ **\$6,624** Check with seller for
(excluding insurance)

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	124C
Vehicle Details	
Vehicle No.:	SJQ1734B
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2021
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	1NZX895660
Chassis No.:	MR053HY9305110345
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,047.00
Original Registration Date:	27 Apr 2009
First Registration Date:	27 Apr 2009
Transfer Count:	5
Actual ARF Paid:	\$12,047.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,088.00
COE Rebate Amount:	\$8,005.00
Total Rebate Amount:	\$8,005.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Apr 2021

OK