TP A19.

SHENG LI LAI

Derise.

2 Kaki Bukit Ave 2 (Kaki Bukit Auto Hub), #01-36, Singapore 417921 H/P: 9111 9222 (Low Eng Chong) Tel: 6842 0302 Fax: 6746 0295 Email: sllshenglilai@gmail.com

Vehicle number: GBD1754D Vehicle Made & Model: TOYOTA DYNA

Qty	List Items		Amount \$
1	Tailgate Dented		1,498.65
1	Tailanta atiakar "TOVOTA" 7		211.40
1	Tailgate sticker "DYNA"		48.60
4	Tailgate hinges - L/R @ 55.60 2 pices Best		222.40-111.20
4	Tailgate hinges pins @ 18.60		74.00 ×
1	Tailgate lower member Peris		541.90 ×
2	Tailgate stoppers - L/R @ 48.60 Helm		97.20 X
2	Tailgate stopper brackets - L/R @ 89.60 Per	ż	179.20 4
2	Taillamps - L/R @ 291.55		583.10
10-000	Taillamp panels - L/R @ 181.95		363.90
2	Side gate - LH	300335	1,895.90 ×
	Rear exhaust pipe No Mu	2252.51	481.90 X
1	Rear spare wheel carrier Not New	42500	361.50 X
1			186.50
1	Rear licence plate bracket		89.95
1	Rear licence lamp NR New	Sub-total	6,836.10
,		Less 25%	1,709.03
		Total List	5,127.08
		TOTAL LIST	3,127.08
	EMBROVIO RETAIN DESCRIPTION		
	Special Nett Items		10.00
1	Rear sticker "70 KM/H" ?		/
1	Real Sticker 13 FAX		10.00
1 set	Rear no. plate with holder	420	60.00
2	Rear reflectors - Top @ 120 Cruled	(10	240.00
2	Rear reflectors - Lower @ 85 2 2		220.00
1	Rear step bracket		180.00 /20
			670.00

Vehicle number: GBD1754D

Vehicle Made & Model: TOYOTA DYNA

Labour charges

To check rear electrical wiring

To remove, refix rear exhaust systems

To respray undercoating

To respray painting and etc

Panel beating, cut, weld remove & replacing above parts

1090

50.00 30

80.00 ×

80.00 60

1,080.00 600

900.00 400 .

Total Labour

2,190.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

7,987.08

total: 3762:51

4/s: 3k

OADays.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: