

Surveyor

TG LIM

ASSIGNMENT

From:

Date: 7/4/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN 7135 B

at Workshop m/s V Maps Motor

of 10 Kaki Bt Rd 2 1st East Ctr

Insured:

Policy No. 2070162533

Claims No. 8114722906SG


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 5000/-

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS W/P

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

FBN 7135 B

Yr Regn: 29/11/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Vespa Piaggio GTS C.C 155

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

44871

T/Radio: Insured / Std / NI / NA

Eng/No:

MA32M5001492

C/No:

ZAPMA32000001536

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70/12 PIR

R: 130/70/12 Mitas

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. mm

L/Bal. mm

D.O.A. 30/3/2021

D.O.I. 7/4/2021

Survey held at

V Maps Motor

Des. of Damages: Frt / Rear / O/S / N/S U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Survey photos taken on 7/4/2021 @ 11:10:20 AM
Resurvey photos taken on 22/4/2021 @ 12:32:18 PM
Post survey photos taken on 11/5/2021 @ 2:01 PM TG Lim

18/05/21 Submit DAR; 4 repair days.

MV 5000/-

PR 2284/-

NV 2716/-

TG Lim
7/4/2021

Date/Time, File Pass to?

☐ : Preli. Report

1) 18/05 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: MER-DAR

Lump Sum / I.B.I: (\$)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|------------------------|
| Date of Submission | 05/04/2021 14:12 (SGT) |
| Date of Accident | 30/03/2021 09:45 (SGT) |
| Exact Location of Accident | Singapore |
| Additional Location Information | NORTH BUONA VISTA ROAD |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------|
| Vehicle Registration Number | FBN7135B |
|-----------------------------|----------|

INSURED/POLICYHOLDER

| | |
|--------------------------|------------------------------|
| Is company? | No |
| Name Of Registered Owner | TEO WENG KIAT(ZHANG YONGJIE) |
| NRIC No | SXXXX413A |
| Email Address | ja777ck@yahoo.com |
| Mobile Phone No | (Phone) +65-91169966 |
| Alternative Phone No | +65-91169966 |

VEHICLE PARTICULARS

| | |
|--|-----------------------------|
| Manufacturer | Piaggio |
| Model | PIAGGIO / VESPA GTS 150 ABS |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Motorcycle |
| Transmission | Auto |
| CC | 150 |

INSURANCE COMPANY

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC Income Insurance Co-operative Ltd |
| Type of Coverage | ThirdPartyFireTheft |
| Fleet Policy | No |
| Policy Number | 5117836106 |
| Cover Note Number | - |

DRIVER

| | |
|----------------|------------------------------|
| Name of Driver | TEO WENG KIAT(ZHANG YONGJIE) |
| NRIC No | SXXXX413A |



SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Witnessed by Reporting Centre
Personnel


05 APR 2021

Sketch Plan



Describe Circumstances of the Accident

Refer to Police Report



Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Witnessed by Reporting Centre Personnel

05 APR 2021

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

May 2005

FOR MOTORCYCLE

Motorcycle

Vehicle No: FBN 7135B

| NAC | INC | Item | CON | AC | Qty |
|------|--------|---------------------------------|-----|----|-----|
| I001 | 991886 | Front Number Plate | | | |
| 3001 | 995065 | Front Tyre | | | |
| 3002 | 995095 | Front Rim | | | |
| 3003 | 994872 | Front Tyre Rim Spoke | | | |
| 3004 | 991771 | Front Fender Wheel Guard | CUT | ✓ | |
| 3005 | 991283 | Front Brake Disc | | | |
| 3006 | 991281 | Front Brake Caliper | | | |
| 3007 | 991785 | Front Fork Assy | | | |
| 3008 | 991787 | Front Fork Inner Tube | | | |
| 3009 | 991789 | Front Fork Outer Tube | | | |
| 3010 | 991167 | Front Fork Bracket | | | |
| 3011 | 991182 | Front Fork Oil Seal | | | |
| 3012 | 991174 | Front Fork Garnish | | | |
| 3013 | 992376 | Front Headlamp Rim | | | |
| 3014 | 992328 | Front Headlamp | | | |
| 3015 | 992337 | Front Headlamp Bracket | | | |
| 3016 | 992345 | Front Headlamp Fairing | | | |
| 3017 | 992130 | Front Windshield | | | |
| 3018 | 992134 | Front Wing Mirror pair | MIS | ✓ | |
| 3019 | 995245 | Front LH Signal Lamp | | | |
| 3020 | 995246 | Front RH Signal Lamp | | | |
| 3021 | 992556 | Meter Casing | | | |
| 3022 | 992553 | Meter Assy | | | |
| 1118 | 991019 | ERP Bracket | | | |
| 1119 | 991020 | ERP Unit | | | |
| 3023 | 992446 | Ignition Switch | | | |
| 3024 | 992442 | Ignition Key Assy | | | |
| 3025 | 990706 | Cowling Stay | | | |
| 3026 | 994470 | Steering Stem | | | |
| 3027 | 994427 | Steering Cone | | | |
| 3028 | 992299 | Handle Bar | | | |
| 3029 | 992312 | Handle Bar Switch | | | |
| 3030 | 992310 | Handle Bar Grip | | | |
| 3031 | 995184 | Handle Bar Balancer LH | | | |
| 3032 | 992300 | Handle Bar Balancer RH | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 3033 | 990438 | Brake Reservoir | | | |
| 3034 | 990621 | Clutch Lever | CUT | ✓ | |
| 3035 | 992293 | Hand Brake Lever | | | |
| 3036 | 991119 | Side Fairing | | | |
| 3037 | 994220 | Side Fairing Top Garnish | | | |
| 3038 | 994219 | Side Fairing Inner Garnish | | | |
| 3039 | 991118 | Fairing Shield | | | |
| 3040 | 992047 | Front Top Fairing Inner Garnish | | | |
| 3041 | 991123 | Fairing Top Garnish | | | |
| 3042 | 990538 | Center Fairing | | | |
| 3043 | 993378 | Rear Fairing | | | |
| 3044 | 991121 | Fairing Stopper | | | |
| 3045 | 991117 | Fairing Lower | | | |
| Frnt | | fairing garnish | CUT | ✓ | |
| Frnt | | wheel fender | CUT | ✓ | |
| Frnt | | fairing | CUT | X | R |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-----------------------------|-----|----|-----|
| I052 | 995074 | Radiator | | | |
| I053 | 992738 | Radiator Cowling | | | |
| 3046 | 994146 | Seat Assy | | | |
| 3047 | 990915 | Engine Crash Bar | | | |
| 3048 | 990928 | Engine Guard | | | |
| I067 | 990219 | Battery | | | |
| I068 | 990224 | Battery Cover | | | |
| I069 | 990223 | Battery Bracket | | | |
| 3049 | 991144 | Foot Brake | | | |
| 3050 | 991154 | Front Foot Rest | | | |
| 3051 | 991779 | Front Foot Rest Bracket | | | |
| 3052 | 994269 | Side Stand | | | |
| 3053 | 992549 | Main Stand | CUT | ✓ | |
| 3054 | 990615 | Clutch Engine Cover | | | |
| 3055 | 992478 | Kick Starter Rubber | | | |
| 3056 | 992477 | Kick Starter Lever | | | |
| 3057 | 991145 | Foot Gear Shifter | | | |
| 3058 | 993500 | Rear Foot Rest | | | |
| 3059 | 993501 | Rear Foot Rest Bracket | | | |
| 3060 | 992581 | Exhaust Muffler Heat Shield | | | |
| 3061 | 991058 | Exhaust Muffler Assy | | | |
| I055 | 993719 | Rear LH Shock Absorber | | | |
| I056 | 993720 | Rear RH Shock Absorber | | | |
| 3062 | 995065 | Rear Tyre | | | |
| 3063 | 991200 | Rear Rim | | | |
| 3064 | 994872 | Rear Tyre Rim Spoke | | | |
| 3065 | 993474 | Rear Fender Wheel Guard | | | |
| 3066 | 993443 | Rear Fender Mudflap upper | CUT | ✓ | |
| 3067 | 992940 | Rear Brake Disc | | | |
| 3068 | 992936 | Rear Brake Caliper | | | |
| 3069 | 995236 | Rear Spocket | | | |
| 3070 | 990585 | Chain | | | |
| 3071 | 990580 | Chain Guard | | | |
| 3072 | 994530 | Swing Arm | | | |
| I020 | 993819 | Rear Sub frame | | | |
| 3073 | 995245 | Rear LH Signal Lamp | | | |
| 3074 | 995246 | Rear RH Signal Lamp | | | |
| 3075 | 995251 | Rear Taillamp | | | |
| I037 | 993626 | Rear Number Plate | BR | ✓ | |
| 3076 | 994192 | Side Box | | | |
| 3077 | 992927 | Rear Box | CUT | ✓ | |
| 3078 | 992928 | Rear Box Bracket | | | |
| 3079 | 991328 | Emblem Rear | MIS | ✓ | |
| I036 | 990247 | Sticker | | | |
| left | rear | fender lower side | DD | ✓ | |
| rear | | mud flap | BT | ✓ | |
| rear | | number plate | BR | ✓ | |

No of Items: 14

Assessor: TGLM mi 22/4/2021

ORIGINAL COPY