

A.S.S. REC. BY: Sun Pin

REF:

C53/AIG21004380/Qvfi**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLL1518L Yr Regn: 1Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda shuttle. C.C. _____Colour: Red. A/C: Insured / Std / NI / NASp. Reading: 43894 T/Radio: Insured / Std / NI / NAEng/No: -C/No: GK81101138.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60 R15R: 185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 6 mm / R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 07/04/2021Survey held at Ycep Auto.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Workshop nu give 61ARepair day 1 days

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

MOTOR CAR (RH)

Vehicle No: SLL1518L
(1) Part No. (2) Quantity (3) Location
(4) Remarks (5) Date

Right Portion

NAC	INC	Item	CON	AC	QTY
1316	991654	Fit RH Door	R	1	
1317	991654	Fit RH Door Protector			
1318	991601	Fit RH Door Hinge			
1319	991688	Fit RH Door Wing Mirror			
1320	991583	Fit RH Door Garnish	CR	1	
1321	991639	Fit RH Door Glass Outer Moulding			
1322	991588	Fit RH Door Glass Inner Moulding	SCR	1	
1323	991584	Fit RH Door Glass			
1324	991595	Fit RH Door Glass Regulator			
1325	991596	Fit RH Door Glass Regulator Motor			
1326	991662	Fit RH Door Rubber			
1327	991636	Fit RH Door Outer Handle			
1328	991607	Fit RH Door Inner Handle			
1329	991625	Fit RH Door Lock w/Key			
1330	991624	Fit RH Door Lock			
1331	991562	Fit RH Door Central Lock			
1332	991675	Fit RH Door Switch			
1333	991617	Fit RH Door Inner Trim Board			
1334	991568	Fit RH Door Checker			
1335	991575	Fit RH Door Felt			
1336	991688	Fit RH Door Wire Harness			
1337	991683	Fit RH Door Window Glass Pillar			
1338	991640	Fit RH Door Outer Pillar			
1339	991613	Fit RH Door Inner Pillar			
1340	991646	Fit RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Fit RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Fit Bumper			
1006	991325	Fit Bumper Bracket			
1007	991462	Fit Bumper Side Retainer			
1008	991433	Fit Bumper Reinforcement			
1010	991468	Fit Bumper Sponge			
1011	991427	Fit Bumper Protector			
1012	991301	Fit Bumper Moulding			
1013	991407	Fit Bumper Lower Spoiler			
1030	991821	Fit RH Headlamp Assy			
1032	995089	Fit RH Side Lamp			
1035	995071	Fit RH Fender			
1107	991744	Fit RH Fender Lamp			
1108	991752	Fit RH Fender Protector			

Vehicle No: SLL1518L

NAC	INC	Item	CON	AC	QTY
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
994070		Roof Top Panel			
994098		Roof Top Moulding			
994085		Roof Top Air-bag			
994084		Roof Top Air-bag Sensor			
994083		Roof Top Air-bag Control Unit			
992958		Rear Bumper			
992976		Rear Bumper Bracket			
993048		Rear Bumper Side Reinliner			
993045		Rear Bumper Reinforcement			
993077		Rear Bumper Sponge			
993040		Rear Bumper Protector			
993026		Rear Bumper Moulding			
993023		Rear Bumper Lower Spoiler			
995116		Rear RH Taillamp			
993456		Rear RH Fender			
993450		Rear RH Fender Protector			
990247		Sticker			

No. of Items:

Assessor: