



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 07/04/21
LKK - STEVE

VEHICLE NO : SLW 3478 Y

MODEL : KIA/FORTE K3 1.6 AL

WIP : 31542

Material	:	\$	<u>1,084.00</u>
Labour	:	\$	<u>4,050.00</u>
Sub-Total	:	\$	<u>5,134.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>4,834.00</u>
GST 7%	:	\$	<u>338.38</u>
Grand Total	:	\$	<u>5,172.38</u>
Finalise By/Date : <u>Lanny on 28/04/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 09 WORKING DAYS + 4 days (2 wk. ends)

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 08/04/2021	<table> <tr> <td>Cust No/Name</td><td>/Olivia Hwai Fang Loh Mrs Olivia</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLW3478Y / 08/02/2018</td></tr> <tr> <td>Date In/Mileage</td><td>07/04/2021/ 32406</td></tr> <tr> <td>Chassis/Package</td><td>KNAFJ411MJ576180C /KC17P</td></tr> <tr> <td>Engine No</td><td>G4FGHH691742</td></tr> <tr> <td>Make/Model</td><td>KIA/FORTE K3 1.6 A L 189</td></tr> <tr> <td>Colour/Trim</td><td>B4U GRAVITY BLUE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Olivia Hwai Fang Loh Mrs Olivia	Reg No/Reg Date	SLW3478Y / 08/02/2018	Date In/Mileage	07/04/2021/ 32406	Chassis/Package	KNAFJ411MJ576180C /KC17P	Engine No	G4FGHH691742	Make/Model	KIA/FORTE K3 1.6 A L 189	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK
Cust No/Name	/Olivia Hwai Fang Loh Mrs Olivia														
Reg No/Reg Date	SLW3478Y / 08/02/2018														
Date In/Mileage	07/04/2021/ 32406														
Chassis/Package	KNAFJ411MJ576180C /KC17P														
Engine No	G4FGHH691742														
Make/Model	KIA/FORTE K3 1.6 A L 189														
Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/04/2021/ 16:33	BLK	884 / Lauro Songcuan	31542

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR LH FENDER, REAR BUMPER & AFFECTED AREAS				1200.00 ✓
E PNT98000 SPRAY PAINT REAR LH DOOR, REAR LH FENDER & REAR BUMPER				1050.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				60.00 ✓
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00 ✓
E PNT88000 REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR				120.00 ✓
A 13900099 REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR				400.00 ✓
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS				240.00 ✓
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT				80.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS				40.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY REAR LH SPORT RIM				380.00 ✓
S SPECIALISTJOB TRANSFER REAR LH RIM INCLUDING BALANCING				30.00 ✓

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Olivia Hwai Fang Loh Mrs Olivia Reg No/Reg Date SLW3478Y / 08/02/2018 Date In/Mileage 07/04/2021/ 32406 Chassis/Package KNAFJ411MJ576180C /KC17P Engine No G4FGHH691742 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK
08/04/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/04/2021/ 16:33	BLK	884 / Lauro Songcuan	31542

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X EXC				-300.00
INSURANCE EXCESS				
X PANEL ASSY-QUARTER OUTER,LH ✓	1.00	1213.00	20.00	970.40 ✓
X FILM-ANTI CHIPPG LH ✓	1.00	27.00	20.00	21.60 ✓
X STOPPER-RR WINDOW GLASS ✓	2.00	4.00	20.00	6.40 ✓
X PAD-WINDSHIELD GLASS ✓	10.00	2.00	20.00	16.00 ✓
X MOULDING-REAR WINDOW GLASS	1.00	27.00	20.00	21.60 X
X STOPPER-RR WINDOW GLASS	2.00	4.00	20.00	6.40 X
X CHANNEL ASSY-REAR DOOR DIVISIO	1.00	52.00	20.00	41.60 X

Z TEXT

OD CLAIM - AIG
 DOA: 31.03.2021
 SURVEY: STEVE (LKK) 07/04/2021
 09 DAYS

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	1,084.00		Nett	4,834.00
Labour	3,460.00	7% GST on	4834.00	338.38
Standard Menu	0.00			
Specialist Job	410.00		Total Payable	5,172.38
Diagnostics Job	0.00			
Sundry/Others	-120.00			
Total(w/o GST)	4,834.00			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SLW 3478 Y

<u>Materials</u>		<u>Cost \$</u>
1	Moulding- Rear Window Glass	<i>nec</i> 27.00 ✓
2	Stopper- RR Window Glass (2 pcs)	<i>nec</i> 8.00 ✓
3	Channel Assy- Rear Door Division	<i>CYT</i> 52.00 ✓
		87.00
20% Discount		17.40
		69.60
7% GST		4.87
Total		74.47

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SLW 34784WIP: 31542

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Moulding Rear	? / SUPP			87131A7000
2	Stopper Rear windscreen x2	? / SUPP			8711431000
3	Channel Assy Rear Door Division LH	? / SUPP			83510A7000
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	14/04/21	Person (P)
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Cerato 1.6SURVEYOR: Steve - Lkh

Work Order: R001412
License: SLW3478Y
Technician: 214 THAM
Mileage: 32406
Date: 23.4.21 15:34

Kia : Cerato/Forte : 2013-19 (YD/YDm)

Front : Left

Actual	Before	Specified Range
-0°06'	-0°05'	-0°52' 0°08'
3°46'	3°46'	3°31' 4°31'
0°04'	-0°04'*	-0°03' 0°09'
14°55'*	14°54'*	13°06' 14°06'
14°49'*	14°49'*	12°14' 14°14'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°39'	-0°39'	-0°52' 0°08'
4°09'	4°09'	3°31' 4°31'
0°02'	-0°01'	-0°03' 0°09'
14°45'*	14°45'*	13°06' 14°06'
14°06'	14°06'	12°14' 14°14'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°33'	0°34'	
-0°22'	-0°22'	
0°10'	0°09'	
0°06'	-0°05'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°04'	-1°04'	-2°00' -1°00'
0°12'	0°12'	0°00' 0°27'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°59'	-1°59'	-2°00' -1°00'
0°10'	0°09'	0°00' 0°27'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°55'	0°55'	
0°21'	0°21'	0°00' 0°54'
0°01'	0°01'	

* This value is not within specification. Tire wear, handling and safety problems may result.



HOME

Online



CERATO/FORTE../2018/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



BCM



SJB



CLU

9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IMMO	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.

M-E-K-01-00-0243

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0184

OS Ver.

Android 10



HOME

Online



CERATO/FORTE../2018/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



CLU



BCM



SJB

9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
IMMO	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.

M-E-K-01-00-0243

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0184

OS Ver.

Android 10