

ASS. REC. BY: Sun Pin.

REF:

CC3/ALG21002340/Qgs3.**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SM B 50034 Yr Regn: 10/04/2014.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Alexander Dennis Euro500 S844Colour: Silver. A/C: Insured / Std / NI / NASp. Reading: 516814. T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: SFD76CLR5EMTLJ463

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_Tyre Size: F: 305 / 70 R22-5R: 305 / 70 R22-5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firenza

Front

Rear

R/Bal. 6 mm / R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/03/2021 D.O.I. 05/04/2021Survey held at SMRT.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Rep. Format: \_\_\_\_\_

Lump Sum / B.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others

TOTAL

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                   |
|-------------------------------|-------------------|
| Owner ID Type:                | Company           |
| Owner ID:                     | 292D              |
| Vehicle Details               |                   |
| Vehicle No.:                  | SMB5003U          |
| Vehicle to be Exported:       | No                |
| Intended Deregistration Date: | 06 Apr 2021       |
| Vehicle Make:                 | ALEXANDER DENNIS  |
| Vehicle Model:                | ENVIRO500         |
| Primary Colour:               | Silver            |
| Secondary Colour:             | Black             |
| Manufacturing Year:           | 2014              |
| Engine No.:                   | 22120870          |
| Chassis No.:                  | SFD76CLR5EMTL3463 |
| Maximum Power Output:         | -                 |
| Open Market Value:            | \$470,004.00      |
| Original Registration Date:   | 10 Sep 2014       |
| First Registration Date:      | 10 Sep 2014       |
| Transfer Count:               | 0                 |
| Actual ARF Paid:              | \$0.00            |
| Intended PARF Rebate Details  |                   |
| PARF Eligibility:             | No                |
| PARF Eligibility Expiry Date: | -                 |
| PARF Rebate Amount:           | \$0.00            |
| Intended COE Rebate Details   |                   |
| COE Rebate Amount:            | \$0.00            |
| <b>Total Rebate Amount:</b>   | <b>\$0.00</b>     |

The information contained herein is correct as at 06 Apr 2021

OK