

ASS. REC. BY:

REF: CS/MSG21004415/Kvf3

Special Instruction:

Surveyor: KENNETH

ASSIGNMENT (Office)

From (Person): JOWYN TAY MEI LING of MSIG Date/Time: 07 Apr 2021 11:18

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 3778L Insured: SJX 7787Y

at Workshop m/s Heng Yap Seng Auto Services Tel: 9183 3008

of BLK 160 SIN MING DRIVE, #08-13 SIN MING AUTOCITY, 575722 Sin Ming

Policy No: 80480710QMX Claim No: 635054

Sum Insured: Excess:

Make of Veh: D.O.A. 03/04/2021
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 07-04-21 1.38P.M Person Contacted: HAN MENG Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLV 3778L - ☒
	SJX 7787Y- CS/GAI18016577/R1sd3n2 DOA :07/09/2018