

62.
PRS

AK

ASSIGNMENT

50F5560M 08 Feb 2013

Estimated Cost

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No

Workshop n/s

Garage 13

Insured

Policy No

Claims No

Insured

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value

JAC Accident Report

WIA / PR Seen

Est Repairs

Repair Sum

\$40k

Consistent? Yes or No

Consistent? Yes or No

days Res Yes or No

% 3 Val Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Type: M / Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp Reading

Eng No

C/N

Gen Cond Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod: Nil / STD A/Rim or

Tyre Size

R

BS / HON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal

L/Bal

D.O.A

Survey held at

Des. of Damages Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

BMW 316i 1.6 cc 1598

white

265429

WPA3A 120505719560

Good

In order

In order

Nil / STD A/Rim or

225 / 50 RF17

BS / HON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front Rear

R/Bal 6 mm R/Bal 6 mm

L/Bal 6 mm L/Bal 6 mm

D.O.A w/s D.OI 07-04-21

Survey held at 4:30 pm

Des. of Damages Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Bot Body Injured

Rebate: 28435

Code/Name File Pass No

1)

Code/Time File Return No

☐ : Preli. Report
☐ : Final Report

Days Of Repair

Resurvey No. of Trip

3rd Fee

☐ Site Insp
☐ Subsy Insp
☐ ...

Survey Fee

Transportation

Empty box for stamp or signature