

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305462562 Via Fax : Email
Date : 070421 Your Insured : SLW 88864
Time of Fax : _____ Date of Acc : _____

Attn: Motor Claims Department

Aig Asia

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

C3154J

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811	} limts@cdge.com.sg Fax no. 6546 8156
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.04.2021

Time: 13:51:16

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305462562
 REGN NO : SHC3154J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 19.07.2018
 DATE/TIME IN : 07.04.2021 11:00
 ACCIDENT DATE : 03.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0002 03-01-0104-2020-A	REAR WHEEL SPORT RIM RH	1	1,124.20	20.00	899.36
0003 28-01-9999-2023-A	REAR DOOR APPS RH	1	80.00	2.00	80.00
0004 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0005 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00	50.00

SUB-TOTAL : 1,414.48

JOB NATURE

0000 20-05	Rear Door Adv.Sticker RH	100.00
0001 20-05	Rear Fender Adv.Sticker RH	100.00
0002 20-05	Rear Bumper Adv.Sticker	50.00
0003 PB	PANEL BEATING-Rear Fender RH	800.00
0004 SP	SPRAYPAINT-Rear Door RH	900.00
0005 20-00	TUFF COAT ON AFFECTED PARTS.	40.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.04.2021

REPAIR ESTIMATE

Time: 13:51:16

Page: 2

Ag Asia

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305462562
REGN NO : SHC3154J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 19.07.2018
DATE/TIME IN : 07.04.2021 11:0
ACCIDENT DATE : 03.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,990.00

TOTAL : 3,404.48

Limf

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :