

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.04.2021

Time: 13:51:16

Page: 1 *12 TS**Big Asia
CP/P)*

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305462562
 REGN NO : SHC3154J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 19.07.2018
 DATE/TIME IN : 07.04.2021 11:00
 ACCIDENT DATE : 03.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	<i>Rp</i>
0002 03-01-0104-2020-A	REAR WHEEL SPORT RIM RH	1	1,124.20	20.00	899.36	<i>at</i>
0003 28-01-9999-2023-A	REAR DOOR APPS RH	1	80.00		80.00	<i>nei</i>
0004 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	<i>x</i>
0005 04-01-0104-1150-A	PROTECTOR MAT	1	50.00		50.00	<i>x</i>

SUB-TOTAL : 1,414.48

JOB NATURE

0000 20-05	Rear Door Adv.Sticker RH	100.00	<i>cut</i>
0001 20-05	Rear Fender Adv.Sticker RH	100.00	<i>cut</i>
0002 20-05	Rear Bumper Adv.Sticker	50.00	<i>cut</i>
0003 PB	PANEL BEATING-Rear Fender RH	800.00	<i>525</i>
0004 SP	SPRAYPAINT-Rear Door RH	900.00	<i>750</i>
0005 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	<i>x</i>

COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.04.2021

REPAIR ESTIMATE

Time: 13:51:16

Page: 2/2 TS

Ag Asia cp/p)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305462562
REGN NO : SHC3154J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 19.07.2018
DATE/TIME IN : 07.04.2021 11:0
ACCIDENT DATE : 03.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,990.00

TOTAL : 3,404.48

Lmf

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanpin 97495347
WP 7/4/21 @ 4pm
2-3 days

o/p showing new parts, after repair parts
tanpin @ khauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 07.04.2021 13:33

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.305462562

OMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R)

(O)

(P)

UNIT CARD NO.

REGN NO. SHC3154J	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 07.04.2021 11:00
YR OF MANU 19.07.2018	TARGET DATE
CHASSIS CODE KMHC851CVJU103699	COMPLETION DATE/TIME


cident Date: 03.04.2021
TURE: 3P 03.04.2021

JOB DESCRIPTION

NO

LABOR CODE

DESCRIPTION



D & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHC3154J

LIMITS

Vehicle No.: SHC3154J

vice Advisor

Signature/Date

Name of Service Advisor

Date

ad to Service Reception upon collection

To be kept by Security Guard