

ASS. REC. BY:

REF: CS3/AIG21004437/Qqf3

Special Instruction:

Surveyor: SUN PINASSIGNMENT (Office)From (Person): DIVYASHNI SUBRAMANIAMof AIGDate/Time: 7/4/2021 7:22 AM

Estimated Cost: _____

Bill to: _____

OD-☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SMH 5026Y

Insured: _____

SLD 5571Yat Workshop m/s Guan Auto ServiceTel: 9388 4210of Block 7 Sin Ming Industrial Estate Sector C #01-82 / #01-80 Singapore 575642

Policy No: _____

Claim No: _____

6215364441SG

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 04/04/2021

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 07-04-21 4.58P.MPerson Contacted: JACKYVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SMH 5026Y - ☒
	SLD 5571Y - ☒