

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2103636

INV Date 21/05/2021

Reference CS/EQI21004485/Uqf3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SKF 1835P

Insured Veh. SKK 31Y

Claim No. DM21HO00537-JG

Policy No. DMPPHQ21-002093

Accident Date 01/04/2021

Inspection Date 28/04/2021

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Auto	mobile
	EQ INSURANCE C	COMPANY LTD	Ref:	CS/EQI21004485/Uqf3e2
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		Date	9: 21/05/2021
			Cod	e: EQI
1.		Policy Particulars	- THIRD PARTY CLA	AIM
	Insured Veh.	SKK 31Y	Veh. Inspected	SKF 1835P
	Policy No.	DMPPHQ21-002093	Coverage (\$)	0.00
	Claim No.	DM21HO00537-JG	Excess (\$)	0.00
	Assign From	JOEL GOH	Assign Date	08/04/2021
2.		Vehicle Partic	culars & Condition	
	Make & Model	HONDA CIVIC (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	JHMFB1630CS200837	Colour	GREY
	Odometer	178796 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	PIRELLI	6 mm
	L/H Front Tyre	205/55 R16	PIRELLI	6 mm
	R/H Rear Tyre	205/55 R16	PIRELLI	6 mm
	L/H Rear Tyre	205/55 R16	PIRELLI	6 mm
4.		Description	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR O/S PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		General	Information	
	Accident Date	01/04/2021	Inspection Date	28/04/2021
	Survey held at	AUTOMOBILE INTEGRATED MA	ANAGEMENT PTE LTE	O (AIM)
		23 KAKI BUKIT AVE 5 #04-01 (S	OUTH WING) SINGAP	ORE 415933
5a.		Re	emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		
5b.		Estimate I	Days of Repair	
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	2 Wo	orking Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 1835P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED / TORN	785.40	681.10
2	REAR BUMPER SIDE RETAINERS - L/R @\$49.92	SERVICEABLE	99.84	-
1	REAR TAIL LAMP RH	SCRATCHED	376.00	288.20
	LESS 25% DISCOUNT		-315.31	-242.33
			945.93	726.97
	SPECIAL NETT ITEMS			
1	SET REAR REVERSE SENSOR (SN)	SHORTED	307.90	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	46.80	30.00
			354.70	230.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE AND REPLACE REAR REVERSE SENSORS.		80.00	50.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	120.00	-
	TO RESPRAY PAINTING AND ETC.		800.00	400.00
	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS.		1,000.00	200.00
			2,050.00	670.00
	GRAND TOTAL		3,350.63	1,626.97

RECOMMENDED COST OF LUMP SUM REPAIRS	1,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/EQI21004485/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

SS1Y2147000A / SME MOTOR PTE LTD ENTRY DATE & TIME: 07/04/2021 15:31 (SGT) SUBMITTED BY: Chia Pei Ying VERSION: 1 (07/04/2021 15:31 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/04/2021 15:31 (SGT) Date of Accident 01/04/2021 17:50 (SGT) Exact Location of Accident Bideford Rd, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Honda

Vehicle Registration Number SKF1835P

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LEE HO ANN NRIC No. SXXXX438J Email Address annwoonlimosineservice@outlook.com Mobile Phone No (Phone) +65-91808436 Alternative Phone No +65-91808436

VEHICLE PARTICULARS

Manufacturer

Model Civic Variant Exact purpose for which vehicle was being used at time of Private hire accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1600

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd Type of Coverage Comprehensive Fleet Policy Nο Policy Number MR002420 Cover Note Number

DRIVER

Name of Driver LEE HO ANN NRIC No. SXXXX438J

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	07/03/1967 Outdoor 16/09/1974 46 YEARS AND 7 MONTHS Male (Phone) +65-91808436 +65-91808436 annwoonlimosineservice@outlook.com BLK 527 HOUGANG AVE 6 #09-213 - 530527 Yes - No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Head to Rear Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 2 No - Yes 2 No
PASSENGER 1 Name	UNKNOWN
Gender	Male
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Police Station Name Police Station Phone No Alt. Police Station Phone No Police Station Address Was notice of intended Prosecution given? If yes, against whom?	Yes Hougang Neighbourhood Police Centre (Phone) +65-18004890999 (Fax) +65-63128989 60 Hougang Ave 9 Singapore 538775 No
CIRCUMSTANCES OF ACCIDENT	
REFER TO POLICE REPORT: T/20210401/2100.	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes Yes No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer	SKK31Y

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	_
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	-

automin claim@gmail.com

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time Sketch Plan	Driver's Signature (If driver is not the policyholder) / Date & Time Pava 9	Witnessed by Reporting Centre Personnel ∪ ∩ -
1	DIAD	A - SKF18857
	B	B - SEK 314.

Describe Circumstances of the Accident

police

report attached



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 1835P

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 1835P

RE-INSPECTION





