

ASS. REC. BY:

Steve

REF:

AIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 7210005078

Claims No. 2070187918SG


Sum Insured: \_\_\_\_\_ Excess: 2000

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 24 days Res.: Yes or No

Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMY 195K Yr Regn: 9/2/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato C.C. 15.91

Colour: White A/C: Insured / Std / NI / N

Sp. Reading: 183 T/Radio: Insured / Std / NI / N

Eng/No: \_\_\_\_\_

C/No: KNAF 546 MM 5100889

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 7/4/21 D.O.I. 8/4/21

Survey held at Cycle &amp; Carriage

Des. of Damages: Frt / Rear / O/S (N/S) / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MIV-93K

09/04/21 @ 3.12pm revert to AIG via Merimen. (repairer ok repair within \$41K)

12/04/21 @ 10.34am Kok Chong informed C/A via Merimen.

12/04/21 @ 12.07pm Informed Coco C/A not more than \$41K on P/P basis &amp; ex \$2000 by email.

22/09/21 @ 12.22pm confirmed with Ms Loi final fig \$35828.40, 24 days (Red \$15990.60, 31%)

Date/Time, File, Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 24

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

\$ + RS \$

Police

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (%)☐ : Weighing (%)

FORMED:

MER-OD

Total Sum / P.P.:

35828.40



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / CocoLu	31674		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000				2			7200.00
RENEW FRT FENDER, FRT DOOR LH, REAR DOOR LH, A-PILLAR LH, ROOF PANEL				2			
<del>ROCKER PANEL LH, SIDE SILL LH, SIDE AIRDAM LH, CENTER PILLAR LH,</del>				11 1/2	80		4680
INNER PANEL A-PILLAR LH, REPAIR REAR FENDER LH, BONNET,				1/2			300.00
E PNT88000							
REMOVE & INSTALL ROOF GLASS							
E PNT98000							3500.00
SPRAY PAINT FOR BONNET, FRT FENDER LH, FRT DOOR LH, REAR DOOR LH,							
A-PILLAR LH, SIDE AIRDAM LH, SIDE SILL LH, CENTRE PILLAR LH, ROOF, PANEL				9			3150
REAR FENDER LH,							
E PNT88000							180.00
REMOVE & INSTALL FRT DOOR TRIMS, GLASS, LOCK, SPEAKER, WIRING AND							
OTHER RELATED MECHANISMS							
E PNT88000							180.00
REMOVE & INSTALL REAR DOOR TRIMS, GLASS, LOCK, SPEAKER, WIRING AND							
OTHER RELATED MECHANISMS							
E PNT88000							240.00
RENEW FRT WINDSCREEN							
E PNT88000							240.00
REMOVE & INSTALL REAR WINDSCREEN							
M SUNDRY							160.00
APPLY SEALANT FOR FRT & REAR WINDSCREEN				80 + 80			
M SUNDRY							220.00
APPLY SOLAR FILM FOR FRT WINDSCREEN							
M SUNDRY							150 180.00
APPLY SOLAR FILM FOR FRT DOOR GLASS SOLAR FILM							
B WHEEL ALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							30 60.00
TRANSFER FRT LEFT RIM & REAR RIGHT RIM							
A 90000001							400.00
RENEW SIDE AIRBAG AND SEAT AIRBAG							
A 90000001							200 400.00

8/4/21, 3:00pm

Steve CLKK)

OD- AL AL

EXCERS -?

P/P

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / CocoLu	31674			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
RENEW FRT BOTH SEAT BELTS AND IMPACT SENSORS								400.00 ✓
A 90000001								80.00 ✓
REMOVE & INSTALL ROOFLINING								
E PNT88000								400.00 ✓
TO CLEAN AND VACUUM SHATTERED GLASS								
E PNT88000								800.00 ✓
REMOVE & INSTALL ALL THE SEATS AND CARPET TO FACILITATE REPAIR								
A 90000001								? 400.00
RENEW DASHBOARD AND COWL CROSS BAR								
A 90000001								400.00 ✓
RENEW FRT UNDER CARRIAGE								
E PNT88000								30.00 ✓
REMOVE & INSTALL ALL THE PILLAR TRIMS TO FACILITATE REPAIR								
A 90000001								120.00 ✓
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								? 500.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								80 120.00
TO CONDUCT FLOOR BENCH TO PULL THE BODY ALIGNMENT								
M SUNDRY								? 400.00
APPLY SEALANT FOR ACCIDENT PORTION								
A 90000001								
RENEW FLOOR WIRING ASSY								
M SUNDRY								
Sundry								
M SUNDRY								
PANEL ASSY- PILLAR OUTER LH -- 71110M6A10 / 00 (No Price)								
M PANEL-FENDER,LH / 00					1.00	430.00	00.00	430.00
M INSULATOR-FENDER LH / CR4					1.00	27.00	00.00	27.00
M PANEL ASSY-FRONT DOOR,LH / 00					1.00	1277.00	00.00	1277.00
M HINGE ASSY-FRONT DOOR,LH / 0T					1.00	30.00	00.00	30.00
M HINGE ASSY-DOOR LOWER,LH / 0T					1.00	27.00	00.00	27.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI BLK 423 CLEMENTI AVENUE 1 #14-327 SINGAPORE 120423 Contact No	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora Reg No/Reg Date SMY195K / 09/02/202 Date In/Mileage / 0 Chassis No KNAF5416MM5100880 Engine No G4FGLH711854 Make/Model KIA/CERATO 1.6 A GT LINE H370 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV13863	CRDVCH	08/04/2021/ 13:06	RLC	442 / Cocolu	31674			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M LABEL-TIRE PRESSURE	✓	RC			1.00	7.00	00.00	7.00
M PANEL ASSY-REAR DOOR, LH	✓	DO			1.00	1377.00	00.00	1377.00
M HINGE ASSY-REAR DOOR UPPER, LH	✓	?			1.00	33.00	00.00	33.00
M HINGE ASSY-DOOR UPPER, LH	✓	?			1.00	26.00	00.00	26.00
M PILLAR ASSY-CENTER INNER, LH	✓	?			1.00	257.00	00.00	257.00
M PANEL ASSY-SIDE SILL INNER, LH	✓	DO			1.00	172.00	00.00	172.00
M PANEL COMPLETE-DASH	✓	CRU			1.00	1156.00	00.00	1156.00
M PANEL-ROOF	✓	DO			1.00	843.00	00.00	843.00
M RAIL ASSY-ROOF FR	✓	?			1.00	112.00	00.00	112.00
M RING ASSY-SUNROOF REINF	✓	?			1.00	406.00	00.00	406.00
M GUARD ASSY-FRONT WHEEL, LH	✓	CRU			1.00	95.00	00.00	95.00
M GLASS-WINDSHIELD	✓	OR			1.00	821.00	00.00	821.00
M MOULDING-WINDSHIELD GLASS	✓	RC			1.00	56.00	00.00	56.00
M BAR ASSY-COWL CROSS	✓	OT (Centre bar)			1.00	750.00	00.00	750.00
M CRASH PAD ASSY-MAIN	✓	CRU			1.00	1279.00	00.00	1279.00
M COVER ASSY-C/PAD SIDE LH	✓	OR			1.00	34.00	00.00	34.00
M HUB ASSY-FR WHEEL	✓	?			1.00	436.00	00.00	436.00
M GEAR ASSY-STEERING	✓	?			1.00	770.00	00.00	770.00
M WHEEL ASSY-ALUMINIUM	✓	(FR LH) - CNT			1.00	926.00	00.00	926.00
M TORSION AXLE COMPLETE	✓	?			1.00	1031.00	00.00	1031.00
M PAD-FRONT DOOR SIDE IMPACT, LH	✓	RC			1.00	13.00	00.00	13.00
M HANDLE ASSY-DOOR INSIDE, LH	✓	CNT			1.00	71.00	00.00	71.00
M PANEL ASSY-FRONT DOOR TRIM, LH	✓	CRU			1.00	699.00	00.00	699.00
M SWITCH ASSY-P/WDO MAIN	✓	?			1.00	295.00	00.00	295.00
M SWITCH-POWER WINDOW	✓	?			1.00	250.00	00.00	250.00
M SWITCH ASSY-IMS CONTROL	✓	?			1.00	82.00	00.00	82.00
M TRIM ASSY-FR PILLAR LH	✓	CNT			1.00	52.00	00.00	52.00
M TRIM ASSY-COWL SIDE LH	✓	?			1.00	23.00	00.00	23.00
M-TRIM-FR STEP PLATE, LH	✓	OR			1.00	18.00	00.00	18.00
M-TRIM ASSY-FR DR SCUFF LH	✓	CNT			1.00	19.00	00.00	19.00
M TRIM ASSY-CTR PILLAR LWR LH	✓	X			1.00	52.00	00.00	52.00
M TRIM ASSY-RR DR SCUFF LH	✓	?			1.00	19.00	00.00	19.00
M TRIM-RR STEP PLATE LH	✓	X			1.00	12.00	00.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / Cocolu	31674
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M TRIM ASSY-CTR PILLAR UPR LH	X	1.00	39.00	00.00	39.00
M CLIP-TRIM MTG STEEL	APC	10.00	1.00	00.00	10.00
M CLIP-TRIM MTG	APC	6.00	1.00	00.00	6.00
M CLIP-TRIM MTG	APC	4.00	1.00	00.00	4.00
M RUN ASSY-FR DR WDO GLASS LH	CNT	1.00	126.00	00.00	126.00
M GLASS ASSY-FRONT DOOR, LH	BR	1.00	207.00	00.00	207.00
M CHANNEL ASSY-FRONT DOOR LOWER,	CNT	1.00	15.00	00.00	15.00
M PANEL ASSY-FRONT DR MODULE, LH	BR (pylone)	1.00	241.00	00.00	241.00
M PLUG	?	1.00	5.00	00.00	5.00
M MOTOR ASSY-FRONT POWER WDW, LH	?	1.00	165.00	00.00	165.00
M TAG-BURGLAR ALARM	APC	1.00	3.00	00.00	3.00
M HEADLINING ASSY	CRU	1.00	1584.00	00.00	1584.00
M MOULDING ASSY-FRT DR FRAME, LH	BT	1.00	72.00	00.00	72.00
M W/STRIP ASSY-FR DR BELT O/S LH	CNT	1.00	80.00	00.00	80.00
M W/STRIP ASSY-FR DR SIDE LH	CNT	1.00	102.00	00.00	102.00
M W/STRIP-FR DR BODY SIDE LH	CNT	1.00	125.00	00.00	125.00
M W/STRIP-FR DR BELT I/S LH	CNT	1.00	43.00	00.00	43.00
M HANDLE ASSY-DOOR OUTSIDE, LH	BR	1.00	164.00	00.00	164.00
M COVER-FR DR O/S HDL LH	BR	1.00	14.00	00.00	14.00
M PAD-FR DR O/S HDL HINGE, LH	APC	1.00	5.00	00.00	5.00
M PAD-FR DR O/S HDL COVER, LH	APC	1.00	5.00	00.00	5.00
M STRIKER ASSY-DR	X	1.00	14.00	00.00	14.00
M BASE ASSY-FR DR O/S HANDLE LH	BR	1.00	52.00	00.00	52.00
M LATCH ASSY-FRONT DOOR, LH	BT (lock)	1.00	400.00	00.00	400.00
M CHECKER ASSY-FRONT DOOR, LH	BT	1.00	44.00	00.00	44.00
M MOULDING ASSY-RR DR FRAME, LH	APC	1.00	50.00	00.00	50.00
M MOULDING ASSY-RR DR FRAME, LH	X Repeated	1.00	50.00	00.00	50.00
M COVER ASSY-COWL TOP	?	1.00	247.00	00.00	247.00
M COVER-AFTER SERVICE, LH	?	1.00	11.00	00.00	11.00
M BLACK TAPE-FR DR RR, LH	APC	1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FR, LH	APC	1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FRAME RR OTR,	APC	1.00	8.00	00.00	8.00
M MIRROR ASSY-OUTSIDE RR VIEW, LH	BR	1.00	559.00	00.00	559.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / Cocolu	31674			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER ASSY-FR DR QDRNT INR, LH				BR	1.00	57.00	00.00	57.00
M SAB MODULE ASSY-FR, LH					1.00	357.00	00.00	357.00
M BACK ASSY-FR SEAT, LH				BR	1.00	1975.00	00.00	1975.00
M SHIELD COVER-FR SEAT OTR, LH				npc	1.00	30.00	00.00	30.00
M S/BELT ASSY-FR RH				Jammed	1.00	317.00	00.00	317.00
M S/BELT ASSY-FR LH				Jammed	1.00	315.00	00.00	315.00
M ADJUSTER ASSY-HEIGHT					1.00	37.00	00.00	37.00
M WIRING ASSY-FR DR(PASS)				npc	1.00	403.00	00.00	403.00
M-SENSOR ASSY-PRESS SIDE IMPACT				npc	1.00	89.00	00.00	89.00
M MODULE ASSY-AIR BAG CONTROL				npc	1.00	1025.00	00.00	1025.00
M-SENSOR ASSY-A TYPE CRASH				npc	1.00	54.00	00.00	54.00
M UNIT ASSY-IBU					1.00	564.00	00.00	564.00
M CURTAIN AIR BAG MODULE, LH				BR	1.00	1166.00	00.00	1166.00
M WIRING ASSY-FLOOR					1.00	1574.00	00.00	1574.00
M GLASS & MOULDING ASSY-QUARTER				X	1.00	252.00	00.00	252.00
M-NOZZLE ASSY-DEFROSTER, LH				CUT	1.00	12.00	00.00	12.00
M-DUCT ASSY-SIDE AIR VFNT, LH				CUT	1.00	128.00	00.00	128.00
M-GARNISH-C/PAD, LH				CUT	1.00	117.00	00.00	117.00
M CONNECTOR ASSY-HEATER TO AIR V					1.00	232.00	00.00	232.00
M GLOVE BOX ASSY					1.00	166.00	00.00	166.00
M PANEL ASSY-LOWER CRASH PAD					1.00	153.00	00.00	153.00
M HOSE ASSY-SIDE DEFROSTER, LH					1.00	44.00	00.00	44.00
M SUNROOF ASSY				CRU	1.00	3172.00	00.00	3172.00
M-MOULDING ASSY-SIDE SILL, LH				(Body Kit) - BR	1.00	279.00	00.00	279.00
M WHEEL ASSY-ALUMINIUM				Repaired	1.00	926.00	00.00	926.00
M BRACKET, IU ADHESIVE				npc	1.00	26.00	00.00	26.00
M ARM COMPLETE-FR LWR, LH					1.00	286.00	00.00	286.00

Confirm &amp; accepted by

7% GST on **Nett** 49,245.00  
49245.00 3447.15

**Total Payable** 52,692.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	07/04/2021 17:21 (SGT)
Date of Accident	07/04/2021 14:12 (SGT)
Exact Location of Accident	Commonwealth Ave W, Singapore
Additional Location Information	COMMONWEALTH AVE WEST
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMY195K
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	ELDORA KOK YING ZHI
NRIC No	SXXXX136I
Email Address	ELDORAKOK@GMAIL.COM
Mobile Phone No	(Phone) +65-97851968
Alternative Phone No	+65-97851968

## VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

## INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	7210005078
Cover Note Number	-

## DRIVER

Name of Driver	ELDORA KOK YING ZHI
NRIC No	SXXXX136I

Date of Birth .....  
 Occupation .....  
 Date of Driving Pass .....  
 Driving experience .....  
 Gender .....  
 Mobile Number .....  
 Alt. Phone Number .....  
 Email Address .....  
 Address .....  
 Address complement .....  
 Postcode .....  
 Is the driver the policyholder? .....  
 If No, Relationship of the Driver with the Insured .....  
 Does Driver Own Other Vehicles? .....  
 Vehicle Registration Number of Other Vehicle Owned by Driver .....  
 Insurance Company of Other Vehicle Owned by Driver .....

01/02/1993  
 Indoor  
 04/09/2012  
 8 YEARS AND 7 MONTHS  
 Female  
 (Phone) +65-97851968  
 +65-97851968  
 ELDORAKOK@GMAIL.COM  
 BLK 423 CLEMENTI AVE 1 #14-327  
 -  
 120423  
 Yes  
 -  
 No  
 -  
 -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
 Weather Conditions .....  
 Road Surface .....

Collision - Cross Junction  
 Clear  
 Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....  
 Number of vehicles involved in the accident .....  
 Was anybody injured in the Accident? .....  
 Was any injured conveyed to hospital by ambulance? .....  
 Was any other material or property damaged? .....  
 Number of Passengers (Including Driver) .....  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....

No  
 2  
 Yes  
 No  
 Yes  
 2  
 No

#### PASSENGER 1

Name .....  
 Gender .....

NICHOLAS WEE  
 Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....  
 Was notice of intended Prosecution given? .....  
 If yes, against whom? .....

No  
 No  
 -

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment? .....  
 Was there any video captured by Car Camera? .....  
 Was there any audio recorded? .....

Yes  
 Yes  
 No

#### DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number .....  
 Vehicle Manufacturer .....  
 Vehicle Model .....  
 Vehicle Variant .....  
 Vehicle Colour .....  
 Vehicle Category .....

SBS8646K  
 -  
 -  
 -  
 -  
 Bus

Driver  
Number  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

(Phone) +65-91125997

## INJURED PERSONS DETAILS

### INJURED 1

Name of injured person  
Address  
Address Complement  
Post Code  
Approximate Age Years Old  
Injuries Sustained  
Injured person in which vehicle?  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?

NICHOLAS WEE

ABRASIONS  
SMY195K  
Yes  
No

### INJURED 2

Name of injured person  
Address  
Address Complement  
Post Code  
Approximate Age Years Old  
Injuries Sustained  
Injured person in which vehicle?  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?

ELDORA KOK

ABRASIONS  
SMY195K  
Yes  
No



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan




**Circumstances of the Accident**

~~Acc~~ Traffic was cleared to turn, so we followed the car ahead of us to make the right turn. However, the oncoming bus going forward did not slow down and dashed through the traffic, thus colliding into us.  
When I make turning there's green arrow light on my side.

**Declaration**

We declare the foregoing particulars are true in every respect.

 07/04/21  
03:53PM

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel

# CERTIFICATE OF INSURANCE

## KIA AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : ELDORA KOK YING ZHI  
**Period of Insurance** : 09 Feb 2021 To 08 Feb 2023  
**Engine No.** : G4FGLH711854  
**Chassis No.** : KNAF5416MM5100880

**Vehicle No.** : SMY195K  
**Policy No.** : 7210005078  
**Endorsement No.** :  
**Issued Date** : 22 Feb 2021

### ABOUT THE COVER

**Make/Model** : KIA Cerato  
**Engine Capacity/Tonnage** : 1,591.00 CC  
**Driver Restriction** : NA  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2021  
**Insuring with COE/PAF** : Yes

**Person or Classes of Persons Entitled to Drive\*** :

- a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition

**Mileage Condition** : Unlimited Mileage

**Limitation as to use\*** :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

**Loss of Use 1500cc - 1600cc**

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

**Section 1**  
**Fire - \$0 Own Damage - \$2000 Theft - \$0 Flood Cover - \$2000**

**Section 2**  
**Property Damage - \$0**

**Windscreen : \$100**

**Named Driver and Excess (where applicable)**

ELDORA KOK YING ZHI - \$2000 (Own Damage), \$2000 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

**Hire Purchase Company/Employer's Loan: United Overseas Bank Limited**

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504671205

CYCLE & CARRIAGE - DERRIC

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

SSCNFY