

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305462800 Via Fax : Email  
Date : 080421 Your Insured : SKS 8880T  
Time of Fax : \_\_\_\_\_ Date of Acc : 060421

Attn: Motor Claims Department

Aig Asia

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

8307X

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811	} <b>limts@cdge.com.sg</b> <b>Fax no. 6546 8156</b>
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
♦ <b>Lim Tien Siong</b>	<b>Tel: 6214 8398 or HP: 9635 8546</b>	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President  
Taxi Accident Repair

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Ag Asia

Date: 08.04.2021

Time: 11:25:37

Page: 1

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305462800  
 REGN NO : SH 8307X  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 31.05.2019  
 DATE/TIME IN : 07.04.2021 16:10  
 ACCIDENT DATE : 06.04.2021

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2282-G	REAR BUMPER	1	458.60	25.00	343.95
0002 04-01-0302-2287-G	REAR BUMPER CENTER GUARD	1	552.60	25.00	414.45
0003 04-01-0302-2286-G	REAR BUMPER TOW COVER	1	82.70	25.00	62.02
0004 04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50
0005 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	<del>2.50</del>	135.70
0006 04-01-0302-1150-A	REAR BUMPER MAT	1	50.00	<del>0.25</del>	50.00

SUB-TOTAL : 1,022.62

## JOB NATURE

0000 PB	PANEL BEATING	400.00
0001 SP	SPRAYPAINT CHARGE	300.00
0002 L	R/I REVERSE SENSOR	120.00

SUB-TOTAL : 820.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 08.04.2021

REPAIR ESTIMATE

Time: 11:25:37

Page: 2

Arg Asia

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305462800  
REGN NO : SH 8307X  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID  
DATE OF REGN : 31.05.2019  
DATE/TIME IN : 07.04.2021 16:1  
ACCIDENT DATE : 06.04.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Limy

TOTAL : 1,842.62

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :