

[Service Requests](#)[Messages](#)[Claims](#)

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## General Details

Involving	TPVD TBC (GBK4718E)
Date of Loss	24 March 2021
Time of Loss	18:50
Loss Description	SLQ5592T (INSD) C/W GBK4718E
Comment	

## Workshop Details

Total Rebate Amount	0
Nett Loss Amount	-\$18,893.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	GBK4718E	Purchase Date	<div>DD/MM/YYYY</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>11/08/2020</div> <div></div>
Mileage	<div>23822</div>	Age of Vehicle	0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2020</div>


## Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name		<div></div>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD	<input type="text" value="TOYOTA"/>
Model	TBC	<input type="text" value="HIACE DX 2.8 AUTO"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="GDH2012012559"/>
Engine No		<input type="text" value="1GD8576082"/>
Engine Capacity		<input type="text" value="2754"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age		
Occupation		<input type="text" value=""/>
Education Qualification		<input type="text" value=""/>
Driving Experience		
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address		<input type="text"/>
Address type		<input type="text" value=""/>
Gender		<input type="text" value=""/>
Marital status		<input type="text" value=""/>
Identification #		<input type="text"/>



Service Requests

Messages

Claims



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

08/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake  
(Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

195/80R15

MICHELIN6mm

MICHELIN6mm

195/80R15

DUNLOP6mm

DUNLOP6mm



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

25

Settlement%

100

## Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part supplied by  
P  
a  
r  
t  
S  
u  
p  
p  
l  
i  
e  
d  
b  
y

A  
X  
A

Save






Assessment Details

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACT (PA
	0	1		FRONT BUMPER	Serviceable	0	0	No	0	0	0	0	0	De
	0	2		FRONT BUMPER SIDE RETAINER	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		HEADLAMP RH	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		FRONT DOOR RH	Repair	0	0	No	0	0	0	0	0	De
	0	1		FRONT STEP PANEL GARNISH RH	Serviceable	0	0	No	0	0	0	0	0	De
	0	1		SLIDING DOOR RH	Repair	0	0	No	0	0	0	0	0	De

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC1 (PA
	0	1		SIDE MIRROR RH	Serviceable	0	0	No	0	0	0	0	0	De















Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		R&R FRONT DOOR COMPONENT	0	0	0	0	Deny		
	0		R&R SLIDING DOOR	0	0	0	0	Deny		
	0		WHEEL ALIGNMENT	0	0	0	0	Deny		
	0		UPHOLSTERY	0	0	0	0	Deny		
	0		PANEL BEATING	0	0	0	0	Deny		
	0		RUST PROOFING	0	0	0	0	Deny		
	0		SPRAY PAINTING	0	600	0	0	Reviewing		



Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

## Summary

Add

Approve

Deny

Submit All

EDIT

SR  
NO

NAME

ACTION

ESTIMATED  
AMOUNT

ADJUSTED  
AMOUNT

COMMENT

REMOVE



0

DAYS OF  
REPAIR : 3  
DAYS

Reviewing

0

0



0

SUNDRIES

Deny

0

0

NOT  
NECESSARY



0

FRONT  
BUMPER  
CLIPS











Deny

0

0

NOT  
NECESSARY



EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FRONT DOOR SEALANT	Deny	0	0	NOT NECESSARY	
	0	FRONT DOOR COMPANY STICKER	Reviewing	0	50	NECESSARY	
	0	FRONT STEP PANEL GARNISH CLIPS	Deny	0	0	NOT NECESSARY	
	0	SLIDING DOOR SEALANT	Deny	0	0	NOT NECESSARY	
	0	FRONT RIM CAP & REAR RIM CAP (2PCS)	Deny	0	0	NOT NECESSARY	





Service Requests

Messages

Claims



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$650.00

CATEGORY

ESTIMATE

ADJUSTED

Labour

Miscellaneous

Submit for Review