



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Ref: CC4/ASM21004505/Uba3q2 Date: 29/06/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5637E	Veh. Inspected	SLQ 2891A	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M037IQ	Excess (\$)	0.00	
Assign From		Assign Date	08/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT MEGANE (A)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1RFB00057842934	Colour	WHITE	
Odometer	110330 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	MICHELIN	6 mm	
L/H Front Tyre	215/50 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/50 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/50 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/04/2021	Inspection Date	08/04/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	