



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH			Ref: CC4/ASM21004507/Uga3q2 Date: 19/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLU 170P	Veh. Inspected	GBF 772A	
Policy No.	GA266594	Coverage (\$)	0.00	
Claim No.	S1M037H8	Excess (\$)	0.00	
Assign From		Assign Date	08/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZFA26300006C30532	Colour	WHITE	
Odometer	113817 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	LASSA	6 mm	
L/H Front Tyre	195/60 R16	LASSA	6 mm	
R/H Rear Tyre	195/60 R16	LASSA	6 mm	
L/H Rear Tyre	195/60 R16	LASSA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S WING MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/04/2021	Inspection Date	08/04/2021	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	