ASS. PEC. B. Sun Pin. 1 3//4/192/00	04514/Q++1.		
ASSI	GNMENT		
From. Date:	Veh No: SBS 8803 Z. Yr Regn: 27/10/2009 Type: M.Car / M.Cycle (Bus) / Van / Lorry / Taxi / Prime Mover /		
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	Make: Scania CubatX2 c.c 9290.		
at Workshop m/s	Colour Multiplour A/C: Insured / Std / NI / NA		
of	Sp.Reading 999735 T/Radio: Insured / Std / NI / NA		
Insured:	Eng/No:		
Policy No.	C/No: YS2K4X20001865725		
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt		
Sum Insured: Excess:	Sleering: Inorder / Jammed / Leaked / Burnt or		
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or		
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or		
	Tyre Size: F: 275 / 70 R 2 z - 5		
(Policy Condition) Remark: The yeb had commenced its N/S O/S	R: 215/70 N22-5		
Remark: The veh had commenced its repair at the time of inspection.	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or		
1			
Bal. or Market Value:	Front Rear		
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm		
GIA / PR Seen: Consistent?: Yes or No			
Est. Repairs: days Res.: Yes or No	01/01/109		
Lum Sum: % 3 Val.: Yes or No	Survey held at SBS Transit		
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S (N/S) /, U/C / Rooftop or		
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.		
Date / Time Action / Instruction			
	· · · · · · · · · · · · · · · · · · ·		
Date/Time, File Pass to? : Preli. Report	Days Of Repair:		
	Resurvey No. of Trip: Survey Fee:		
Date/Time, File Return to?	Transportation:		
Add Fee:	: Site Insp (\$)3+RSSI		
	: Interview (\$) Fhotos		
Property Follows	: Fech Ings (5) propo		

English that the

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	653M
Vehicle No.:	SBS8803Z
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Apr 2021
Vehicle Make:	SCANIA
Vehicle Model:	KUB4X2 9.3L A/T ABS TURBO
Primary Colour:	Multicolor
Manufacturing Year:	2009
Engine No.:	6422538
Chassis No.:	YS2K4X20001865725
Maximum Power Output:	
Open Market Value:	\$320,763.00
Original Registration Date:	27 Oct 2009
First Registration Date:	27 Oct 2009
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$16,039.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	•
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 13 Apr 2021

AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087 Tel: (65) 6253 0233 Email: sales@autoteam.com.sg Co. Reg. No. 201205841K

Quote To **SBS Transit Ltd** Ang Mo Kio Workshop 15 Ang Mo Kio Street 63 Singapore 569117

Attn: Mr Li Ming

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

 No Hegal modification(s) is Nowed

 Supplementary item(s) must be resurveyed and is subject to final appro

Insurance Company

Acknowledged by Repairer Signature:

Date:

QUOTATION

Quotation No. Q21040449


Date

8 Apr 2021

Terms

Net 30

S/No	Description	Qty Unit Price	Amount
	Repair Accident Bus - SBS 8803Z		
		A STATE OF THE STA	CONTRACTOR OF ST
1.	Supply 3 workers (16 Working Hours)	1 S\$800.00	\$\$800.00
-	Replace Left Side Panel No. 3 & 4		- /
-	Repair Left Side Door No. 6		
-	Repair Radiator Door		
_	Spray Painting Radiator Door	Cel	



Remark(s) All Material To Be Supplied by SBST

Total

\$\$800.00

This is computer generated. No signature is required.