



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 13/04/21
LKK - STEVE

VEHICLE NO : SMX 286 L

MODEL : KIA/STONIC 1.0 A BET

WIP : 31623

Material	:	\$	<u>767.20</u>
Labour	:	\$	<u>1,310.00</u>
Sub-Total	:	\$	<u>2,077.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>2,077.20</u>
GST 7%	:	\$	<u>145.40</u>
Grand Total	:	\$	<u>2,222.60</u>
Finalise By/Date :	<u>ARRY ON 28/04/21</u>		

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk.end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 13/04/2021	Cust No/Name	/KOO YI XUAN MICHELLE
	Reg No/Reg Date	SMX286L*ECB20/ 22/12/2020
	Date In/Mileage	13/04/2021/ 2382
	Chassis/Package	KNAD6811VL6456277 /#
	Engine No	G3LCLP068357
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/04/2021/ 15:27	BLK	884 / Lauro Songcuan	31623

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER & AFFECTED AREAS				400.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER & FRONT RH FENDER				700.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X COVER-FR BUMPER UPR ✓	1.00	476.00	20.00	380.80 ✓
X COVER-FR BUMPER, LWR ✓	1.00	367.00	20.00	293.60 ✓
X GARNISH ASSY-FNDR SIDE, RH	1.00	45.00	20.00	36.00 ✗
X AIR DUCT-FR BUMPER, RH	1.00	38.00	20.00	30.40 ✗
X BRACKET-FR BUMPER SIDE, RH ?	1.00	13.00	20.00	10.40 ?
X CLIP → Supp	10.00	2.00	20.00	16.00 ✗
Z TEXT AIG OD CLAIM - REVERT DOA: 06.04.2021 SURVEY: STEVE (LKK) 13/04/2021 04 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	767.20	Nett	2,077.20
Labour	1,250.00	7% GST on	145.40
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	2,222.60
Sundry/Others	60.00		
Total (w/o GST)	2,077.20		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMX 286 L

<u>Materials</u>		<u>Cost \$</u>
1	Garnish Assy- Fndr Side, RH	<i>CUT</i> 45.00 ✓
2	Air Duct- FR Bumper, RH	<i>BR</i> 38.00 ✓
3	Clip (10 pcs)	<i>neC</i> 20.00 ✓
		<hr/> 103.00
	20% Discount	20.60
		<hr/> 82.40
	7% GST	5.77
	Total	<hr/> 88.17

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMX 286L

WIP: 31623 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	GAMMISTH ASSY <u>80</u>	? / SUPP	<u>SEA</u>		87712 H8700
2	AIR DUCT FIL	? / SUPP	<u>CR</u>	<u>Praveen Pd</u>	86574 H8700
3	BRACKET	? / SUPP	<u>CR</u>	<u>14/02/21</u>	86574 H8700
4	CLIP. <u>410</u>	? / SUPP	<u>NOL</u>		86575 27500
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	<u>14/02/21</u>	<u>Praveen Pd</u>
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Stanic

SURVEYOR: Steve - Wk

Fault Code Searching

Rescan Erase All DTC Go to DTC Save



10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
i-TPMS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0243	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0184	OS Ver.	Android 10

Fault Code Searching

Rescan Erase All DTC Go to DTC Save



10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
i-TPMS	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0243	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0184	OS Ver.	Android 10