

ASS. REC. BY:

REF:

AG/ 210045271Kt

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / Y / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s S Three

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|---|-----|
|  | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: Sma 4713K Yr Regn: 08, 20

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vevet c.c. 1496

Colour: M. Red AC: Insured / Std / Nil / NA

Sp. Reading: 12316 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: Bu 3 . 1323523

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 225/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 7/4/21

Survey held at

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 9/4/2021

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

1) _____

: Final Report

Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Transportation:

S - RS. \$ _____

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



S THREE AUTOMOTIVE RECOVERY PTE LTD

*NOT APPROVED
Recovery Bypaint
Today*

TO :
ATTN : MOTOR CLAIM DEPT. T/P VEH. NO. : SKN8847S

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : YEONG THIM
ADDRESS :

CONTACT :

LICENSE NO. SMU4713K TRANS. :
MAKE / MODEL : HONDA VEEL
OWNER'S INSURER : AXA INSURANCE (AGAINST AIG)
JOB-CODE : TP S/A : MICHELLE

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 7-Apr-21

CLAIM DETAIL

| <u>MATERIALS</u> | | QTY | QUO-PRICE | DISC. % | DISC- PRICE | SUR | REV. PRICE |
|------------------------------------|-------------|------|-----------|------------|----------------|-----|------------|
| 1 FRONT BUMPER | <i>By</i> | 1.00 | 927.50 | 20.00 | 742.00 | Y | <u>✓</u> |
| 2 FRONT BUMPER LOWER GARNISH | <i>Diff</i> | 1.00 | 300.70 | 20.00 | 240.56 | Y | <u>✓?</u> |
| 3 FRONT BUMPER RETAINER LH | <i>my</i> | 1.00 | 38.00 | 20.00 | 30.40 | Y | <u>✓</u> |
| 4 FRONT BUMPER RETAINER RH | <i>su</i> | 1.00 | 38.00 | 20.00 | 30.40 | Y | <u>X</u> |
| 5 FRONT BUMPER LOWER GRILLE | <i>CM</i> | 1.00 | 180.00 | 20.00 | 144.00 | Y | <u>✓</u> |
| 6 FRONT BUMPER TOWING COVER | <i>su</i> | 1.00 | 38.00 | 20.00 | 30.40 | Y | <u>X</u> |
| 7 FRONT BUMPER REINFORCEMENT | | 1.00 | 321.00 | 20.00 | 256.80 | Y | <u>?</u> |
| 8 FRONT HEADLAMP RH | <i>su</i> | 1.00 | 1716.70 | 20.00 | 1373.36 | Y | <u>X</u> |
| 9 FRONT HEADLAMP LH | | 1.00 | 1716.70 | 20.00 | 1373.36 | Y | <u>?</u> |
| 10 FRONT HEADLAMP LOWER BRACKET LH | | 1.00 | 70.00 | 20.00 | 56.00 | Y | <u>?</u> |
| 11 FRONT HEADLAMP LOWER BRACKET RH | <i>su</i> | 1.00 | 70.00 | 20.00 | 56.00 | Y | <u>X</u> |
| 12 FRONT HEADLAMP TOP RH | <i>R</i> | 1.00 | 168.00 | 20.00 | 134.40 | Y | <u>X</u> |
| 13 FRONT HEADLAMP TOP LH | <i>R</i> | 1.00 | 168.00 | 20.00 | 134.40 | Y | <u>X</u> |
| 14 FRONT CHROME | <i>WJ</i> | 1.00 | 108.00 | 20.00 | 86.40 | Y | <u>X</u> |
| 15 FRONT GRILLE | | 1.00 | 128.00 | 20.00 | 102.40 | Y | <u>?</u> |
| 16 FRONT GRILLE TOP COVER | | 1.00 | 250.00 | 20.00 | 200.00 | Y | <u>?</u> |
| 17 FRONT RADIATOR GRILLE LOGO | <i>CM</i> | 1.00 | 285.00 | 20.00 | 228.00 | Y | <u>✓</u> |
| 18 FRONT SIDE EMBLEM 'HYBRID' RH | <i>su</i> | 1.00 | 68.00 | 20.00 | 54.40 | Y | <u>X</u> |
| 19 FRONT SIDE EMBLEM 'HYBRID' LH | <i>su</i> | 1.00 | 68.00 | 20.00 | 54.40 | Y | <u>X</u> |
| 20 FRONT FOG LAMP RH | <i>su</i> | 1.00 | 327.70 | 20.00 | 262.16 | Y | <u>X</u> |
| 21 FRONT FOG LAMP LH | <i>su</i> | 1.00 | 327.70 | 20.00 | 262.16 | Y | <u>X</u> |
| 22 FRONT FOG LAMP COVER RH | <i>su</i> | 1.00 | 85.00 | 20.00 | 68.00 | Y | <u>X</u> |
| 23 FRONT FOG LAMP COVER LH | | 1.00 | 85.00 | 20.00 | 68.00 | Y | <u>?</u> |
| 24 FRONT FENDER RH | <i>R</i> | 1.00 | 580.00 | 20.00 | 464.00 | Y | <u>X</u> |

| | | | | | | | |
|----|--------------------------------------|------|--------|-------|--------|---|---|
| 25 | FRONT FENDER LH | 1.00 | 580.00 | 20.00 | 464.00 | Y | X |
| 26 | FRONT FENDER WHEEL ARCH PROTECTOR RH | 1.00 | 156.20 | 20.00 | 124.96 | Y | X |
| 27 | FRONT FENDER WHEEL ARCH PROTECTOR LH | 1.00 | 156.20 | 20.00 | 124.96 | Y | ? |
| 28 | FRONT FENDER INNER SHIELD RH | 1.00 | 130.10 | 20.00 | 104.08 | Y | X |
| 29 | FRONT FENDER INNER SHIELD LH | 1.00 | 130.10 | 20.00 | 104.08 | Y | X |
| 31 | HORN HIGH | 1.00 | 40.10 | 20.00 | 32.08 | Y | X |
| 32 | HORN LOWER | 1.00 | 40.10 | 20.00 | 32.08 | Y | X |
| 33 | RADAR SENSOR ASSY | 1.00 | 880.00 | 20.00 | 704.00 | Y | ? |

TOTAL (PARTS): 9087.50 7270.00

SPECIAL NETT ITEM

| | | | | | | | |
|---|---|------|---------|------|---------|---|------|
| 1 | FRONT GRILLE CLIPS | 1.00 | 50.00 | 0.00 | 50.00 | Y | ✓ |
| 2 | FRONT FENDER INNER SHIELD CLIPS LH & RH | 1.00 | 100.00 | 0.00 | 50.00 | Y | X |
| 3 | FRONT BUMPER CLIPS | 1.00 | 50.00 | 0.00 | 50.00 | Y | ✓ |
| 4 | FRONT BUMPER LOWER SPOILER | 1.00 | 1600.00 | 0.00 | 1600.00 | Y | ? |
| 5 | FRONT BUMPER LOWER SPOILER SEALANT | 1.00 | 80.00 | 0.00 | 80.00 | Y | ? |
| 6 | FRONT FENDER WHEEL ARCH PROTECTOR CLIPS | 1.00 | 100.00 | 0.00 | 50.00 | Y | X |
| 7 | FRONT NUMBER PLATE (LASER 3D) | 1.00 | 180.00 | 0.00 | 180.00 | Y | 6000 |
| 8 | FRONT PORTION BLACK STICKER SET | 1.00 | 800.00 | 0.00 | 800.00 | Y | ? |

TOTAL (PARTS): 2960.00 2860.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer
Signature:

ABOUT

| | | | | | | | |
|---|--|------|---------|------|---------|---|-----|
| 1 | STRAIGHTEN & PANEL BEAT ACCIDENT AREAS | 1.00 | 1400.00 | 0.00 | 1400.00 | Y | 500 |
| 2 | SPRAY PAINTING ON ACCIDENT AREAS | 1.00 | 1400.00 | 0.00 | 1400.00 | Y | 600 |
| 3 | CHECK & REPAIR WIRING SYSTEM | 1.00 | 120.00 | 0.00 | 120.00 | Y | 200 |
| 4 | RESPRAY TUFF KOTE ON AFFECTED AREAS | 1.00 | 100.00 | 0.00 | 100.00 | Y | X |
| 5 | PROGRAMME RADAR COLLISION CODING | 1.00 | 680.00 | 0.00 | 680.00 | Y | ? |

TOTAL (LABOUR): 3700.00 3700.00

TOTAL PARTS & LABOUR 15747.50 13830.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/04/2021 17:01 (SGT)
Date of Accident 07/04/2021 20:30 (SGT)
Exact Location of Accident Holland V, Singapore
Additional Location Information Holland Village B1 carpark
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMU4713K

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Yeong Thim
NRIC No SXXXX427Z
Email Address kcsjoey@gmail.com
Mobile Phone No (Phone) +65-97833195
Alternative Phone No (Home) +65-97833195

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number GA549093/1
Cover Note Number -

DRIVER

Name of Driver Yeong Zhi Jian Joseph
NRIC No SXXXX687J

| | |
|--|----------------------------------|
| Date Of Birth | 08/11/1991 |
| Occupation | Indoor |
| Date Of Driving Pass | 06/10/2011 |
| Driving experience | 9 YEARS AND 6 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-97833195 |
| Alt. Phone Number | - |
| Email Address | kcsjoey@gmail.com |
| Address | Blk 206A Compassvale Lane #14-79 |
| Address complement | - |
| Postcode | 541206 |
| Is the driver the policyholder? | No |
| If No, Relationship of the Driver with the Insured | Child |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|---|
| Type of Accident | Hit and run / Vandalism / Damaged whilst parked |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other material or property damaged? | Yes |
| Number of Passengers (Including Driver) | 0 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-------------|
| Vehicle Registration Number | SKN8847S |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private car |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |

Describe Circumstances of the Accident

My vehicle was parked stationary in the parking lot when I saw a note left on my front windscreen that ^{driver of} vehicle SKN 88275 wrote to ~~me~~ that she had hit onto the front portion of my vehicle. My vehicle front portion was damaged.

Declaration

We declare the foregoing particulars are true in every respect.

1