## MFORTDELGRO ENGINEERING PTE LTD

## ¿PAIR ESTIMATE\*

**VEHICLE NO** 

MODEL

SHA1145J

MAKE

**IONIQ G3** 

###

CHIANG/NTUC

Qty	Parts Description/ Labor	ur	Туре	1	Amount
1	1 REAR BUMPER 1 REAR BUMPER SIDE BRACKET RH 1 REAR REFLECTOR RH 1.0 REAR BUMPER CLIPS 1 REAR BUMPER CENTRE MOULDIN DISCO	G SUB TOTAL 20.00% UNTED TOTAL		451.25 4361	\$459.40 \$55.80 \$32.00 \$22.00 \$451.25 \$1,020.45 \$204.09 \$816.36
	1 REAR NUMBER PLATE W/ HOLDER 1 REVERSE SENSOR 10.00%  Labour Charge Panel Beating Spray Painting Charge Tuff Kote Towing fee Remove/refix Reverse sensor	LKK Auto Consi the Repairer of To resurvey before To display damage Parts prices are su Third party survey No illegal modifica Supplementary ite is subject to final a Acknowledged by Re Signature: Date: OTAL LABOUR	the following alafter spray pa ed part(s) during ubject to confirm is on a "Withou ition(s) is allowed m(s) must be re approval from an	inting g resurvey nation It Prejudice" basis ed	\$55.00 \$180.00 \$211.50 (0%); \$50 \$650.00 \$300.00 \$60.00 \$60.00 \$1,130.00
	ESTIMATE TOTAL			Zleys	\$2,157.86
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Janph 97415749

althe 04m

plp repr2 days

tauthir Chhautour