

REPAIR ESTIMATE

MVA: JUMANI

Tamlin 97445749
 WP 8/4/21 @ 430pm
 2-3 days
 P/P Resumy before paint
 tamlin@hkaudio.com

Date/Time: 08.04.2021 13:10 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.:305462804

CUSTOMER

NAME: COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO: 7010045
ADDRESS: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L (R) 65508755 (O)
(P)

COUNT CARD NO.


REGN NO.: SHC2954Z	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ (G2)	DATE/TIME IN 08.04.2021 09:30
YR OF MANU. 14.05.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU146356	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 08.04.2021

NATURE: 3P 08.04.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHC2954Z** **JU/ YY AIG**

Vehicle No.: **SHC2954Z**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard